For 3160-5 (J. 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

HOBB®OCD

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

5. Lease Serial No.

NMNM'	114991	

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter a	0	^		
Do not use this form for proposals to drill or to re-enter an	3	U	ZU17	
abandoned well. Use form 3160-3 (APD) for such proposals.				

abandoned wel	6. If Indian, Allott	6. If Indian, Allottee or Tribe Name						
SUBMIT IN 1	TRIPLICATE - Other instruction	7. If Unit or CA/A	greement, Name and/or No.					
1. Type of Well		8. Well Name and No. GREEN WAVE 20 32 FED STATE COM 1H						
2. Name of Operator DEVON ENERGY PRODUCT		CA DEAL	9. API Well No. 30-025-4318	86-00-X1				
3a. Address 6488 SEVEN RIVERS HIGHW ARTESIA, NM 88211	3b. Pho	one No. (include area code) 05-228-8429	10. Field and Pool GWC-025 G	10. Field and Pool or Exploratory Area GWC-025 G06 S263407P				
4. Location of Well (Footage, Sec., T.	., R., M., or Survey Description)		11. County or Pari	ish, State				
Sec 20 T26S R34E NWSW 21	55FSL 270FWL /		LEA COUNT	LEA COUNTY, NM				
12. CHECK THE AF	PPROPRIATE BOX(ES) TO INI	DICATE NATURE OF	F NOTICE, REPORT, OR C	OTHER DATA				
TYPE OF SUBMISSION		ACTION						
Notice of Intent	☐ Acidize ☐	Deepen	☐ Production (Start/Resume)) ■ Water Shut-Off				
_	☐ Alter Casing	Hydraulic Fracturing	□ Reclamation	■ Well Integrity				
☐ Subsequent Report	☐ Casing Repair	New Construction	☐ Recomplete	⊠ Other				
☐ Final Abandonment Notice	☐ Change Plans	Plug and Abandon	□ Temporarily Abandon	Change to Original A				
	☐ Convert to Injection ☐	Plug Back	■ Water Disposal	10				
 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. Devon Energy respectfully requests the following changes to the original APD: Utilize a Spudder Rig - Procedure Below 1. Spudder rig will move in and drill surface hole. a. Rig will utilize fresh water based mud to drill 17 ?? surface hole to TD. Solids control will be handled entirely on a closed loop basis. 2. After drilling the surface hole section, the spudder rig will run casing and cement following all of the applicable rules and regulations (OnShore Order 2, all COAs and NMOCD regulations). 3. The wellhead will be installed and tested once the 13-3/8? surface casing is cut off and the WOC time has been reached. 4. A blind flange with the same pressure rating as the wellhead will be installed to seal the 								
14. I hereby certify that the foregoing is	Electronic Submission #385008 v For DEVON ENERGY PROI mmitted to AFMSS for processing	DUCTION COM LP, sen by ZOTA STEVENS on	t to the Hobbs 08/24/2017 (17ZS0015SE)					
Name (Printed/Typed) REBECCA	A DEAL	Title REGUL	ATORY COMPLIANCE PRO	FESSI				
Signature (Electronic S	Submission)	Date 08/16/20	017					
	THIS SPACE FOR FED	ERAL OR STATE	OFFICE USE					
Approved By ZOTA STEVENS		TitlePETROLE	JM ENGINEER	Date 08/25/2017				
Conditions of approval, if any, are attached certify that the applicant holds legal or equ								

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2) ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **



Additional data for EC transaction #385008 that would not fit on the form

32. Additional remarks, continued

wellbore. Pressure will be monitored with a pressure gauge installed on the wellhead.

5. Spudder rig operations is expected to take 4-5 days per well on a multi well pad.

6. The NMOCD will be contacted and notified 24 hours prior to commencing spudder rig operations.

7. Drilling operations will be performed with the drilling rig. At that time an approved BOP stack will be nippled up and tested on the wellhead before drilling operations commences on each well.

a. The NMOCD will be contacted / notified 24 hours before the drilling rig moves back on to the pad with the pre-part surface assign.

with the pre-set surface casing.

Devon Energy, Green Wave 20-32 Fed State Com 1H

Will be pre-setting casing? Yes

- 1. Spudder rig will move in and drill surface hole.
 - a. Rig will utilize fresh water based mud to drill 17 ½" surface hole to TD. Solids control will be handled entirely on a closed loop basis.
- 2. After drilling the surface hole section, the spudder rig will run casing and cement following all of the applicable rules and regulations (OnShore Order 2, all COAs and NMOCD regulations).
- 3. The wellhead will be installed and tested once the 13-3/8" surface casing is cut off and the WOC time has been reached.
- **4.** A blind flange with the same pressure rating as the wellhead will be installed to seal the wellbore. Pressure will be monitored with a pressure gauge installed on the wellhead.
- 5. Spudder rig operations is expected to take 4-5 days per well on a multi well pad.
- **6.** The NMOCD will be contacted and notified 24 hours prior to commencing spudder rig operations.
- 7. Drilling operations will be performed with the drilling rig. At that time an approved BOP stack will be nippled up and tested on the wellhead before drilling operations commences on each well.
 - **a.** The NMOCD will be contacted / notified 24 hours before the drilling rig moves back on to the pad with the pre-set surface casing.