>						
Form 3160-5 (June 2015) UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT OCT 1 6 201 SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals EIV			017 5	FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018 5. Lease Serial No. NMLC064118 6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on page 2			7	7. If Unit or CA/Agreement, Name and/or No.		
1. Type of Well				8. Well Name and No. E.C. HILL B FEDERAL 3		
2. Name of Operator Contact: DAVID STEWART OXY USA INC. E-Mail: david_stewart@oxy.com				9. API Well No. 30-025-10948		
3a. Address P.O. BOX 50250 MIDLAND, TX 79710	hone No. (include area code) 432-685-5717 32-685-5742	1	10. Field and Pool or Exploratory Area TEAGUE PADDOCK BLINEBRY			
4. Location of Well <i>(Footage, Sec., 7</i> Sec 34 T23S R37E NWNE 84 32.265762 N Lat, 103.147583		1	11. County or Parish, State LEA COUNTY, NM			
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA						
TYPE OF SUBMISSION	TYPE OF ACTION					
□ Notice of Intent					timate duration thereof. ent markers and zones. filed within 30 days )-4 must be filed once	
14. I hereby certify that the foregoing is true and correct.         Electronic Submission #391727 verified by the BLM Well Information System         For OXY USA INC., sent to the Hobbs         Name (Printed/Typed)       DAVID STEWART       Title       SR. REGULATORY ADVISOR						
Waite (Printed Typed) UAVID ST	June SR. REV	OULTON' P				
Signature (Electronic	Date 10/12/20					
	THIS SPACE FOR FE	DERAL OR STATE	OFFICE USE		V	
Approved By Conditions of approval, if any, are attache certify that the applicant holds legal or eq which would entitle the applicant to condu Title 18 U.S.C. Section 1001 and Title 43	Title Trant or t lease Office	OR REC	ORD ONI	Date		
States any false, fictitious or fraudulent			withung to make	to any department or		
(Instructions on page 2) <b>** OPERA</b>	TOR-SUBMITTED ** OPERA	TOR-SUBMITTED *	* OPERATO	R-SUBMITTED	**	

## Additional data for EC transaction #391727 that would not fit on the form

## 32. Additional remarks, continued

32. Additional remarks, continued
tagged low, POOH. RIH & set pkr @ 32', test csg from 32-3436' to 500#, tested good.
9/29/2017 RIH w/ pkr, test below and above pkr to 500#, tested good. Contact BLM, wanted perf @ 3386' and sqz 55sx cmt. RIH & perf 4-1/2''/7" @ 3386', attempt to EIR, pressure to 1500#, no rate, rec BLM appr to spot plug. Rel pkr & POOH. RIH to 3436', M&P 25sx CI C cmt, PUH, WOC.
10/2/2017 RIH & tag cmt @ 3348', tagged low, start to POOH w/ tbg & operator dropped tbg. SI WO fishing tools. RIH w/ overshot, latch onto tbg & POOH & insoect tbg. RIH w/ pkr & set @ 3000'.
10/3/2017 RIH & perf 4-1/2''/7" @ 3253', attempt to EIR, pressure up to 1500#, no rate, rel pkr & POOH. RIH to 3303', M&P 25sx CL C cmt, PUH, WOC.
10/4/2017 RIH & tag cmt @ 3094', notified BLM, POOH. RIH & set pkr, RIH & perf 4-1/2''/7" @ 2979', attempt to EIR, pressure to 1500#, no rate, rel pkr & POOH. RIH to 3304', no rate, rel pkr & POOH. RIH to 3405', M&P 25sx CL C cmt, PUH, WOC.
10/4/2017 RIH & tag cmt @ 2910', POOH. RIH & set pkr @ 32', test below pkr to 1500#, no communication on 7", rel pkr, POOH.
10/5/2017 RIH & set pkr @ 2500', test csg to 500#, test good. RIH & perf 4-1/2''/7" @ 2823', attempt to EIR, pressured up, no rate, rel pkr & POOH. RIH to 2876', M&P 25sx CI C cmt, PUH, WOC.
10/6/2017 RIH & tag cmt @ 2547', notified BLM, approved tag & next plug. RIH & set pkr @ 2000', RIH & perf 4-1/2''/7" @ 2410', attempt to EIR, pressured up w/ no rate, rel pkr & POOH. RIH to 2547', M&P 25sx CL C cmt, PUH, WOC.
10/9/2017 RIH & tag cmt @ 2151', notified BLM, approved tag & next plug. RIH & set pkr @ 900', RIH & perf 4-1/2''/7" @ 1320', EIR on 7" csg, M&P 45sx CL C cmt, WOC.
10/10/2017 RUH & tag cmt @ 2151', notified BLM, approved tag & next plug. RIH & set pkr @ 900', RIH & perf 4-1/2''/7" @ 1320', EIR on 7" csg, M&P 45sx CL C cmt, WOC.
10/10/2017 RUH & tag cmt @ 2151', notified BLM, approved tag & next plug. RIH & set pkr