

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT**SUNDRY NOTICES AND REPORTS ON WELLS**
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.FORM APPROVED
OMB NO. 1004-0137
Expires: January 31, 20185. Lease Serial No.
NMLC064118
6. If Indian, Allottee or Tribe Name
7. If Unit or CA/Agreement, Name and/or No.**SUBMIT IN TRIPLICATE - Other instructions on page 2**

| | | |
|---|--|---|
| 1. Type of Well <input checked="" type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other | | 8. Well Name and No. E.C. HILL B FEDERAL 3 |
| 2. Name of Operator OXY USA INC. | | 9. API Well No. 30-025-10948 |
| 3a. Address P.O. BOX 50250 MIDLAND, TX 79710 | | 10. Field and Pool or Exploratory Area TEAGUE PADDOCK BLINEBRY |
| 3b. Phone No. (include area code) Ph: 432-685-5717 Fx: 432-685-5742 | | 11. County or Parish, State LEA COUNTY, NM |
| 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Sec 34 T23S R37E NWNE 840FNL 1655FEL 32.265762 N Lat, 103.147583 W Lon | | |

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

| TYPE OF SUBMISSION | TYPE OF ACTION | | | |
|---|---|--|---|--|
| <input type="checkbox"/> Notice of Intent | <input type="checkbox"/> Acidize | <input type="checkbox"/> Deepen | <input type="checkbox"/> Production (Start/ | INT TO PA _____ P&A NR _____ P&A R _____ |
| <input checked="" type="checkbox"/> Subsequent Report | <input type="checkbox"/> Alter Casing | <input type="checkbox"/> Hydraulic Fracturing | <input type="checkbox"/> Reclamation | |
| <input type="checkbox"/> Final Abandonment Notice | <input type="checkbox"/> Casing Repair | <input type="checkbox"/> New Construction | <input type="checkbox"/> Recomplete | |
| | <input type="checkbox"/> Change Plans | <input checked="" type="checkbox"/> Plug and Abandon | <input type="checkbox"/> Temporarily Abar | |
| | <input type="checkbox"/> Convert to Injection | <input type="checkbox"/> Plug Back | <input type="checkbox"/> Water Disposal | |

13. Describe Proposed or Completed Operation. Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

9/18/2017 MIRU PU, dig out WH, re-plumb surface lines and valves
9/19/2017 Kill well w/ 20bbl BW, POOH w/ rods & pump.
9/20/2017 NDWH, NU BOP. Rel TAC, POOH w/ tbg. RIH w/ gauge ring to 5028', POOH.
9/21/2017 RIH w/ CIBP & attempt to set, failed. WO WL truck, RIH w/ CIBP & set @ 4997', POOH.
9/22/2017 RIH w/ tbg & tag CIBP @ 4997', WO cmt truck
9/25/2017 Circ hole w/ 10# MLF, M&P 25sx CL C cmt @ 4997'-Calc TOC @ 4631', WOC.
9/26/2017 RIH w/ tbg & tag cmt @ 4759', BLM-Paul Flowers witnessed & approved tag & TOC, POOH. RIH w/ pkr, EOT @ 2980'. Load and test csg to 300#, test good, set pkr @ 2654'. RIH & perf 4-1/2"/7" @ 3445', start to POOH, unable to rel pkr, had to shear. POOH w/ tbg, EOT @ 1499'.
9/27/2017 Continue to POOH & LD tbg & pkr. RIH w/ tbg to 3567', start to pump cmt, pump truck failure.
9/28/2017 Load hole w/ 10# MLF, M&P 25sx CL C cmt w/ 2% CaCl₂, PUH, WOC. RIH & tag cmt @ 3436',

14. I hereby certify that the foregoing is true and correct.

Electronic Submission #391727 verified by the BLM Well Information System
For OXY USA INC., sent to the Hobbs

| | |
|------------------------------------|------------------------------|
| Name (Printed/Typed) DAVID STEWART | Title SR. REGULATORY ADVISOR |
| Signature (Electronic Submission) | Date 10/12/2017 |

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

| | | |
|---|--------------|------------|
| Approved By _____ | Title _____ | Date _____ |
| Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. | Office _____ | |

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED **

Additional data for EC transaction #391727 that would not fit on the form

32. Additional remarks, continued

tagged low, POOH. RIH & set pkr @ 32', test csg from 32-3436' to 500#, tested good.
9/29/2017 RIH w/ pkr, test below and above pkr to 500#, tested good. Contact BLM, wanted perf @ 3386' and sqz 55sx cmt. RIH & perf 4-1/2"/7" @ 3386', attempt to EIR, pressure to 1500#, no rate, rec BLM appr to spot plug. Rel pkr & POOH. RIH to 3436', M&P 25sx CL C cmt, PUH, WOC.
10/2/2017 RIH & tag cmt @ 3348', tagged low, start to POOH w/ tbg & operator dropped tbg. SI WO fishing tools. RIH w/ overshot, latch onto tbg & POOH & insoect tbg. RIH w/ pkr & set @ 3000'.
10/3/2017 RIH & perf 4-1/2"/7" @ 3253', attempt to EIR, pressure up to 1500#, no rate, rel pkr & POOH. RIH to 3303', M&P 25sx CL C cmt, PUH, WOC.
10/4/2017 RIH & tag cmt @ 3094', notified BLM, POOH. RIH & set pkr, RIH & perf 4-1/2"/7" @ 2979', attempt to EIR, pressure to 1500#, no rate, rel pkr & POOH. RIH to 3045', M&P 25sx CL C cmt, PUH, WOC. RIH & tag cmt @ 2910', POOH. RIH & set pkr @ 32', test below pkr to 1500#, no communication on 7", rel pkr, POOH.
10/5/2017 RIH & set pkr @ 2500', test csg to 500#, test good. RIH & perf 4-1/2"/7" @ 2823', attempt to EIR, pressured up, no rate, rel pkr & POOH. RIH to 2876', M&P 25sx CL C cmt, PUH, WOC.
10/6/2017 RIH & tag cmt @ 2547', notified BLM, approved tag & next plug. RIH & set pkr @ 2000', RIH & perf 4-1/2"/7" @ 2410', attempt to EIR, pressured up w/ no rate, rel pkr & POOH. RIH to 2547', M&P 25sx CL C cmt, PUH, WOC.
10/9/2017 RIH & tag cmt @ 2151', notified BLM, approved tag & next plug. RIH & set pkr @ 900', RIH & perf 4-1/2"/7" @ 1320', EIR on 7" csg, M&P 45sx CL C cmt, WOC.
10/10/2017 WO BLM, rel pkr, RIH & tag cmt @ 949', POOH. RIH & perf @ 364', RIH & set pkr @ 25', EIR, M&P 135sx CL C cmt, circ cmt to surf, POOH, top off csg, NDBOP, RDPU.