Form 3160-5 (Jame 2015)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

Date 10/03/2017

BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WEIGHS.

Do not use this form for proposals to drill or to re	Tarisdau.	riciu Ullice	i
phandoned well. Use form 3160-3 (APD) for such r	ronosals o	6 If Indian, Allottee or	Tribe Name
bandoned well. Use form 3160-3 (APD) for such p	"oposais. OCD	Hobbs	

abandoned we	II. Use form 3160-3 (AP	D) for such p	roposals.	CD H	obbs	i Tribe Ivani	
SUBMIT IN	TRIPLICATE - Other ins	tructions on	page 2		7. If Unit or CA/Agre	ement, Name	and/or No.
1. Type of Well					8. Well Name and No. HAMON FED CO		
○ Oil Well		MATT DICKS	NOS		9. API Well No.		- (
LEGACY RESERVES OPERA	ATING LÆ-Mail: mdickson@	plegacylp.com	7014		30-025-43248-0	00-X1	
3a. Address 303 W WALL SUITE 1600 MIDLAND, TX 79702		3b. Phone No Ph: 432-68	. (include area co 9-5200	de)	10. Field and Pool or TEAS	Exploratory A	Area
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description	)			11. County or Parish,	State	
Sec 6 T20S R34E SWSE 552	FSL 1914FEL				LEA COUNTY,	NM	
12. CHECK THE AF	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE	OF NOTICE	, REPORT, OR OTI	HER DAT	A
TYPE OF SUBMISSION			TYPE	OF ACTION			
Notice of Intent	☐ Acidize	☐ Dee	pen	☐ Produc	etion (Start/Resume)	□ Water	r Shut-Off
_	☐ Alter Casing	☐ Hyd	lraulic Fracturin	g Reclar	nation	■ Well	Integrity
☐ Subsequent Report	☐ Casing Repair	□ New	Construction	☐ Recom	plete	Other	ř
☐ Final Abandonment Notice	☐ Change Plans	_	g and Abandon		orarily Abandon		
	☐ Convert to Injection	Plug		☐ Water			
13. Describe Proposed or Completed Ope If the proposal is to deepen direction: Attach the Bond under which the wor following completion of the involved testing has been completed. Final At determined that the site is ready for final	ally or recomplete horizontally, rk will be performed or provide d operations. If the operation re bandonment Notices must be fil	give subsurface the Bond No. or sults in a multipl	locations and men in file with BLM/E le completion or r	asured and true s BIA. Required s ecompletion in a	vertical depths of all pertinubsequent reports must be new interval, a Form 316	nent markers filed within 60-4 must be	and zones. 30 days filed once
Legacy Reserves Operating re intermediate casing cement pr utilizing two DV tools. Both DV shoe and a minimum of 200 fe placement. Please see the foll	rocedures. This option wo / tools shall be set a mini- eet above the current sho	ould allow for mum of 50 fe e and adjust o	a three-stage et below the proportion	cement job revious casin tionately bas	ed on		
		CI	EE ATTA	CHED	FOR		
					APPROVAL		
		C	JNDITIO	JNS OF	AFFROVAL	,	
•							
14. I hereby certify that the foregoing is  Comm  Name (Printed/Typed) MATT DIC	Electronic Submission # For LEGACY RE itted to AFMSS for process	SERVES OPE	RATING LP, se RAH MCKINNE	nt to the Hobi	os 17 (17DLM1403SE)		
Name (Transactive and Transactive and Transact	DROON	-	THE DIVIL	LING LINGIN	LLIN		
Signature (Electronic S	Submission)		Date 06/23	3/2017			
	THIS SPACE FO	OR FEDERA	L OR STAT	E OFFICE (	JSE		

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

\_Approved By MUSTAFA HAQUE

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

(Instructions on page 2) \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED

TitlePETROLEUM ENGINEER

Office Hobbs

#### Hamon #7H

## Intermediate Casing

In the event that circulation is lost (> 50%) while drilling the 12-1/4" intermediate hole in the Capitan Reef at +/-4000', we will plan to install a DV tool and external casing packer within 200' of the top depth where lost circulation occurred and will pump a two-stage cement job with the potential to add an additional DV tool for a three-stage cement job. If there is no lost circulation a single stage cementing procedure will be followed. Legacy plans to cement to surface regardless of whether a single stage, 2-stage or 3-stage procedure is implemented.

#### No DV tool (80% excess on lead & 80% excess on tail to design for cement top at surface)

<u>Lead:</u> 1400 sx (35:65) poz (fly ash) class C cement+ 4% bwoc bentonite II + 5% bwoc MPA-5 + 0.25% bwoc FL- 52 + 5 lbs/sack LCM-1 + 0.125 lbs/sk cello flake+ 0.005 lbs/sk defoamer + 0.005 gps FP-6L + 1.2% bwoc Sodium Metasilicate + 5% bwow Sodium Chloride (12.5 ppg, 2.13 cfps, 8.81 gps wtr)

<u>Tail:</u> 200 sx class C cement (14.80 ppg, 1.33 cfps, 6.35 gps wtr)

## With (1) DV Tool (100% excess on lead & 100% excess on tail to design for cement top at surface)

Assuming DV tool set at 3950' but if the setting depth changes, cement volumes will be adjusted proportionately.

#### Stage 1

<u>Lead:</u> 400 sx (35:65) paz (fly ash) class C cement+ 4% bwoc Bentonite II+ 5% bwoc MPA-5 + 0,25% bwoc FL-52 + 5 lbs/sack LCM-1 + 0.125 lbs/sk cello flake+ 0.005 lbs/sk defoamer + 0.005 gps FP-6L + 1.2% bwoc Sodium Metasilicate + 5% bwow Sodium Chloride (12.5 ppg, 2.13 cfps, 8.81 gps wtr)

<u>Tail:</u> 200 sx class C cement (14.80 ppg, 1.33 cfps, 6.35 gps wtr)

#### Stage 2

<u>Lead</u>: 1100 sx (35:65) paz (fly ash) class C cement+ 4% bwoc bentonite II + 5% bwoc MPA-5 + 0,25% bwoc FL-52 + 5 lbs/sack LCM-1 + 0.125 lbs/sk Cello Flake+ 0.005 lbs/sk Static Free+ 0.005 gps FP-6L + 1.2% bwoc Sodium Metasilicate + 5% bwow Sodium Chloride (12.5 ppg, 2.13 cfps, 8.81 gps wtr)

<u>Tail:</u> 200 sx class C cement (14.80 ppg, 1.33 cfps, 6.35 gps wtr)

With (2) DV Tools (100% excess on lead & 100% excess on tail to design for cement top at surface)

Assuming one DV tool set at 3950' and one DV tool set at 1800' but if the setting depths change, cement volumes will be adjusted proportionately.

#### Stage 1

<u>Tail:</u> 200 sx class C cement (14.80 ppg, 1.33 cfps, 6.35 gps wtr)

#### Stage 2

<u>Lead</u>: 600 sx (35:65) paz (fly ash) class C cement+ 4% bwoc bentonite II + 5% bwoc MPA-5 + 0,25% bwoc FL-52 + 5 lbs/sack LCM-1 + 0.125 lbs/sk Cello Flake+ 0.005 lbs/sk Static Free+ 0.005 gps FP-6L + 1.2% bwoc Sodium Metasilicate + 5% bwow Sodium Chloride (12.5 ppg, 2.13 cfps, 8.81 gps wtr)

Tail: 200 sx class C cement (14.80 ppg, 1.33 cfps, 6.35 gps wtr)

### Stage 3

<u>Lead</u>: 600 sx (35:65) paz (fly ash) class C cement+ 4% bwoc bentonite II + 5% bwoc MPA-5 + 0,25% bwoc FL-52 + 5 lbs/sack LCM-1 + 0.125 lbs/sk Cello Flake+ 0.005 lbs/sk Static Free+ 0.005 gps FP-6L + 1.2% bwoc Sodium Metasilicate + 5% bwow Sodium Chloride (12.5 ppg, 2.13 cfps, 8.81 gps wtr)

Tail: 200 sx class C cement (14.80 ppg, 1.33 cfps, 6.35 gps wtr)

Matt Dickson
Drilling Engineer
(432)689-5204
mdickson@legacylp.com

# PECOS DISTRICT CONDITIONS OF APPROVAL

OPERATOR'S NAME: Legacy Reserves Operating

LEASE NO.: NMNM040406

WELL NAME & NO.: | 7H – Hamon Fed Com A

SURFACE HOLE FOOTAGE: | 552'/S & 1914'/E

BOTTOM HOLE FOOTAGE | 330'/S & 1060'/E SEC. 07

LOCATION: Section 06, T 20 S., R 34 E., NMPM

COUNTY: Lea County, New Mexico

#### A. CASING

## All previous COAs still apply except the following:

1. The minimum required fill of cement behind the 9 5/8 inch intermediate casing, which shall be set at approximately 5600 feet, is:

## Option 1:

- a. Cement to surface. If cement does not circulate to the surface, the appropriate BLM office shall be notified and a temperature survey utilizing an electronic type temperature survey with surface log readout will be used or a cement bond log shall be run to verify the top of the cement. Temperature survey will be run a minimum of six hours after pumping cement and ideally between 8-10 hours after completing the cement job.
- b. Wait on cement (WOC) time for a primary cement job is to include the lead cement slurry due to potash.
- c. Wait on cement (WOC) time for a remedial job will be a minimum of 4 hours after bringing cement to surface or 500 pounds compressive strength, whichever is greater.
- d. If cement falls back, remedial cementing will be done prior to drilling out that string.

## Option 2:

Operator has proposed DV tool at depth of 3950 feet, but will adjust cement proportionately if moved. DV tool shall be set a minimum of 50 feet below previous shoe and a minimum of 200 feet above current shoe. Operator shall submit sundry if DV tool depth cannot be set in this range.

a.	First stage to DV tool:
	This stage to DV tool.
	Cement to circulate. If cement does not circulate, contact the appropriate BLM office before proceeding with second stage cement job. Operator should have plans as to how they will achieve circulation on the next stage.
b.	Second stage above DV tool:
	Cement to surface. If cement does not circulate see A.1.Option 1.a, c-d above. Wait on cement (WOC) time for a primary cement job is to include the lead cement slurry due to potash.
ption 3	<u>3:</u>
roporti	r has proposed DV tool at depth of 1800 feet and 3950 feet, but will adjust cement onately if moved. DV tool shall be set a minimum of 50 feet below previous shoe
	inimum of 200 feet above current shoe. Operator shall submit sundry if DV tool nnot be set in this range.
	nnot be set in this range.
epth ca a.	nnot be set in this range.
epth ca a.	nnot be set in this range.  First stage to DV tool:  Cement to circulate. If cement does not circulate, contact the appropriate BLM office before proceeding with second stage cement job. Operator should have plans as to
a.	nnot be set in this range.  First stage to DV tool:  Cement to circulate. If cement does not circulate, contact the appropriate BLM office before proceeding with second stage cement job. Operator should have plans as to how they will achieve circulation on the next stage.
epth ca a. b.	nnot be set in this range.  First stage to DV tool:  Cement to circulate. If cement does not circulate, contact the appropriate BLM office before proceeding with second stage cement job. Operator should have plans as to how they will achieve circulation on the next stage.  Second stage above DV tool:  Cement to circulate. If cement does not circulate, contact the appropriate BLM office before proceeding with third stage cement job. Operator should have plans as to how

1. 11 ×