Submit 1 Copy To Appropriate District Office	State of New Mexico		Form C-103	
District I - (575) 393-6161	Energy, Minerals and Natural Resources OIL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505		Revised August 1, 2011	
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.	
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210			30-005-62389	~
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410			5. Indicate Type of Lease FEDERAL,	
<u>District IV</u> – (505) 476-3460				
1220 S. St. Francis Dr., Santa Fe, NM 87505		6. State Oil & Gas Lease No		
SUNDRY NOTICES AND REPORTS ON WELLS			NMNM-077993 Federal Lease 7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name of Onit Agre	Sement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCHED PROPOSALS.) 1. Type of Well: Oil Well Gas Well X Other		Inexco Federal	~	
1. Type of Well: Oil Well	Gas Well X Other		8. Well Number 002	~
2. Name of Operator	VOV	137017	9. OGRID Number	
State of New Mexico formerly McKay Oil Corp			14424	/
3. Address of Operator 1625 N. French Drive Hobbs, NM 88240 RECEIVED		10. Pool name or Wildcat		
	s, NM 88240 RE	CLIT	Pecos Slope Abo, West (Gas	s) /
4. Well Location				
	1905feet from theSouth_			
Section 25 Township 5S Range 22E 21E NMPM Chaves County				
11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
NOTICE OF INTENTAL SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK P				
I hereby certify that the information	above is true and complete to the b	est of my knowledg	e and belief.	
SIGNATURE	TITLE		DATE	
Type or print name	E-mail address:		PHONE:	
For State Use Only	2 man address			
M1.00	Whitelem TITLE P.E		DATE II/I	13/2017
APPROVED BY:	TITLE TIE	. 2.	DATE	3/201
Conditions of Approval (if any):				

Plugging Report Inexco Federal #2

Lat: 33.8435272578 Lon: -104.688367559

Moved in equipment. Installed matting board and rigged up. Blew down well and pumped 20 bbls down the casing. Unflanged the wellhead. There was no pipe in the well. Installed BOP. Moved pipe to location that came from the West McKay Harvey Fed A #1. RIH with gauge ring and sat down at 912'. POOH with wireline and RIH with bit and scrapper to 3087'. POOH with scraper and set CIBP at 3070'. There was a collar at 3062'. RIH with tubing and tagged CIBP at 3070'. Laid down 1 joint and SION.

11/9/2017 Circulated MLF and tested casing to 600#. Casing was good. Spotted 25 sx Class C cement on top of CIBP. POOH and perforated 4 ½" casing at 950". Set packer at 583". Broke down perfs and established a rate. There was no communication with the surface. Squeezed the perfs with 30 sx cement with CaCl. WOC 4 hrs. Left packer set and pressure tested plug. Held 500#. Released packer and tagged cement at 837". POOH to 101" and circulated cement to surface. SION.

. 11/10/2017 Cut off wellhead. Filled up both stings of casing with less than 1 sack of cement. Installed marker and cut off anchors. Cleaned pit.