Form 3160-5 (June 2015)

DEPARTMENT OF THE INTERIOR TISDAD FIELD OF BUREAU OF LAND MANAGEMENT Lease Serial No.

FORM APPROVED
OMB NO. 1004-0137
Expires: January 31, 2018

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an

NMNM53380

abandoned wel	6. If Indian, Allottee	or Tribe Name				
SUBMIT IN TRIPLICATE - Other instructions on page HOBBS OCD 7. If Unit or CA/Agreement, Name and/or No.						
Type of Well		8. Well Name and N CAVINESS 10 F				
Name of Operator MATADOR PRODUCTION CO	MMY R I INK	9. API Well No. 30-025-29981				
3a. Address 5400 LBJ FREEWAY, SUITE DALLAS, TX 75240	1500 F	b. Phone No. (include area code Ph: 575-627-2465	lo. (include area code) 10. Field and Pool or Exp			
4. Location of Well (Footage, Sec., T.	, R., M., or Survey Description)	/	11. County or Parish, State			
Sec 10 T18S R33E Mer NMP	SENW 2310FNL 330FEL		LEA COUNTY	, NM		
12. CHECK THE AF	PPROPRIATE BOX(ES) TO	O INDICATE NATURE O	F NOTICE, REPORT, OR OT	THER DATA		
TYPE OF SUBMISSION		ТҮРЕ О	F ACTION			
Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	■ Water Shut-Off		
-	☐ Alter Casing	☐ Hydraulic Fracturing	☐ Reclamation	■ Well Integrity		
☐ Subsequent Report	□ Casing Repair	■ New Construction	Recomplete	☐ Other		
☐ Final Abandonment Notice	☐ Change Plans	□ Plug and Abandon	□ Temporarily Abandon			
	☐ Convert to Injection	☐ Plug Back	■ Water Disposal			
Attach the Bond under which the wor following completion of the involved testing has been completed. Final Ab determined that the site is ready for fi BLM Bond: NMB0001079 Surety Bond: RLB0015172 See Attached Process and We	operations. If the operation result and on ment Notices must be filed nal inspection.	is in a multiple completion or reconly after all requirements, included the second sec	ompletion in a new interval, a Form 3	160-4 must be filed once d and the operator has		
, , ,	For MATADOR PRO Committed to AFMSS for p	4889 verified by the BLM We DDUCTION COMPANY, sent brocessing by MUSTAFA HA	to the Hobbs QUE on 10/24/2017 ()			
TANNOT IV	Name (Printed/Typed) TAMMY R LINK Title PRODUCTION ANALYST					
Signature (Electronic S		Date 08/16/2				
	THIS SPACE FOR	FEDERAL OR STATE	OFFICE USE			
Approved By Mustafa	Hague	Title	PETROLEUM ENGINEER	Date 10-30-201		
Conditions of approval, if any, are attached certify that the applicant holds legal or equ		Lines Inne	-RURFALL OF LAND MANAGEM	FNT		

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

which would entitle the applicant to conduct operations thereon.

** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED **

Office

GEBUREAU OF LAND MANAGEMENT

Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No. 1004-0137
Expires: January 31, 2018

5 Lease Serial No NMNM53380

6 If Indian, Allottee or Tribe Name

SUNDRY NOTICES AND REPORTS ON WELLS

	Use Form 3160-3 (A							
SUBMIT IN TRIPLICATE - Other instructions on page 2					7 If Unit of CA/Agreement, Name and/or No.			
1. Type of Well								
✓ Oil Well Gas Well Other					8 Well Name and No. Caviness 10 Federal #3			
2 Name of Operator Matador Produc			9 API Well No 30-025					
2 Add 2 Discovery No. (6 add 2 and 2					10 Field and Pool or Exploratory Area			
5400 LBJ Freeway, Sui Dallas, TX 75240	te 1500	(575) 623-660	1		Mescalero Escar Bone Spring			
4 Location of Well (Footage, Sec., T., F	R., M., or Survey Description)			11. Country or Parish, S	tate		
Sec 10 SENW, T18S, R33E; 2310)' FNL & 330' FEL	9			Lea County, NM			
12. CHE	ECK THE APPROPRIATE B	BOX(ES) TO IND	ICATE NATURI	E OF NOTI	CE, REPORT OR OTHE	ER DATA		
TYPE OF SUBMISSION			TY	PE OF AC	TION			
✓ Notice of Intent	Acidize Alter Casing	Deepe Hydra	n ulic Fracturing		uction (Start/Resume) amation	Water Shut-Off Well Integrity		
Subsequent Report	Casing Repair Change Plans		Construction nd Abandon	✓ Reco	omplete porarily Abandon	Other		
Final Abandonment Notice	Convert to Injection			-	er Disposal			
is ready for final inspection) o R/U Workover rig and pull ro o RIH with WL and log with pul o RIH with 2 7/8" work string ar -Squeeze existing perforation o Drill out cement retainer and o RIH with WL and perforate fro o RIH with 2 7/8" work string ar o RIH with 2 3/8" tubing and pr	ds and tubing currently in lsed neutron tool from TD nd set cement retainer at ons at 8573'-8646' with 30 cement. Pressure test to from 9240'-9260', 42 shots nd retrievable packer and roduce up tubing string	hole to top of cemen 8473'. Dbbls of Class H 5500 psig for 30 total.	t cement, perfor min.	rming hesit	lations at 2-5 min inter			
14 I hereby certify that the foregoing is Chris Villarreal	true and correct Name (Pr		Operation Title	ns Enginee	er			
Signature //			Date 08/17/2017					
	THE SPACE	E FOR FEDE	RAL OR S	TATE OF	ICE USE			
Approved by								
			Title		D	ate		
Conditions of approval, if any, are attac certify that the applicant holds legal or o which would entitle the applicant to cor	equitable title to those rights							
Title 18 U S C Section 1001 and Title 4	3 U S C Section 1212, make	e it a crime for any	person knowin	gly and will	Ifully to make to any dep	partment or agence the United States		

(Instructions on page 2)



406

3152

7465

9660

CURRENT WELLBORE SCHEMATIC Spudded: 8/5/1987 Int. Casing TOC @ 150


lole Size 17 1/2	Casing Size	Туре	Weight lb/ft	Joints	Depth Set
17 1/2	122/9				
	12 3/0		48	10	406
11	8 5/8	J-55	24, 32	75	3152
77/8	5 1/2	J-55	17	233	9,660
OV Tool larker Jt.	7465		The transfer of the second		
	7 7/8 V Tool	7 7/8 5 1/2 VV Tool 7465 arker Jt.	7 7/8 5 1/2 J-55 N/ Tool 7465 arker Jt.	7 7/8 5 1/2 J-55 17 V Tool 7465 arker Jt.	77/8 51/2 J-55 17 233 V Tool 7465 arker Jt.

			Cementing Record	
				400 sks Cl "C" (Circulated)
	Prod. Casing TOC @ 1800	Intermediate	(1)300 sks DLW II & 200	0 sks CI "C" & (2)430 sks DLW III & 100 sks "C" (TOC @ 150')
15		Production	(1)125 sks DLW III & 445	sks "H" (2)1340 sks DLW III & 100 sks "H" Neat (TOC @ 1800')

DV tool @ 7,465'

Tub	ing	Ro	ds	Geologic	Markers
Joints	267	Total	348	Rustler	1586
Diam.	2 3/8	7/8"	99	Cowden	
PBTD	9600	3/4"	228	Yates	3051
TA	8452	7/8"	21	Yates "A"	
SN	8736	1"		7 Rivers	3482
		Pony	4'	Bowers	3968
		Pump 2 x 1 1/4 x 24'		Queen	
				Penrose	4483
				Grayburg	
				San Andres	
				Delaware	5852
				Bone Spring	6508

		Tbg Anchor @ 8,452' (9/2/1987) 8573-8646 77 Holes Acdz w/ 7500 gal 20% SRA & 10000 gal of 28% NEFE
--	--	---



42 holes from 9,240'-9,270'

9660

9,100

4,910

100% Collapse

19,090

Caviness 10 Fed 3 30-025-29981 Matador Production Company Conditions of Approval

Notify BLM at 575-361-2822 (Eddy County) or 575-393-3612 (Lea County) a minimum of 24 hours prior to commencing work.

Work to be completed by January 30, 2018.

- Must conduct a casing integrity test before perforating and fracturing. Submit results to BLM. The CIT is to be performed on the production casing to max treating pressure. Notify BLM if test fails.
- 2. Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 3. Surface disturbance beyond the originally approved pad must have prior approval.
- 4. Closed loop system required.
- 5. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 6. Operator to have H2S monitoring equipment on location.
- 7. A minimum of a 2000 (2M) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (2M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.
- 8. Subsequent sundry required detailing work done, a C-102 form, and completion report for the new formations. Operator to include well bore schematic of current well condition when work is complete.

9. See attached for General Plugback Guidelines

MHH 10302017

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220

575-234-5972

Permanent Abandonment of Production Zone Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

- 1. Plug back operations shall commence within <u>ninety (90)</u> days from this approval. If you are unable to plug back the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged back. Failure to do so will result in enforcement action.
- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plug back operations. For wells in Eddy County, call 575-361-2822. For wells in Lea County, call 575-393-3612
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. Before pumping cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either **Neat Class "C"**, for up to 7,500 feet of depth or **Neat Class "H"**, for deeper than 7,500 feet plugs.

- 6. <u>Subsequent Plug back Reporting:</u> Within 30 days after plug back work is completed, file one original and three copies of the Subsequent Report, Form 3160-5 to BLM. The report should give in detail the manner in which the plug back work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date work was completed.</u> If plugging back to a new zone submit a Completion Report, form 3160-4 with the Subsequent Report.
- 7. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.