Submit 1 Copy To Appropriate District Office District II - (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240 District III - (575) 748-1283 811 S. First St., Artesia, NM 88210 District III - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 District IV - (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other 2. Name of Operator CHEVRON U.S.A. INC. 3. Address of Operator	Form C-103 Revised July 18, 2013 WELL API NO. 30-025-03109 5. Indicate Type of Lease STATE FEE 6. State Oil & Gas Lease No. 7. Lease Name or Unit Agreement Name HOBBS 'N' STATE 8. Well Number 2 9. OGRID Number 4323 10. Pool name or Wildcat
6301 DEAUVILLE BLVD, MIDLAND, TX 79706 4. Well Location	VACUUM; BLINEBRY
Unit LetterC:330feet from theNORTH line and1650feet from theWESTline	
Section 8 Township 18-S Range 35-E NMPM County LEA	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3953' (GL)	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPL DOWNHOLE COMMINGLE CASING/CEMENT JOB CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. Proposed procedure is as follows: 1. Call and notify NMOCD 24 hours before operations begins. 2. MIRU, NDWH, NU BOPE. 3. Pull equipment and test casing. 4. Set CIBP between 5970-5980', circulate well with packer fluid and spot 25 sxs or dump bail 35' of cement on top. 5. Notify NMOCD to witness pressure test of casing and chart. 6. File subsequent report with MIT chart to NMOCD.	
Proposed wellbore diagram is attached. Condition of Approval: notify	
OCD Hobbs office 24 hours	
Spud Date: Rig Release Date: prior of r	unning MIT Test & Chart
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNATURE	

Hobbs "N" State No. 2

