Submit 1 Copy To Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources			Form C-103 Revised August 1, 2011			
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Diergy, Willierans and Tyacarar Resol			WELL API N	10.		
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSE	CONSERVATION DIVISION		30-005-62221	1		
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	Brazos Pd. Aztec NM 87410				5. Indicate Type of Lease FEDERAL		
<u>District IV</u> – (505) 476-3460	Santa Fe, NM 87505			STATE FEE			
1220 S. St. Francis Dr., Santa Fe, NM 87505				6. State Oil & Gas Lease No Federal Lease NMNM-032330			
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)  HOBBS OCD				7. Lease Name or Unit Agreement Name			
				James Dan Fadand			
				Jerry Don Fe 8. Well Num			
Type of Well: Oil Well     Name of Operator	Gas Well X Other			9. OGRID Number			
State of New Mexico formerly McKay Oil Corp  DEC 2 6 2017				14424			
3. Address of Operator				10. Pool name or Wildcat			
1625 N. French Drive Hobbs, NM 88240 <b>RECEIVED</b>				Pecos Slope Abo, West (Gas)			
4. Well Location	700 6 6			700 6 . 6	.1	г. г.	
Unit LetterA:			h line and				
Section 24	Township  11. Elevation (Show		ange 21E		Chaves	County	
Tr. Elevation (Snow whether DR, RRB, RT, GR, etc.)							
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data							
NOTICE OF INTEI SUBSEQUENT REPORT OF:							
PERFORM REMEDIAL WORK ☐ PL REMEDIAL WOR						RING CASING	
TEMPORARILY ABANDON CI INT TO PA COMMENCE DRI				_	P AND	XX A C	
PULL OR ALTER CASING  M P&A NR CASING/CEMENT JOB							
DOWNHOLE COMMINGLE	P&AR	IM					
OTHER:			OTHER:				
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date							
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.							
proposed completion of recompletion.							
SEE ATTACHED							
I hereby certify that the information	above is true and com	plete to the bo	est of my knowledge	e and belief.			
			, .				
SIGNATURE	Т	TITLE			DATE		
SIGNATURE	1	TILE			_DATE		
Type or print name	F	E-mail address	s:		PHONE:		
For State Use Only	01.	0 1				1 . 1	
APPROVED BY: Market	Mitalam T	ITLE P.E	.5.		DATE 12	-126/2017	
Conditions of Approval (if any):						,	

## Plugging Report Jerry Don Federal #1

Lat: 33.9525452222 Lon: -104.685702708

12/5/2017 Cleared road to location with the backhoe. Moved rig in and spotted on location.

12/6/2017 Rigged up and started blowing the well down. Dug out the cellar and plumbed the surface head into the tank. Killed well and installed the BOP. Pulled and tallied the tubing. 86 joints in the well. Made gauge ring run to 2910'. Set CIBP at 2880'. There was a collar at 2876'. RIH with tubing from the well and brought pipe from the Antelope Fed #2 to get to the CIBP. SION

12/7/2017 Circulated MLF and tested casing to 500#. Casing good. Spot 25 sx cement on top of CIBP. POOH and perforated 4 ½" casing at 1137". Established circulation with 30 bbls. Squeezed perfs with 45 sx cement with CaCl. WOC and tagged cement at 976". Laid down remaining pipe and perforated at 100". Established circulation and pumped cement down 4 ½" casing to perfs at 100" and up annulus to surface. Took 30 sx. Will cut off in the morning.

12/8/2017 Dug out wellhead and cut off. Filled up  $4\frac{1}{2}$ " & 8 5/8" casing with 2 sx cement. Installed marker, cut off anchors, and cleaned the pit.