Form 3160-5 (June 2015)


UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018 5! Lease Serial No. NMLC069276


BUREAU OF LAND MANAGEMENT
SUNDRY NOTICES AND REPORTS ON WELL'S

abandoned wel	I. Use form 3160-3 (APD) for such	Direction	S. C. Oolf	Indian, Allottee or Tribe	Name	
SUBMIT IN 1	RIPLICATE - Other instructions or	page 2	P D If	Unit or CA/Agreement,	Name and/or No.	
Type of Well			8. We	8. Well Name and No. WEST CORBIN 19 02		
Name of Operator DEVON ENERGY PRODUCT	ACK		PI Well No. 0-025-33508-00-S1			
3a. Address 6488 SEVEN RIVERS HIGHW ARTESIA, NM 88211	o. (include area code) 52-4615		10. Field and Pool or Exploratory Area S CASS			
4. Location of Well (Footage, Sec., T		11. (County or Parish, State			
Sec 19 T18S R33E NWSW 21	173FSL 660FWL		Li	EA COUNTY, NM		
12. CHECK THE AI	PPROPRIATE BOX(ES) TO INDICA	ATE NATURE OF	F NOTICE, REPO	ORT, OR OTHER I	DATA	
TYPE OF SUBMISSION	TYPE OF ACTION					
Notice of Intent	☐ Acidize ☐ De	epen draulic Fracturing	☐ Production (S☐ Reclamation	INT TO PA	ff ,	
☐ Subsequent Report		ew Construction	Recomplete	P&A NR		
☐ Final Abandonment Notice		ug and Abandon	☐ Temporarily	P&A R		
	☐ Convert to Injection ☐ Pl	ug Back	☐ Water Dispo			
Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. 1. MIRU P&A unit. TIH and tag current PBD reported @ 9,885'. Circulate wellbore w/10# salt gel mud. 2. Spot 25 sx (200') CI H @ 8,561' - 8,361'. Tag TOC. (dv tool 8461') 3. Spot 30 sx (300') CI C @ 7,105' - 6,805'. Tag TOC. (bone spring 7055') 4. Spot 30 sx (300') CI C @ 2,910' - 2,510'. Tag TOC. (delaware 5225') 5. Spot 40 sx (400') CI C @ 2,910' - 2,510'. Tag TOC. (vates 2854'; b.salt 2665') 6. Spot 25 sx (250') CI C @ 1,550' - 1,300'. Tag TOC. (t.salt 1528') 7. Circulate 51 sx CI C from 510' to surface. 8. Cut wellhead off 3' below ground level. Set dry hole marker. SEE ATTACHED FOR CONDITIONS OF APPROVAL					ust be filed once operator has	
	Electronic Submission #398635 verification For DEVON ENERGY PRODUC Committed to AFMSS for processing by	TION COM LP, sen JIM AMOS on 01/	t to the Hobbs 02/2018 (18JA002	SSE)		
Name (Printed/Typed) RONNIE	SLACK	Title PRODU	CTION TECHNO	LOGIST		
Signature (Electronic S	Date 12/20/20)17				
	THIS SPACE FOR FEDER	AL OR STATE	OFFICE USE			
Approved By ZOTA STEVENS		TitlePETROLE	UM ENGINEER		Date 01/23/2018	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		1				
	U.S.C. Section 1212, make it a crime for any statements or representations as to any matter		willfully to make to a	nny department or agenc	y of the United	
(Instructions on page 2)						

FOR RECORD ONLY



	PRODUCTION COMPANY LP			
Well Name: WEST CORBIN 19 FEDERAL #2	Field: CORBIN SOUTH			
Location: 2173' FSL & 660' FWL; SEC 19-T185-R33E	County: LEA State: NM			
Elevation: 3810' KB; 3797' GL; 13' KB to GL	Spud Date: 4/27/97 Compl Date: 8/30/97			
API#: 30-025-33508 Prepared by: Ronnie Slack	Date: 12/20/17 Rev:			
17-1/2" hole 13-3/8", 48#, H40, 8RD , STC, @ 460' Cmt'd w/400 sx to surface	Proposed: 3. Set dry hole marker. 2. Cut wellhead off 3' below ground level. 1. Circulate 51 sx Cl C from 510' to surface.			
	10# Mud Proposed: 1. Spot 25 sx (250') CI C @ 1,550' - 1,300'. Tag. (7. Salt 1528') 10# Mud			
11" Hole 8-5/8", 32#, J55, 8RD, STC, @ 2,860' Cmt'd w/750 sx to surface	Proposed: 1. Spot 40 sx (400') Cl C @ 2,910' - 2,510'. Tag. (Yates 2854'; B.Salt 2665')			
	10# Mud Proposed: 1. Spot 30 sx (300') CI C @ 5,275' - 4,975'. Tag. (Delaware 5225') 10# Mud			
Tested casing to 595 psi. Bled to 460 psi in 1 hr. (12/14/17)	Proposed: 1. Spot 30 sx (300') CI C @ 7,105' - 6,805'. Tag. (Bone Spring 7055')			
DV Tool @ 8,461'	10# Mud Proposed: 1. Spot 25 sx (200') Cl H @ 8,561' - 8,361'. Tag.			
	10# Mud			
WOLFCAMP (10/19/08) 10,343' - 10,354' 2 spf, 120° 10/22/08: acidized 10343-50' w/1500 gal 15% HCl	Tagged TOC @ 9,885'. (12/13/17) Spot 50 sx CI H @ 10,290'. (12/12/17) CIBP @ 10,290' (12/11/17)			
WOLFCAMP (8/97) 11,080' - 11,086'	Published days of the service of the			
WOLFCAMP (8/97) 11,102' - 11,106' Sqzd w/50 sx Cl H @ 3500 psi				
7-7/8" Hole 5-1/2", 17#, N80, 8RD, LTC, @ 11,350' Cmt'd Stg 1 w/575 sx, Circ 0 sx off DV Cmt'd Stg 2 w/1,375 sx. Circ 64 sx to pit	11,350' TD			



BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days (APRIL 23, 2018) from the approval date of this Notice of Intent to Abandon.

If you are unable to Recomplete the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be Recompleted. Failure to do so will result in enforcement action.

The rig used for the Recomplete procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any Recomplete operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat

Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

- 7. <u>Subsequent Recomplete Reporting:</u> Within 30 days after Recomplete work is completed, file one original and three copies of the Subsequent Report of Recomplete, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was recompleted.**
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.