State of New Mexico Office District I – (575) 393-6161 District II – (575) 748-1083 District II – (575) 748-1083	Form C-103
1625 N. French Dr., Hobbs, NACOS	Revised July 18, 2013
District II - (575) 748-1283	WELL API NO. 30-025-07578
811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION	5. Indicate Type of Lease
District II – (575) 748-1033 811 S. First St., Artesia, NM 88210 District III – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	STATE FEE
District IV - (505) 476-3460 Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1000 Rio Brazos Rd., Aztec, 185/410 <u>District IV</u> – (505) 476-3460  1220 S. St. Francis Dr., Santa Fe, NMCE  87505  SUNDAY NOTICES AND REPORTS ON WELLS	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	North Hobb (G/SA) Unit
1. Type of Well: Oil Well Gas Well Other Temporarily Abandoned	8. Well Number 221
2. Name of Operator Occidental Permian, Ltd	9. OGRID Number 157984
3. Address of Operator	10. Pool name or Wildcat
HCR 1 Box 90 Denver City, TX 79323	Hobbs (G/SA)
4. Well Location	110000 (0.01.)
Unit Letter F: 1980 feet from the North line and 17	oo feet from the West line
Section 34 Township 18-S Range 38-E	NMPM Lea County
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
3625' GL	
12. Check Appropriate Box to Indicate Nature of Notice,	Report or Other Data
NOTICE OF INTENTION TO: SUB-	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORL	
TEMPORARILY ABANDON	LLING OPNS. P AND A
PULL OR ALTER CASING   MULTIPLE COMPL   CASING/CEMENT	JOB
DOWNHOLE COMMINGLE	
CLOSED-LOOP SYSTEM OTHER: TA Status extension request OTHER:	П
13. Describe proposed or completed operations. (Clearly state all pertinent details, and	give pertinent dates, including estimated date
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Con	npletions: Attach wellbore diagram of
proposed completion or recompletion.	
Run MI test to gain extension on temporary abandoned status.	
Tan in test to gain extension on temperary are necessary	
Condition of An	provel notify
Condition of Ap	•
Condition of Ap OCD Hobbs of	•
OCD Hobbs of	fice 24 hours
	fice 24 hours
OCD Hobbs of	fice 24 hours IIT Test & Chart
OCD Hobbs of prior of running M	fice 24 hours IIT Test & Chart
OCD Hobbs of	fice 24 hours IIT Test & Chart
OCD Hobbs of prior of running M	fice 24 hours IIT Test & Chart
OCD Hobbs of prior of running M  Spud Date:  Rig Release Date:	fice 24 hours IIT Test & Chart
OCD Hobbs of prior of running M	fice 24 hours IIT Test & Chart
OCD Hobbs of prior of running M  Spud Date:  Rig Release Date:  I hereby certify that the information above is true and complete to the best of my knowledge and the prior of running M  Rig Release Date:	fice 24 hours  IIT Test & Chart  and belief.
OCD Hobbs of prior of running M  Spud Date:  Rig Release Date:	fice 24 hours IIT Test & Chart
OCD Hobbs of prior of running M  Spud Date:  Rig Release Date:  I hereby certify that the information above is true and complete to the best of my knowledge SIGNATURE Admin. Associate	fice 24 hours  IIT Test & Chart  and belief.  DATE 01/30/2018
OCD Hobbs of prior of running M  Spud Date:  Rig Release Date:  I hereby certify that the information above is true and complete to the best of my knowledge and the prior of running M  Rig Release Date:	fice 24 hours  IIT Test & Chart  and belief.  DATE 01/30/2018
Spud Date:  Rig Release Date:  Thereby certify that the information above is true and complete to the best of my knowledge SIGNATURE Company TITLE Admin. Associate  Type or print name Mendy A. Johnson E-mail address: mendy_johnson	fice 24 hours  IIT Test & Chart  and belief.  DATE 01/30/2018

NO PROD REPORTED-212 MONTHS