Form 3160-5 (June 2015)

# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

NMOCD Hobbs

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018


#### 5. Lease Serial No. NMLC032099A

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.


6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on page 2				7. If Unit or CA/Agreement, Name and/or No.	
1. Type of Well  ☑ Oil Well ☐ Gas Well ☐ Other				8. Well Name and No. EUNICE MONUMENT SOUTH UNIT 413	
2. Name of Operator XTO ENERGY, INC  Contact: STEPHANIE RABADUE E-Mail: stephanie_rabadue@xtoenergy.com				9. API Well No. 30-025-04673	
3a. Address 500 W. ILLINOIS ST STE 100 MIDLAND, TX 79701	lo. (include area code) 620-6714	ea code)  10. Field and Pool or Exploratory Area EUNICE MONUMENT; GB-SA			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				11. County or Parish, St	tate
Sec 18 T21S R36E Mer NMP 660FSL 660FWL				LEA COUNTY, N	IM
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA					
TYPE OF SUBMISSION	TYPE OF ACTION				
☐ Final Abandonment Notice ☐ Chan	Casing Hy ng Repair No ge Plans Pl	eepen  Adraulic Fracturing  Ew Construction  Lug and Abandon  Lug Back	<ul> <li>□ Production (Start/Resume)</li> <li>□ Reclamation</li> <li>□ Recomplete</li> <li>☒ Temporarily Abandon</li> <li>□ Water Disposal</li> </ul>		☐ Water Shut-Off ☐ Well Integrity ☐ Other
13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.  XTO Energy, Inc respectfully requests a 5-Year Temporary Abandon based on economics for the referenced well using the following procedure:  1. Set CIBP @ 3747?  2. Cap w/25sx cmt thru tbg or 35? via wireline  3. WOC 4 hours. Tag.  4. Run good MIT.  A closed-loop system will be used to perform this procedure.  SEE ATTACHED FOR CONDITIONS OF APPROVAL  WILL Les a Waddy Seen Shution 14 or 20 personal.					
14. I hereby certify that the foregoing is true and correct.  Electronic Submission #401784 verified by the BLM Well Information System					
For XTO ENERGY, INC, sent to the Hobbs Committed to AFMSS for processing by PRISCILLA PEREZ on 02/01/2018 ()					
Name (Printed/Typed) STEPHANIE RABAD	Title REGUL	EGULATORY ANALYST			
Signature (Electronic Submission)		Date 01/22/20	018	PPROVED	
THIS SPACE FOR FEDERAL OR STATE OFFICE USE					
	. A		/ FI	EB 2 2 2018	VAL
Approved By  Conditions of approval, if any, are attached. Approval certify that the applicant holds legal or equitable title to which would entitle the applicant to conduct operations	Office	BUREAU Q	FLANDWANAGENE	Date	
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.					
(Instructions on page 2)  ** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED **					

## **WELL DATA SHEET**



## **WELL DATA SHEET**



#### BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Approved for a period of 1 year ending 02/22/2019 subject to conditions of approval.

Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
  - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging. CIBP must be capped with minimum 25 sacks cement, placed with tubing, or 35 feet of cement if placed with bailer.
  - b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. Any leak-off will be evaluated.
  - c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
  - d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
  - e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned. 43 CFR 3162.3-4 (a) The operator shall promptly plug and abandon...wells in which oil or gas is not encountered in paying quantities...

Wells that successfully pass the casing integrity test **may** be approved for Temporary Abandonment (TA) status provided that the operator:

- 1. **Submits a subsequent Sundry Notice** (Form 3160-5) requesting TA approval <u>with wellbore diagram</u> with all perforations and CIBP's and tops of cement on CIBP's.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

#### **Eunice Monument South Unit 413**

- 1. Well is approved to be TA/SI for a period of 1 year or until 02/22/2019
- 2. Must submit NOI to recomplete or NOI to P&A. Must be submitted by 02/22/2019
- 3. COA's met at this time.