Submit 1 Copy To Appropriate District Office	State of New Mexico	Form C-103
District I - (575) 393-6161 1625 N French Dr. Hobbs NM 88240	Minerals and Natural Resources	Revised July 18, 2013 WELL API NO.
District II - (575) 748-1283	NEEDWATION DIVISION	30-025-07539
District I – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283 811 S. First St., Artesia, NM 88240 District III – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 AR District IV – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505		5. Indicate Type of Lease
District III - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 AR District IV - (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505		STATE FEE 6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	, 1411 07303	6. State Off & Gas Lease No.
SUNDRY NONCES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		North Hobbs (G/SA) Unit
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other Injector		8. Well Number 341
Name of Operator Occidental Permian LTD		9. OGRID Number
3. Address of Operator		157984 10. Pool name or Wildcat
PO Box 4294 Houston, TX 77210		Hobbs (G/SA)
4. Well Location		
Unit Letter O: 330 feet from the S line and 2310 feet from the E line		
	nship 18S Range 38E	NMPM County Lea
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
3627' GL		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ☒ ALTERING CASING ☐		
TEMPORARILY ABANDON		
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB		
DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM		
OTHER:	☐ OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date		
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
MIRU x NDWH x NUBOP		
POOH 124 jts tbg X pkr		
• RIH 4 1/8" bit x tagged @ 4310'		
• Shot new perfs @ 4075' – 4082'		
• RIH 5 ½" CIBP @ 4233' x dumped 3' cmt		
Ran acid job w/ 250 gals PAD acid x 25 bbls BW		
 RIH on/off tool@ 3889' x pkr 3895 @ x 123 jts tbg @ 3888' 		
Ran MIT chart – Chart attached		
 RD x NDBOP X NUWH 		
Spud Date: 11/06/2017	Rig Release Date: 11/09/201	7
The description of the state of	la constituta de la la constitución de la constituc	11.11.6
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
LUMPI V X/ARK		
SIGNATURE ////	TITLE Regulatory Specialist	DATE 03/08/18
Type or print name April Hood	E-mail address: April_Hood@Oxy	y.com PHONE: 713-366-5771
For State Use Only	1 /	1
APPROVED BY: VAPUR SIGNON TITLE AD/II DATE 3/12/2018		
Conditions of Approval (if any):		

