(Instructions on page 2)

NMOCD

Form 3160-5 (June 2015)	UNITED STATES DEPARTMENT OF THE INTERIOR		Ho	OCI bbs	OMB No. 1004-0137		
1	BUREAU OF LAND MANAG	GEMENT	25 OCP		5. Lease Serial No. NMNM103880		
BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter and 2018 abandoned well. Use Form 3160-3 (APD) for such provides to					6. If Indian, Allottee or Tribe Name		
Do not use t	his form for proposals to rell. Use Form 3160-3 (API	drill or to re-	enter an	& Silio			
			Pugara	-NE	7. If Unit of CA/Agreem	ent, Name and/or No.	
1. Type of Well	IT IN TRIPLICATE - Other instruct	ions on page 2	REC	Ela	3	,	
✓ Oil Well Gas Well Other					8. Well Name and No. Cedar Point 14-L Federal #1		
2. Name of Operator Hunt Cimarron Limited Partnership					9. API Well No. 30-005-29153		
3a. Address P.O. Box 1592 3b. Phone No. (include area code) Roswell, New Mexico 88202-1592 (575) 623-9799					10. Field and Pool or Exploratory Area		
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description)					11. Country or Parish, State		
1980' FSL & 660' FWL, Section 14, T15S, R30E, NMPM					Chaves County, New Mexico		
12	CHECK THE APPROPRIATE BOX	K(ES) TO INDICA	TE NATURI	E OF NOTIC	CE, REPORT OR OTHE	R DATA	
TYPE OF SUBMISSION TYPE OF AG					TION	_	
Notice of Intent	Acidize	Deepen			uction (Start/Resume) INT TO PA		Δ
_	Alter Casing Casing Repair	Hydraulic New Const			mation mplete	P&A NR	
✓ Subsequent Report	Change Plans	✓ Plug and A			orarily Abandon	P&AR	PM
Final Abandonment Notice		Plug Back		=	Disposal		
is ready for final inspection.) Notify BLM-Roswell. Rot 12/15/17: MIRU PU. Unf 12/16/17: Finish tallying of 12/21/17: Attempt to set of 12/22/17: Plug #1: Set Cl 12/26/17: Tag plug #1 wif 12/28/17: Plug #2: Set Cl 01/05/18: Load well with Pull up to 3435 Plug #3: pump 01/08/18: Tag plug #3 at Plug #4: Squee	ent Notices must be filed only after all pert Hoskinson with BLM on location ange wellhead and nipple up BOF out with the tubing. Rig up cement CIBP at 8700'. Wireline truck breat BP at 8700'. Dump 35' class "H" the tubing at 8673'. Pump 80 bbls. BP at 5850'. Circulate 90 bbls. BP at 5850'. Circulate 90 bbls. of 10 bbls. of 10.5# plug mud. Pump. Load hole with 15 bbls. 10.5# plug mud. Pump. 35 sx 14.8# class "C" from 3435' to 3199'. RU wireline and perforate tize and pump 200 sx 14.8# class 'd and weld dry hole marker plate.	on to witness each P. Begin tallying to pump. SD waiting the down. SD. cement on CIBP. of 10.5# plug mud. 10.5# plug mud. 10.5# class way mud. 10.5# plug mud.	th day. tubing out on gon wirel SD. d. SD. SD. ss "C" ceme ed with 17 and circulat	of well. SD. ine truck. ent from 58s bbls. 10.5# te 15 bbls. 6	Approved as wearly a Lit is reclined un ration is community to 5602'. Displaced plug mud. SD. of 10.5# plug mud.	to plugging of ability under batil surface recorded with 32 bbls. 10.5	f the cond
	oing is true and correct. Name (Printe	ed/Typed)	President			E B	\$ /
Richard C. Gilliland		Title	Title				1
Signature Rohan Cha	lland	Date	;	TAI	CEPTEOBIOGIZO1	A ECORD	
	THE SPACE F	OR FEDERA	L OR ST	ATE OF	CEUSE		no
Approved by			Title		MAR 1 2		
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.					BUREAU OF LAND CARLSBAD FI	MANAGEMENT / ELD OFFICE	
	Fitle 43 U.S.C Section 1212, make it a statements or representations as to any			gly and willf	fully to make to any depa	rtment or agency of the	ne United States