

Submit 1 Copy To Appropriate District
Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87411
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised July 18, 2013

HOBBBS OGD MAR 29 2018 RECEIVED		OIL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505	
SUNDRIY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-42469	
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/> Injector		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>	
2. Name of Operator Occidental Permian LTD		6. State Oil & Gas Lease No.	
3. Address of Operator PO Box 4294 Houston, TX 77210		7. Lease Name or Unit Agreement Name North Hobbs G/SA Unit	
4. Well Location Unit Letter P : 837 feet from the S line and 1277 feet from the E line Section 18 Township 18S Range 38E NMPM County Lea		8. Well Number 953	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3677' KB		9. OGRID Number 157984	
		10. Pool name or Wildcat Hobbs; Grayburg - San Andres	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	P AND A <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPL <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>	
DOWNHOLE COMMINGLE <input type="checkbox"/>			
CLOSED-LOOP SYSTEM <input type="checkbox"/>			
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

MIRU x NDWH x NUBOP.
POOH tbg x pkr.
RIH 6 1/8" bit x tagged @ 4692'.
Perf'd 4372' - 4392'.
Pumped 3800 gals 15% NEFE acid x flushed well.
RIH on/off tool x pkr 4320' @ x 132 jts tbg @ 4312'.
Ran MIT chart - Chart attached.
RD x NDBOP X NUWH.

Spud Date:

01/15/2018

Rig Release Date:

01/19/2018

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE April Hood TITLE Regulatory Specialist DATE 03/21/2018

Type or print name April Hood E-mail address: April_Hood@Oxy.com PHONE: 713-366-5771

For State Use Only

APPROVED BY: Mary Brown TITLE AO/II DATE 4/3/2018

Conditions of Approval (if any):

RBDMS-CHART-✓

RECEIVED

MAR 29 2018

HOBBS OCD

Graphic Controls

DATE 1-19-18
BR 2221

PRINTED IN U.S.A.

Start
Post Wakeover
Oxy
Rel. Hobbs 6500 # 9500
30-015-41169-00-00
P 18-18-3 Hz
cal date 7-24-17
Ser. # 12517
1000 #
60 mm
Start 590
End 590
1/2 mm
Harry Robinson
Cmci Per. Intk

End