B	UNITED STATES EPARTMENT OF THE IN UREAU OF LAND MANAC NOTICES AND REPOR is form for proposals to o II. Use form 3160-3 (APD	TERIOR GEMENT NMO RTS ON WELLS Hob drill or to re-enter an o) for such proposals.	CD 5. Lease Serial No NMLC03174 6. If Indian, Allotte	0B	
SUBMIT IN TRIPLICATE - Other instructions on page 2 HOBBS C				greement, Name and/or No.	
1. Type of Well Soli Well Gas Well Other					
2. Name of Operator XTO ENERGY INC		PATRICIA DONALD nald@xtoenergy.com	ECEIVE BPI Well No.	4	
3a. Address     3b. Phone No. (include area code)       6401 HOLIDAY HILL ROAD BUILDING #5     Ph: 432-571-8220       MIDLAND, TX 79707     Ph: 432-571-8220			10. Field and Pool	or Exploratory Area NUMENT; GB-SA	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Sec 3 T21S R36E 661FSL 663FWL			11. County or Pari	sh, State Y COUNTY, NM 🖌	
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA					
TYPE OF SUBMISSION		TYPE OF ACTION			
<ul> <li>Notice of Intent</li> <li>Subsequent Report</li> <li>Final Abandonment Notice</li> </ul>	<ul> <li>Acidize</li> <li>Alter Casing</li> <li>Casing Repair</li> <li>Change Plans</li> <li>Convert to Injection</li> </ul>	<ul> <li>Deepen</li> <li>Hydraulic Fracturing</li> <li>New Construction</li> <li>Plug and Abandon</li> <li>Plug Back</li> </ul>	<ul> <li>Production (Start/Resume)</li> <li>Reclamation</li> <li>Recomplete</li> <li>Temporarily Abandon</li> <li>Water Disposal</li> </ul>	<ul> <li>Water Shut-Off</li> <li>Well Integrity</li> <li>Other</li> </ul>	
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. XTO SUBMITS THIS SUNDRY TO REPORT THE REFERENCED WELLBORE TA'. 03/12-03/17/2018: MIRU POH LD GE ESP. WIH W/ 7' SCRAPPER POH RIH W/ 5.5 SCARPPER TO 3423 RIH W. PKRS SET AT 3717 LOAD AND TEST CAG TO 600 PSI HELD GOOD. RIH W/ 5.5 CIBP SET T 3439'. MADE 2 CMT BAILER RUNS WOC. TAGGED CMT AT 3401'. NM BOP NU WH RUN OFFICIAL MIT TO 580 PSI WITNESSED BY PAT HUTCHINS W/ BLM RDMO WB OFFICIALLY TA'.					
TA approved Plug or Pro	turone year	3/17/201 °	7/2014.		
	Electronic Submission #4 For XTO Committed to AFMSS for p A DONALD	AC	CHEZ on 03/20/2018 () ATORY ANALYST	QRD	
THIS SPACE FOR FEDERAL OR STATE OFFICE USE					
Approved By Conditions of approval, if any, are attached certify that the applicant holds legal or eq which would entitle the applicant to condu	ed. Approval of this notice does r uitable title to those rights in the	not warrant or	CARESBAD VIELD OF ICED	A Date	
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.					
(Instructions on page 2) <b>** OPERA</b>	TOR-SUBMITTED ** OF Accepted for Re MUSB/OCD 4	cord, Only	* OPERATOR-SUBMITTE	ED **	

\*

