Submit 1 Copy To Appropriate District Office	State of New Me		Form C-103 Revised August 1, 2011
<u>District I</u> – (575) 393-6161 Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NHOBBS OCD		rai Resources	WELL API NO.
District II - (575) 748-1283 811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION		30-025-28357	
District III - (505) 334-6178 MAY 07 2018 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410 1000 Rio Brazos Rd., Aztec, Rd		5. Indicate Type of Lease STATE FEE	
1000 Rio Brazos Rd., Aztec, NM 87470 District IV – (505) 476-3460 Santa Fe, NM 87505		6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Ferre ECEIVED			
SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		South Hobbs (G/SA) Unit	
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other:		8. Well Number: 154	
2. Name of Operator		9. OGRID Number: 157984	
Occidental Permian Ltd.		10 P 1 W''ll 4 H H (C/CA)	
3. Address of Operator HCR 1 Box 90 Denver City, TX 79323		10. Pool name or Wildcat Hobbs (G/SA)	
4. Well Location			
Unit Letter B: 1163 feet from the South line and 2600 feet from the East line			
Section 9 Township 19S Range 38E NMPM Lea County			
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
3611.8' (KB)			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
12. Check Appropriate Box to indicate Nature of Notice, Report of Other Data			
			SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI			
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT			_
DOWNHOLE COMMINGLE		0,101110,02111211	
OTHER. Convert to Injust	or 🖂	OTHER.	
OTHER: Convert to Injector OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of			
proposed completion or recompletion.			
1. MIRU PU. POOH with ESP Eq	uipment		and the world not use
2. Att with oil and deepen wen to 4100			procedure we plan to use
3. Run GR/CNL/CCL/CBL the closed-			loop system with a steel
4. Stimulate existing pay with 2000 gal 15% HCL 5. Selectively perforate per 150 HCNL logs disposal per ODC Rule 19.15.17			
6. Stimulate new pay with 15% HCL			
7. RIH with CICR and cement squeeze OH (4315'-4400') with 100 sx			
Class C Cement 8. RIH with injection equipment and set injection packer at 4110'			
9. Circulate packer fluid			
10. Perform MIT			
11. RDPU			
Spud Date:	Rig Release Da	te:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
1			
SIGNATURE TITLE Production Engineer DATE 05/07/2018			
SIGNATURE TITLE Production Engineer DATE 05/07/2018			
Type or print name Jacob S. Cox E-mail address: Jacob Cox@oxy.com PHONE: 713-497-2053			
For State Use Only			
APPROVED BY: VOLUME STOWN TITLE AO/IL DATE 5/7/2018			
Conditions of Approval (if any)			

MB