

Submit 1 Copy To Appropriate District Office

District I - (575) 393-6161

1625 N. French Dr., Hobbs, NM 88240

District II - (575) 748-1283

811 S. First St., Artesia, NM 88210

District III - (505) 334-6178

1000 Rio Brazos Rd., Aztec, NM 87412

District IV - (505) 476-3800

1220 S. St. Francis Dr., Santa Fe, NM

87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised July 18, 2013

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.
30-025-43074

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

North Hobbs G/SA Unit

8. Well Number 668

9. OGRID Number

157984

10. Pool name or Wildcat

Hobbs; Grayburg - San Andres

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☐ Other ☐ Injector

2. Name of Operator

Occidental Permian LTD

3. Address of Operator

PO Box 4294 Houston, TX 77210

4. Well Location

Unit Letter H : 2132 feet from the N line and 635 feet from the E line

Section 24 Township 18S Range 37E NMPM County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

3627' GL

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

DOWNHOLE COMMINGLE ☐

CLOSED-LOOP SYSTEM ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ P AND A ☐

CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

MIRU x NDWH x NUBOP. POOH on/off tool. Test Csg to 600 psi, lost all psi in 2 min.

Pressure test tbg to 2000 psi, lost 120 psi in 30 min. Release PKR x Pooh 7" pkr x tbg.

Rih w/ 6 1/8 bit n PU 125 jts 2 7/8. RIH 7" CIBP @ 4569'. RIH 7" RBP @ 4428.

Pressure tested csg, held good. Ran acid job w/ 3000 gals 15% NEFE x flushed csg.

POOH RBP x dump 3' cmt on CIBP. RIH w/ 134 jts tbg @ 3944' x PKR @ x on/off tool.

Ran MIT - Chart Attached. RD x NDBOP x NUWH.

Spud Date:

03/29/2018

Rig Release Date:

04/09/2018

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

April Hood

TITLE Regulatory Specialist

DATE 06/14/2018

Type or print name April Hood

E-mail address: April_Hood@Oxy.com

PHONE: 713-366-5771

For State Use Only

APPROVED BY:

Mary Brown

TITLE

AO/I

DATE

6/21/2018

Conditions of Approval (if any):

RBDMS - CHART - ✓

72 MIN

STRA

0x11
46494
A-035-4304
CALC Date 11/24/12
10008
Sent Den 35
Smt - 5804
End - 5654
35 min
Reverse Vol
2/2/12