Submit 1 Copy To Appropriate District State of New Mexico Form C-103 Office Revised July 18, 2013 Energy, Minerals and Natural Resources District I - (575) 393-6161 WELL API NO. 1625 N. French Dr., Hobbs, NM 88240 30-025-31423 <u>District II</u> - (575) 748-1283 OIL CONSERVATION DIVISION 811 S. First St., Artesia, NM 88210 5. Indicate Type of Lease District III - (505) 334-6178 1220 South St. Francis Dr. STATE X FEE \square 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 6. State Oil & Gas Lease No. District IV - (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A South Hobbs G/SA Unit DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) Gas Well Other HOBBS OCD 8. Well Number 235 1. Type of Well: Oil Well X 2. Name of Operator 9. OGRID Number Occidental Permian LTD .IIII 2 4 2**018** 157984 Address of Operator 10. Pool name or Wildcat PO Box 4294 Houston, TX 77210 Hobbs; Grayburg - San Andres RECEIVED 4. Well Location Unit Letter 2160 feet from the line and 2414 feet from the line Section 4 Township **19S** Range **NMPM** County Lea 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3622' KB 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK □ PLUG AND ABANDON REMEDIAL WORK ALTERING CASING □ X COMMENCE DRILLING OPNS. TEMPORARILY ABANDON CHANGE PLANS P AND A MULTIPLE COMPL \Box CASING/CEMENT JOB PULL OR ALTER CASING DOWNHOLE COMMINGLE **CLOSED-LOOP SYSTEM** OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. MIRU. The had 1000 psi x csg had 1000 psi. Circ 15 bbls down the x circ 90 bbls down the up csg. Got rate of 1/2bpm @ 600 psi. NDWH x NUBOP x pulled ESP, which was stuck. Spotted 250 gals 15% NEFE x flushed w/ 20 bbls. Pulled ESP but was unsuccessful. Spotted another 250 gals 15% NEFE x pulled ESP but still couldnt get it free. Flushed acid w/ 20 bbls BW. Ran stuck pipe log, which indicated no obstruction behind the pipe. Cut tbg @ 3835' w/ chemical cutter. POOH 118jts x ESP cable came out. RIH x latched onto fish. Pulled ESP X it came loose. ESP equipment had iron sulfide inside, pumps were stiff, seals were ok, motor was grounded. RIH w/ 43/4" bit x tagged TOL @ 3950'. Circ well clean getting iron sulfide in returns. , POOH 4 3/4" bit x RIH 3 1/4" bit x 122 jts of 2 7/8" tbg x tagged TD @ 5200'. Circ well w/ 120 bbls BW w/ 55 gals surfactant. POOH 122 its. RIH 4" rbp @ 4010' x 5 \%" pkr @ 3914'. Tested liner top to 600 psi which held ok. Tested csg up to surface to 600 psi which held ok. Released pkr x rbp. RIH w/ 115 its 2 7/8" tbg @ 3700'x ESP @ 3747'. 04/25/2018 05/01/2018 (Well RTP) Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledge and belief. April Hood Regulatory Specialist TITLE 06/11/2018 **SIGNATURE** DATE

E-mail address: April_Hood@Oxy.com

for Kecoratile

713-366-5771

PHONE:

DATE 7-2.4-18

Type or print name April Hood

Conditions of Approval (if any):

For State Use Only

APPROVED BY: /