811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec NMOBBS OCD District IV	State of New Mexico rgy, Minerals and Natural Resources Department Oil Conservation Division 1220 South St. Francis Dr.	Submit Original to Appropriate District Office
1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa Fe, NM 87505	
Date: 6/6/2018 <b>RECEIVED</b>	GAS CAPTURE PLAN	
☑ Original ☐ Amended - Reason for Amendment:	Operator & OGRID No.: Devon Energy Prod.	Co., LP 6137

This Gas Capture Plan outlines actions to be taken by the Operator to reduce well/production facility flaring/venting for new completion (new drill, recomplete to new zone, re-frac) activity.

Note: Form C-129 must be submitted and approved prior to exceeding 60 days allowed by Rule (Subsection A of 19.15.18.12 NMAC).

## Well(s)/Production Facility - Name of facility

The well(s) that will be located at the production facility are shown in the table below.

Well Name	API	Well Location (ULSTR)	Footages	Expected MCF/D	Flared or Vented	Comments
Fluffy Cat 16-21 State Fed Com 212H 30-0	1549069	Unit K, Sec 16, T23S, R32E	2620 FNL 619 FWL			Big Cat 16 CTB 9
	7					

# **Gathering System and Pipeline Notification**

Well(s) will be connected to a production facility after flowback operations are complete, if DCP system is in place. The gas produced from production facility is dedicated to DCP and will be connected to DCP low/high pressure gathering system located in Lea County, New Mexico. It will require 458' of pipeline to connect the facility to low/high pressure gathering system. Devon provides (periodically) to DCP a drilling, completion and estimated first production date for wells that are scheduled to be drilled in the foreseeable future. In addition, Devon and DCP have periodic conference calls to discuss changes to drilling and completion schedules. Gas from these wells will be processed at DCP Processing Plant located in Sec.19, Twn.19S, Rng.32E, Lea County, New Mexico. The actual flow of the gas will be based on compression operating parameters and gathering system pressures.

# Flowback Strategy

After the fracture treatment/completion operations, well(s) will be produced to temporary production tanks and gas will be flared or vented. During flowback, the fluids and sand content will be monitored. When the produced fluids contain minimal sand, the wells will be turned to production facilities. Gas sales should start as soon as the wells start flowing through the production facilities, unless there are operational issues on DCP system at that time. Based on current information, it is Devon's belief the system can take this gas upon completion of the well(s).

Safety requirements during cleanout operations from the use of underbalanced air cleanout systems may necessitate that sand and non-pipeline quality gas be vented and/or flared rather than sold on a temporary basis.

## **Alternatives to Reduce Flaring**

Below are alternatives considered from a conceptual standpoint to reduce the amount of gas flared.

- Power Generation On lease
  - Only a portion of gas is consumed operating the generator, remainder of gas will be flared
- Compressed Natural Gas On lease
  - o Gas flared would be minimal, but might be uneconomical to operate when gas volume declines
- NGL Removal On lease
  - o Plants are expensive, residue gas is still flared, and uneconomical to operate when gas volume declines

#### 6. Logging and Testing Procedures

Logging, Coring and Testing.				
X	Will run GR/CNL from TD to surface (horizontal well – vertical portion of hole).			
	Stated logs run will be in the Completion Report and submitted to the BLM.			
	No Logs are planned based on well control or offset log information.			
	Drill stem test? If yes, explain			
	Coring? If yes, explain			

Addi	tional logs planned	Interval	
	Resistivity	Int. shoe to KOP	
	Density	Int. shoe to KOP	
X	CBL	Production casing	
X	Mud log	KOP to TD	
	PEX		

#### 7. Drilling Conditions

Condition	Specify what type and where?
BH Pressure at deepest TVD	5,186 psi
Abnormal Temperature	No

Mitigation measure for abnormal conditions. Describe. Lost circulation material/sweeps/mud scavengers.

Hydrogen Sulfide (H2S) monitors will be installed prior to drilling out the surface shoe. If H2S is detected in concentrations greater than 100 ppm, the operator will comply with the provisions of Onshore Oil and Gas Order #6. If Hydrogen Sulfide is encountered, measured values and formations will be provided to the BLM.

 N
 H2S is present

 Y
 H2S Plan attached

# 8. Other facets of operation

Is this a walking operation? No. Will be pre-setting casing? No.

Attachments

- \_x\_ Directional Plan
- \_\_\_\_ Other, describe

6

Drilling Plan