Submit 1 Copy To Appropriate District Office State of New Mexico	Form C-103
District I – (575) 393-6161 Energy, Minerals and Natural Resource	ves Revised July 18, 2013 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210 OIL CONSTRUATION DIVISIO	N 30-025-31247
District III - (505) 334-6178 1220 South St Ft 27 1 1 1 1 2 1 1 2 1 1 2 1 1 2 1 1 2 1 1 2 1 1 2 1 1 2 1 1 2 1	5. Indicate Type of Lease STATE X FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV - (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505 Santa Fe, NM	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS OF WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO	7. Lease Name or Unit Agreement Name ARROWHEAD GRAYBURG UNIT
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	0. 337 1137 1
1. Type of Well: Oil Well Gas Well Other 2. Name of Operator	8. Well Number 131 9. OGRID Number
XTO ENERGY INC.	5380
3. Address of Operator 6401 HOLIDAY HILL ROAD MIDLAND, TX 79707	10. Pool name or Wildcat ARROWHEAD; GRAYBURG
4. Well Location Linit Letter J . 1980 feet from the SOUTH line and 2080 feet from the EAST line	
Unit Letter J : 1980 feet from the SOUTH line and 2080 feet from the EAST line Section 36 Township 21S Range 36E NMPM County LEA	
11. Elevation (Show whether DR, RKB, RT, C	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUE!	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPL INT TO PA	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPINITO PARTING PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB P&A NR	
DOWNHOLE COMMINGLE	P&A R
CLOSED-LOOP SYSTEM OTHER: OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of	
proposed completion or recompletion.	
VEO CURNITO TUIC CUNDRY AC A RECUEST TO DA REFERENCED MELL.	
XTO SUBMITS THIS SUNDRY AS A REQUEST TO PA REFERENCED WELL: 1.TAG CURRENT CIBP TO CONFIRM DEPTH, APPROX 3 550 . 3640	
36AO 2,2492-3182 W/ 485X CMT. WOC. 50 5X 3,2819-2569 W/ 40SX CMT. WOC.	
3.2819-2569 W/ 40SX CMT. WOC. 4. 4230- 980 W/ 60 SX CMT. WOC. F- PERFC 1210'. SQZ-W/60 SX WOC. TA6 5.350-0 PERF/ SQZ/ CIRC/ VERIFY 120 SX CMT. WOC.	
6. ND BOP AND CUT OFF WELLHEAD 5' BELOW SURFACE. VERIFY CMT. SET P&A MARKER.	
T.O.C. @ 1263' by temp survey	
Spud Date: NOTIFY OCD 24 HOURS PRIOR TO	
BEGINNING PLUGGING OPERATIONS	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNATURE TITLE REGULATORY AN	DATE 08/13/2018
PATRICIA DONA	ALD@XTOENERGY.COM 432-571-8220
Type or print name PATRICIA DONALD E-mail address: PHONE: PHONE:	
N. I. Will Dec nales lang	
APPROVED BY: Washes TITLE 1.E.S. DATE ODES 2018 Conditions of Approval (if any):	

C103 INTENT TO P&A EXPIRES 1 YEAR FROM DATE OF APPROVAL



Arrowhead Grayburg Unit # 131

