Submit 1 Copy To Appropriate District	State of New Mexico		•	Form C-103	
Office District I – (575) 393-6161	Energy, Minerals and Natural Resources			Revised July 18, 2013	
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.		
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION		30-025-43627		
<u>District III</u> - (505) 334-6178	1220 South St. Francis Dr.		5. Indicate Type of STATE	FEE	
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505		6. State Oil & Gas I		
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	S		0. State Off & Gas i	Scasc 140.	
87505					
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or U	nit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			Doggar State Com		
PROPOSALS.)	POSALS.)			Dagger State Com	
1. Type of Well: Oil Well 🛛	Gas Well Other	C	Dagger State Com 8. Well Number: 505H 9. OGRID Number		
2. Name of Operator		HOBBO	9. OGRID Number		
	e Energy Partners Hat Mesa		n 3/	241 /	
3. Address of Operator	shaiman D.J. Hayatan, TV, 77077	SEH IN CO.	10. Pool name or W	iidcat	
11490 Westheimer Rd, Houston, TX 77077					
4. Well Location		RECEIVE			
Unit LetterH	:1610feet from theFNI	line and	_545feet from	theFELline	
Section 30	Township 21S	Range 33E	NMPM	County Lea	
	11. Elevation (Show whether Dh	R, RKB, RT, GR, etc.)			
	3781 GL				
12. Check	Appropriate Box to Indicate N	Jature of Notice.	Report or Other Da	ata	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
PERFORM REMEDIAL WORK	☐ PLUG AND ABANDON ☐ REMEDIAL WORK		<	TERING CASING	
TEMPORARILY ABANDON	CHANGE PLANS ☐ COMMENCE DRILLING OPNS.☐ P AND A			AND A	
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT	JOB 🔲		
DOWNHOLE COMMINGLE	•		.		
CLOSED-LOOP SYSTEM				•	
OTHER:		OTHER:		\boxtimes	
	oleted operations. (Clearly state all	pertinent details, and	give pertinent dates,	including estimated date	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of					
proposed completion or recompletion.					
7/15/18: Pressure test casing to 9800 psi for 30 minutes. 7/19/18 – 7/26/18: Perforate from 11,492' – 18,961' (2220). Acidize with					
74,000 gallons 15% HCl. Frac with 18,690,760 lbs sand and 16,465,639 gal fluid. 7/29/18 – 7/31/18: Drill all plugs and clean out to					
PBTD of 18,972'. 8/14/18 – 8/17/18: Set packer at 10,300'. Run tubing and gas lift valves.					
\cdot					
			·	•	
g . I.D	n's natson n				
Spud Date:	Rig Release Da	ate:			
			· · · · · · · · · · · · · · · · · · ·	,	
hereby certify that the information	above is true and complete to the b	est of my knowledge	and belief.		
	1	·			
SIGNATURE: Drilling Manager DATE:					
PRINT NAME: Braden Harris E-mail address: bharris@advanceenergypartners.com PHONE: (406) 600-3310					
PRINT NAME: Braden Harris	E-mail address: bharris@a	advanceenergypartne	rs.com PHON	IE: (406) 600-3310	
Eng State Has Onlin					
For State Use Only					
APPROVED BY Wen Thank TITLE Dtaff May DATE 9-17-18					
Conditions of Approval (if any):					
CONGRESS OF APPROVALIA (A BRIA).	•	•			

Provide Tubing detail: size, wt., depth