Submit 1 Copy To Appropriate District State of New Mexico	Form C-103			
Company Minangle and Matagol Decompose	Revised August 1, 2011 WELL API NO.			
District II - (575) 748 128	30-025-20866			
District II - (575) 393-5161 1625 N. French Dr., Hobb 188240 District II - (575) 748 058 811 S. First St., Artesia, NM 88240 District III - (505) 334-6178 C. 1000 Rio Brazos Rd., Aztec, NM 87410 Screen For NIM 87505	5. Indicate Type of Lease			
1000 Rio Brazos Rd., Aztec, NM 87410.	STATE X FEE			
District II - (575) 393-6161 1625 N. French Dr., Hobber 188240 District III - (575) 748 (38) 811 S. First St., Artesa, NM 88210 District III - (505) 334-6178 CF 1000 Rio Brazos Rd., Aztec, NM 87410 District IV - (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No.			
87505				
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name VACUUM GLORIETA EAST UNIT TRACT 35			
1. Type of Well: Oil Well \(\big \) Gas Well \(\big \) Other	8. Well Number 001			
2. Name of Operator ConocoPhillips Company	9. OGRID Number			
3. Address of Operator P. O. Box 51810	217817 10. Pool name or Wildcat			
Midland, TX 79710	VACUUM; GLORIETA			
4. Well Location				
Unit Letter D: 330 feet from the NORTH line and 330				
Section 34 Township 17S Range 35E	NMPM County LEA			
11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
12. Check Appropriate Box to Indicate Nature of Notice,	Report or Other Data			
NOTICE OF INTENTION TO:	SEQUENT REPORT OF:			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR				
TEMPORARILY ABANDON	LLING OPNS. P AND A			
PULL OR ALTER CASING	ГЈОВ 🗆			
DOWNHOLE COMMINGLE				
OTHER: WATER SHUT OFF 🔀 OTHER:				
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of				
proposed completion or recompletion.	ipietions. Attach wendore diagram of			
proposes compressors				
CONOCOPHILLIPS COMPANY WOULD LIKE TO PERFORM WATER SHUT OFF	PER ATTACHED PROCEDURES.			
ATTACHED IS A CURRENT/PROPOSED WELLBORE SCHEMATIC				
Spud Date: Rig Release Date:				
•				
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNATURE DATE 09/17/2018				
Type or print name Phonds Posses F mail address: researce@consecutilling.com BUONE: (422)699.0174				
Type or print name Rhonda Rogers E-mail address: rogerrs@conocophillips.com PHONE: (432)688-9174 For State Use Only				
Washington April alzahano				
APPROVED BY: TITLE TITLE	DATE 1/20/2018			
Conditions of Approval (if any)				

VGEU 35-01 WATER SHUT OFF API# 30-025-20866

Important Contacts			
Position	Name	Office	Cell
Prod. Engineer	Aaron Montee	432-688-9056	432-202-5380
Project Supervisor	Manuel Corral	575-391-3159	575-390-6347
Prod. Foreman	Chris Wood	575-391-3106	806-898-2722
Prod. Specialist	Malcolm Cox	575-391-3153	575-390-2127
Ops. Supervisor	Sean Robinson	575-391-3147	575-390-8873
Nalco Champion	Leo Sandmann		575-513-9012

Project Scope

Justification and Background:

This project includes setting a CIBP that isolates more than half the perforations to shut off water and swapping a BPU to match the expected production. Currently, this well makes all water, carries a high fluid level, and is not economic to produce. However, the offset producer (VGEU 22-03) makes 27 oil and 273 water. Therefore, a CIBP will be set to mirror the offset producers open perfs. The cross sections show the difference between these 2 wells are the OWC at the base of the perforated interval in the VGEU 22-03 while it cuts right through the perforated interval in the VGEU 35-01.

Perforations				
Type	Formation	Тор	Bottom	
Perforations	Glorieta	6,085'	6,115'	
PBTD	6,264'			
TD	6,300'			

Well Service Procedure:

- 1) MIRU pulling unit. Kill well.
- 2) TOOH w/ rods & pump. LD rods & pump.
 - a. Will not rerun rods. Will pick up FG rods & D90 rods.
 - b. Note any heavy wear areas and depth. Notify PE on findings.
 - c. If heavy paraffin is present, take sample, and notify Nalco/Champion
 - d. Notify TRC to pick up rods to inspect and place in inventory.
 - e. Send pump to Don-Nan for inspected, repair, and place in inventory. Will not rerun this pump.
- 3) NDWH, NUBOP. Test BOP.
- 4) RU Tbg scanners. TOOH w/ Tbg and stand back in Derrick. RD Tbg scanners.
 - a. Stand back yellow/blue band Jts.
 - b. Place replacement Jts. on bottom.
- 5) RU hydro-testers. PU & TIH w/ bit and scraper sized for 9.5# casing below bottom perf @ 6,115' while hydro-testing to 5000 psi below slips. RD hydro-testers.
 - a. No need to tag PBTD. Will set plug in perfs.
- 6) TOOH & LD bit and scraper.
- 7) RU wireline services. PU & RIH w/ CIBP & set @ 6,090'. RD wireline

VGEU 35-01 WATER SHUT OFF API# 30-025-20866

- a. Correlate depth from Halliburton Thermal Multigate Decay Log dated 1/25/95.
- 8) PU & RIH w/ SN, TAC, and production Tbg.
 - a. Land SN @ ~6070'.
- 9) NDBOP. NUWH.
- 10) PU & RIH w/ new 1.5" pump and rods. Card every 10th triple on steel rods and every 10th double on the Fiberglass rods. Have Fiberglass tech inspect Fiberglass rods while picking up and going in hole.
 - a. PU 20-150 RHBC 28-5 pump from Don-Nan
 - b. 21 K shear tool
 - c. PU 475' of Flexbar C sinker bars
 - d. PU 83 used 7/8" D90 inspected rods from TRC inventory
 - e. PU 92 new .98" Fiberrod from John Crane
- 11) Space out pump and hang well on.
- 12) Contact Nalco Champion to pump CI within 24 hours of rigging down.
- 13) Clean location and release all ancillary rental equipment.
- 14) RDMO PU.
- 15) Notify MSO to sign off on well and return well to production.

स्वामिते हैं जिल्ला

CURRENT SCHEMATIC **VACUUM GLORIETA EAST UNIT 035-01**

