




In Reply Refer to  
3162.4 (P0220)

United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office  
620 E. Greene  
Carlsbad, New Mexico 88220-6292  
www.nm.blm.gov



Marthon Oil Company  
5555 San Felipe  
Houston, TX 77056

September 13, 2018

Carlsbad Field Office  
OCD Hobbs

Gentlemen:

Your Application for Permit to Drill (APD) for the below referenced well has expired because drilling has not commenced per Onshore Order #1:

LEASE	WELL NAME & NUMBER	API#	ORIGINAL APD EXPIRATION	EXTENSION EXPIRATION
NM84728	URRACA FEDERAL COM - 23H	3002542109	09/08/2016	09/08/2018
NM84728	URRACA FEDERAL COM - 25H	3002542048	08/13/2016	08/13/2018

If a well has not been spud, but site construction activities have occurred please contact Jim Amos at (575) 234-5909 for surface reclamation instructions. If drilling operations have commenced on a well send all necessary reports (spud, casing/cementing, etc., 1 original and 3 copies) to the BLM so we may correct our records.

If you wish to drill this well at a later date, please submit a complete application (In AFMSS II data base) to this office. Since the original APD have expired, the resubmitted APD will be subject to all processing requirements including the \$9,790 application fee and the 30-day posting period. Please note on the resubmitted APD that they were previously approved and we will review the expired file for information which will help expedite the processing.

If you have any questions, please contact Duncan Whitlock at (575) 234-5926.

Sincerely,

Cody Layton  
Assistant Field Manager, Lands and Minerals