United States Department of the Interior



BUREAU OF LAND MANAGEMENT

HOBBS OCD Carlsbad Field Office 620 E. Greene SEP 2 6 2018 arlsbad, New Mexico 88220-6292 www.nm.blm.gov

RECEIVED



In Reply Refer to 3162.4 (P0220)

COG Operating LLC 600 W. Illinois Ave. Midland, TX 79701

Gentlemen:

Your Application for Permit to Drill (APD) for the below referenced well has expired because drilling has not commenced per Onshore Order #1:

arlsbau rieid Uttice OCD Hobbs

WELL NAME & NUMBER	API WELL NUMBER	ORIGINAL APD EXPIRATION	EXTENSION EXPIRATION
Parliament 1 Federal Com 13H	300154181700X1	11/18/2015	11/18/2017
Pardue 29 Federal Com 7H	300154242300X1	06/04/2016	06/04/2018
Fat Tire 12 Federal LBB 21H	300154178900X1	11/05/2013	11/05/2017
Fat Tire 12 Federal 11H	300154368000X1	03/17/2018	N/A

If a well has not been spud, but site construction activities have occurred please contact Jim Amos at (575) 234-5909 for surface reclamation instructions. If drilling operations have commenced on a well send all necessary reports (spud, casing/cementing, etc., 1 original and 3 copies) to the BLM so we may correct our records.

If you wish to drill this well at a later date, please submit a complete application (In AFMSS II data base) to this office. Since the original APD have expired, the resubmitted APD will be subject to all processing requirements including the \$9,790 application fee and the 30-day posting period. Please note on the resubmitted APD that they were previously approved and we will review the expired file for information which will help expedite the processing.

If you have any questions, please contact Duncan Whitlock at (575) 234-5926.

. 1.1

i de la companya de l

Sincerely, W hitlork of

Cody Eayton Assistant Field Manager, Lands and Minerals

September 20,2018

Page 1 of 1