Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED OMB NO. 1004-0137

Expires: January 31, 2018

5. Lease Serial No. NMNM14331 SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this	s form for proposals to	drill 9 18 6 hough His	Id Office dian, Allottee		
abandoned wel	i. Use form 3160-3 (API	D) for such proposals.	Allottee	or Tribe Name	
SUBMIT IN 1	RIPLICATE - Other inst	ructions on page 2		eement, Name and/or No.	
Type of Well ☐ Gas Well ☐ Oth	er	НОВ	BS OCD Vell Name and No	SCN FED COM 2H	
2. Name of Operator Contact: JACKIE LATHAN MEWBOURNE OIL COMPANY E-Mail: jlathan@mewbourne.com SEP 2 6 2018 9. API Well No. 30-025-45156-00-X1					
3a. Address P O BOX 5270 HOBBS, NM 88241		3b. Phone No. (include area code) Ph: 575-393-5905	10. Field and Pool or RED TANK-BC	Exploratory Area NE SPRING	
4. Location of Well (Footage, Sec., T.	11. County or Parish,	State			
Sec 17 T21S R32E NESW 16- 32.475948 N Lat, 103.698891			LEA COUNTY,	NM	
12. CHECK THE AP	PROPRIATE BOX(ES)	TO INDICATE NATURE O	F NOTICE, REPORT, OR OT	HER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	■ Water Shut-Off	
	☐ Alter Casing	☐ Hydraulic Fracturing	□ Reclamation	■ Well Integrity	
☐ Subsequent Report	□ Casing Repair	■ New Construction	☐ Recomplete	Other	
☐ Final Abandonment Notice	□ Change Plans	Plug and Abandon	Temporarily Abandon Change to Original		
	☐ Convert to Injection	□ Plug Back	■ Water Disposal		
Attach the Bond under which the wor following completion of the involved	illy or recomplete horizontally, k will be performed or provide operations. If the operation re andonment Notices must be fil nal inspection. uests approval to batch di ment.	give subsurface locations and measu the Bond No. on file with BLM/BIA sults in a multiple completion or reco ed only after all requirements, includ	red and true vertical depths of all pertical Required subsequent reports must bompletion in a new interval, a Form 31 ling reclamation, have been completed	nent markers and zones. e filed within 30 days 60-4 must be filed once	


SEE ATTACHED FOR CONDITIONS OF APPROVAL

14. I hereby certify that t	the foregoing is true and correct. Electronic Submission #436001 verifie For MEWBOURNE OIL CO Committed to AFMSS for processing by PR	MPÁNY.	sent to the Hobbs
Name (Printed/Typed)	ANDY TAYLOR	Title	ENGINEER
Signature	(Electronic Submission)	Date	09/19/2018
	THIS SPACE FOR FEDERA	AL OR	STATE OFFICE USE
Conditions of approval, if a certify that the applicant he	any, are attached. Approval of this notice does not warrant or olds legal or equitable title to those rights in the subject lease olicant to conduct operations thereon.	Title	Petroleum Engineer _{Date} 9/ม อเช Carlsbad Field Office

Mewbourne Oil Company, Caper 20/29 B3CN Fed Com #2H Sec 17, T21S, R32E

SL: 1645' FSL & 2020' FWL BHL: 100' FSL & 1980' FWL

Mewbourne Oil Co. requests approval to batch drill the Caper 20/29 B3CN Fed Com #2H and Caper 20/29 B2CN Fed Com #1H in the sequence depicted below.



- Surface, Production & Intermediate Hole:
 - 1. Drill 17-1/2" surface hole with fresh water to planned casing set depth.
 - 2. Run casing as stated by approved APD, land out wellhead, and cement.
 - 3. N/U and test 13-5/8" BOPE to 250 psi / 5,000 psi.
 - 4. Test casing to required pressure. Drill out shoe and 10' of new formation. Perform FIT.
 - 5. Drill 12-1/4" hole to planned casing set depth.
 - 6. Run casing as stated by approved APD, land out hanger and cement.
 - 7. Test casing to required pressure. Drill out shoe and 10' of new formation. Perform FIT.
 - 8. Drill 8-3/4" vertical section and curve as stated by approved APD.
 - 9. Run casing as stated by approved APD, land out hanger and cement.
 - 10. Secure with wellhead cover, walk rig to Caper 20/29 B2CN Fed Com #1H and repeat Steps 1-9.

Lateral:

1. Test casing to required pressure. Drill out shoe and 10' of new formation. Perform FIT.

Mewbourne Oil Company, Caper 20/29 B3CN Fed Com #2H Sec 17, T21S, R32E

SL: 1645' FSL & 2020' FWL BHL: 100' FSL & 1980' FWL

- 2. Drill 6-1/8" lateral as stated by approved APD.
- 3. Run liner as stated by approved APD, cement, set liner hanger and secure with wellhead cover.
- 4. Walk rig to Caper 20/29 B3CN Fed Com #2H.
- 5. N/U and test 13-5/8" BOPE to 250 psi / 5000 psi.
- 6. Repeat Steps 1-3.

PECOS DISTRICT CONDITIONS OF APPROVAL

OPERATOR'S NAME: | Mewbourne Oil Company

LEASE NO.: | NMNM-14331

WELL NAME & NO.: | Caper 20/29 B3CN Fed Com 2H

SURFACE HOLE FOOTAGE: | 0360' FSL & 1950' FWL

BOTTOM HOLE FOOTAGE | 0330' FSL & 1980' FWL Sec. 17, T. 21 S., R 32 E.

LOCATION: | Section 12, T. 24 S., R 26 E., NMPM

COUNTY: Lea County, New Mexico

A. CASING

All previous COAs still apply except the following:

In the event the operator has proposed to drill multiple wells utilizing a skid/walking rig. Operator shall secure the wellbore on the current well, after installing and testing the wellhead, by installing a blind flange of like pressure rating to the wellhead and a pressure gauge that can be monitored while drilling is performed on the other well(s).

MHH 09212018