Submit 1 Copy To Appropriate District	State of New Me	xico		Form C-103
Office <u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Resources		Revised July 18, 2013	
1625 N. French Dr., Hobbs, NM 88240	8,,		WELL, API NO.	_
District II - (575) 748-1283	OIL CONSERVATION DIVISION		30-02504074	
811 S. First St., Artesia, NM 88210 District III – (505) 334-6178	1220 South St. Francis Dr.		5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410			STATE FEE X	
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Sama PC, 14101 67	303	6. State Oil & Gas Lease No	Э.
87505				
	CES AND REPORTS ON WELLS		7. Lease Name or Unit Agre	eement Name
(DO NOT USE THIS FORM FOR PROPOS DIFFERENT RESERVOIR. USE "APPLIC			Northwest Eumont Unit	
PROPOSALS.)	·		8. Well Number 139	
	s Well X Other Water Injection w	ell		
2. Name of Operator			9. OGRID Number 19111	
Rhombus Operating Co., Ltd.	nrt A:	3 2018	10 D 1 W/11	
3. Address of Operator P.O.Box 627, Littleton, CO 80160-0	00 .	2010	10. Pool name or Wildcat Eumont; Yates-7 Rvrs-Queer	, (Oil
· · · · · · · · · · · · · · · · · · ·		N/En	Eunioni, rates-7 Rvis-Queen	1 (011
4. Well Location	RECE			
	1980feet from the _North li		feet from the _West	_line
Section 26	Township 19S	Range 36E		ty LEA
	11. Elevation (Show whether DR,	RKB, RT, GR, etc	.)	
■ 人工公司等級公司等數公司等數公司等級公司等	GL 3704'			
12. Check A	ppropriate Box to Indicate N	ature of Notice,	Report or Other Data	
NOTICE OF IN	FENTER TO: 197	SI IE	SEQUENT REPORT C	\ E.
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WOR		G CASING □
TEMPORARILY ABANDON	CHANGE PLANS		ILLING OPNS. P AND A	
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN	<u>=</u>	
DOWNHOLE COMMINGLE	MOETIFEE COMPL	CASING/CEIVIEN	11 30B	
CLOSED-LOOP SYSTEM				
OTHER:		OTHER:		
	eted operations. (Clearly state all p	ertinent details, ar	nd give pertinent dates, includin	g estimated date
	rk). SEE RULE 19.15.7.14 NMAC			
proposed completion or reco			, -	
Surface casing: 10 3/4", 32.75# @		7 5/8", 26.4#, 4	^{25 sx}	ched
Production casing: 5½", 17# @ 37			Conditions	f Ammrayal
OH 3790-3950'	CIBP @ 3,690' w/ 25 sx cmt on	top	Conditions of	r Approvai
 MIRU. ND WH. NU BOR 	P.		1 1	
2. RIH w/ 2-3/8" workstring	& tag PBTD. Circ hole w/ brin	e and salt gel. 🗜	ressure test csg.	
3. POOH w/ tbg to 2610' (ba	ase of salt) & spot 25 sx CL C c	mt.		
	spot 25 sx CL C cmt. WOC \$			
	Baker AD-1 tension pkr and se	t at 60'. RIH w/	perf gun and tag cement plug	g. (TOC has to
be no deeper than 128	19'). 267'		Z62'	/ P / P
6. Perf sqz holes at 190. EII	R & circ out 7-5/8". ND BOP &	NU WH. Circ 4	Osx cmt from LOO to surfac	e. (10³/4 Shoc
7. Cut off wellhead & install	l dry hole marker. Cut off ancho	rs & level location	on.	
verify .	CMT TO SURFACE			
Spud Date:	Rig Release Da	te:	•	
<u> </u>				
I hereby certify that the information a	bove is true and complete to the be	st of my knowled	ge and belief.	
SIGNATURE	TITLE_Pres. Of General Pa	rtnerI	DATE	
m	11 12 11 11	9 "	DITONIE (422 C02 0052	
Type or print name Gregory D. Cielir	iski E-mail address: rhombusen	ergy@gmail.com_	_ PHONE: (432-683-8873	
For State Use Only	\cap . $=$, ,
APPROVED BY: Wall	Kitchen TITLE P.E.	S.	DATE IO	03/2018


Conditions of Approval (if any):

W

GENERAL CONDITIONS OF APPROVAL:

- 1) Insure all bradenheads have been exposed, identified, and valves are operational prior to rigging up on well.
- 2) Contact the appropriate NMOCD District Office no later than 24 hours prior to moving in and rigging up.
- 3) A copy of the approved C103 intent to P&A should be distributed to the onsite company and plugging representatives. Approved procedures are good for a period of one year from approved date, unless otherwise specified on the C103 intent. Approvals past this date will require the submission and approval of a new C103 intent.
- 4) A company representative is required to be present to witness all operations including setting CIBP's, circulation of mud laden fluids, perforating, squeezing or spotting cement plugs, tags, or any other operations approved on the C103 intent to P&A. Company representative should contact the NMOCD and report all operations.
- 5) Any changes that may be required during plugging operations should be approved by the NMOCD before proceeding.
- 6) A closed loop system is to be used for all plugging operations. Contents of the steel pits to be hauled to a NMOCD permitted disposal facility.
- 7) Mud laden fluids must be placed between all cement plugs mixed at 25 sacks of salt gel per 100 barrels of brine.
- 8) All cement plugs will be 100' or 25 sacks cement, whichever is greater. Class 'C' cement will be used above 7500' and Class 'H' below 7500'.

Current Conditions



Proposed Conditions

		100' 212'	Sqz holes at 100'. Circ cmt from 100' to surface 10 3/4" 32.75# Surface Csg, 225 sx
		1,339' 1,389'	7 5/8" 26.4# Intermediate Csg, 425 sx 25 sx cmt plug spotted at 1,389'
	27	2,610'	25 sx cmt plug spotted at 2,610
		3,690'	CIBP W/ 25 sx cmt on top
	() () ()	3,790'	5 1/2", 17# Production Csg, 425 sx
1		ט טבטי	Open hole completion 3,790' - 3,950'
·;	1 1 1	3,950' 4,024'	PBTD TD