United States Department of the Interior 30-025-31177



BUREAU OF LAND MANAGEMENT





In Reply Refer to 3162.4 (P0220)

OCT 1 0 2018

RECEIVED

Cimarex Energy Co. 202 S Cheyenne Ave, Suite 1000 Tulsa, OK 74103

## Carlsbad Field Uffice OCD Hobbs

October 3, 2018

Gentlemen:

Your Application for Permit to Drill (APD) for the below referenced well has expired because drilling has not commenced per Onshore Order #1:

WELL NAME & NUMBER	API WELL NUMBER	ORIGINAL APD EXPIRATION	EXTENSION EXPIRATION
CUERVO FEDERAL – 24H	30-025-42167	09-26-2016	09-26-2018
PADUCA AIU FEDERAL SWD – 1H	30-025-31177	09-29-2016	09-29-2018
WEST GRAMA RIDGE 6 FEDERAL – 1H	30-025-42150	09-25-2016	09-25-2018
WEST GRAMA RIDGE 6 FEDERAL – 2H	30-025-42151	09-25-2016	09-25-2018

If a well has not been spud, but site construction activities have occurred please contact Jim Amos at (575) 234-5909 for surface reclamation instructions. If drilling operations have commenced on a well send all necessary reports (spud, casing/cementing, etc., 1 original and 3 copies) to the BLM so we may correct our records.

If you wish to drill this well at a later date, please submit a complete application (In AFMSS II data base) to this office. Since the original APD have expired, the resubmitted APD will be subject to all processing requirements including the \$10,050 application fee and the 30-day posting period. Please note on the resubmitted APD that they were previously approved and we will review the expired file for information which will help expedite the processing.

If you have any questions, please contact Duncan Whitlock at (575) 234-5926.

Sincerely,

Dro hitlalg

For Cody Layton Assistant Field Manager, Lands and Minerals