Submit 1 Copy To Appropriate District Office	State of New Me				Form C-103
District 1 - (575) 393-6161	Printing 1 (575) 202 4141 Energy, Minerals and Natural Resources		Revised August 1, 2011 WELL API NO.		
1625 N. French Dr., Hobbs, NM 88240BBS OCD District II - (575) 748-1283			30-025-44826		
OIL CONSERVATION DIVISION			5. Indicate Type	of Lease	
District III ~ (505) 334-6178 District III ~ (505) 334-6178 OCT 1 5 2018 220 South St. Francis Dr. Santa Fe. NM 87505			STATE		E 🔲
<u>District IV</u> = (303) 476-3460			6. State Oil & Ga	s Lease No).
1220 S. St. Francis Dr., Santa Fe. NRECE 87505	EIVED				
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or	Unit Agre	ement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			South Hobbs (G/SA) Unit		
1. Type of Well: Oil Well Ga	s Well 🔲 Other: Injector 📙	OBBS OCD			
2. Name of Operator Occidental Permian Ltd. OCT 1 5 2018			9. OGRID Number: 157984		
3. Address of Operator			10. Pool name or Wildcat Hobbs (G/SA)		
HCR I Box 90 Denver City, TX 7932	3	RECEIVED			
4. Well Location					
Unit Letter M: 635 feet from the South line and 794 feet from the West line					
Section 24	Township 18S	Range 37E	NMPM	Lea	County
	1. Elevation (Show whether DR	R. RKB, RT, GR, etc.,)	PERSONAL PROPERTY OF THE PERSON NAMED OF THE P	
3	673' (GL)		Mary Summer parties	Takan Kananan	أخديا لأوشيات حديده
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR					G CASING 🔲
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI				P AND A	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN					_
DOWNHOLE COMMINGLE	_		-		
	_				_
OTHER: Initial Completion	dti (Classic state all	OTHER:	J .:	:1	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of					
proposed completion or recompletion.					
proposed compression or recom-	r				
1. MIRU PU.		During this	procedure we p	ian to us	ie
the elecad			loop system wit	h a steel	
3. Run CBL the closed			aul contents to 1	he requi	red
4. Selectively perforate San Andres ROZ and TZ targets between tank and had 100' TVD and Base of Unit @ 4500' TVD.			aul contents to t	15 17	• — -
4100' TVD and Base of Unit @ 4500' TVD. 5. Acid treat new perforations. disposal per ODC Rule 19.15.17					
6. RIH with injection equipment		Condition of Ap	mmovel medic.		
7. RDMO PU.			•		
8. Turn well to injection. 9.		OCD Hobbs of	fice 24 hours		
10.	pri	or of running M	IIT Test & Cha	rt	
	•				
Spud Date:	Rig Release D	Pate:			
		<u> </u>			
I hereby certify that the information about	ave is true and complete to the	sest of my knowledg	e and belief		
Thereby termy that the information abo	The is true and complete to the t	cst of my knowledg	c and belief.		
With Me-	0 (10/7/10		
SIGNATURE / COM	TITLE "ad.	Eny. DATE 1	0///18		
Tune or print come Diel Decor-	17	see siale massam@a	OOM DUONE. T	12,016.74	52
Type or print nameRick Reeves E-mail address <u>rick_reeves@oxy.com</u>					
M / YK					
APPROVED BY: Maley	MOUN_TITLE	MY	DA	TE 14	-10010
Conditions of Approval (if pny):		ł		•	V