

Submit 1 Copy To Appropriate District Office  
District I – (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II – (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III – (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV – (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised August 1, 2011

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO.	
30-015-01949	✓
5. Indicate Type of Lease	
STATE X FEE	✓
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	
Artesia Metex Unit	✓
8. Well Number 024	✓
9. OGRID Number	
269864	✓
10. Pool name or Wildcat	
Artesia QU-GB-SA	✓

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well X Gas Well Other

2. Name of Operator  
State of New Mexico for Canyon E&P Company

3. Address of Operator  
1625 N. French Drive Hobbs, NM 88249

4. Well Location  
Unit Letter O : 660 feet from the South line and 2310 feet from the East line  
Section 19 Township 18S Range 28E NMPM Eddy County ✓

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
DOWNHOLE COMMINGLE <input type="checkbox"/>	P AND A <input checked="" type="checkbox"/>
CASING/CEMENT JOB <input type="checkbox"/>	OTHER: <input type="checkbox"/>

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

HOBBS OCD

SEE ATTACHED

OCT 17 2018

RECEIVED

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

Type or print name \_\_\_\_\_ E-mail address: \_\_\_\_\_ PHONE: \_\_\_\_\_

For State Use Only

APPROVED BY: Mark Whitaker TITLE P.E.S. DATE 10/17/2018

Conditions of Approval (if any):

**Plugging Report**  
**Artesia Metex Unit #24**  
**API 30-015-01949**

10/5/2018      Cleared location and installed 1 anchor. Rigged up. Repaired wellhead and installed BOP. Move in remaining equipment.

10/8/2018      Made another repair on the wellhead. POOH with 44 joints tubing and tallied. Moved in workstring trailer. RIH with 45 jts to 1414' and spotted 50 sx cement with CaCl. WOC 4 hrs and tagged at 1529'. Attempted to catch circulation with 35 bbls brine followed by 45 bbls MLF. No fluid to surface. Stood back 12 stands and laid down remaining pipe. SION

10/9/2018      Dumped 2 yards gravel and tagged at 629'. Dumped ½ yard and tagged at 614'. Dumped 1 yard and tagged 591'. Dumped 2 yards and tagged at 590'. Dumped 2 yards and tagged at 517. Attempted circulation. Good blow to pit until 25 bbls and lost blow. Spotted 50 sx with CaCl at 517'. WOC and tagged at 546'. Lost 29' of fill. Called OCD. Dumped another yard of gravel and tagged at 514'. Spotted 50 sx with CaCl without attempting to circulated. Good blow to the pit while pumping cement. POOH and SION.

~~10/10/2018~~      Tagged at 512'. Dumped 1 yard of gravel. Tagged at 454'. Spotted 50 sx cement with CaCl at 454'. WOC and tagged at 270'. Established circulation and circulated cement to surface inside 8 5/8" casing with 75 sx cement. Rigged down .

10/11/2018      Dig out wellhead and cut off. Filled up casing with 5 sx cement. Installed marker, cut off anchors, cleaned pit and cleared location.