

Submit 1 Copy To Appropriate District Office  
District I – (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II – (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III – (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV – (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised August 1, 2011

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	7. Lease Name or Unit Agreement Name Artesia Metex Unit <input checked="" type="checkbox"/>
2. Name of Operator State of New Mexico for Canyon E&P Company	8. Well Number 014 <input checked="" type="checkbox"/>
3. Address of Operator 1625 N. French Drive Hobbs, NM 88249	9. OGRID Number 269864 <input checked="" type="checkbox"/>
4. Well Location Unit Letter <u>J</u> : <u>1650</u> feet from the <u>South</u> line and <u>1980</u> feet from the <u>East</u> line Section <u>19</u> Township <u>18S</u> Range <u>28E</u> NMPM Eddy County <input checked="" type="checkbox"/>	10. Pool name or Wildcat Artesia QU-GB-SA <input checked="" type="checkbox"/>
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

<b>NOTICE OF INTENTION TO:</b>		<b>SUBSEQUENT REPORT OF:</b>	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	P AND A <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPL <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>	<u>PNR</u>
DOWNHOLE COMMINGLE <input type="checkbox"/>			
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

HOBBS OCD

SEE ATTACHED

OCT 30 2018

RECEIVED

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

Type or print name \_\_\_\_\_ E-mail address: \_\_\_\_\_ PHONE: \_\_\_\_\_

**For State Use Only**

APPROVED BY: Mark Whitaker TITLE P.E.S. DATE 10/30/2018

Conditions of Approval (if any):

**Plugging Report**  
**Artesia Metex Unit #14**  
**API 30-015-01947**

9/27/2018      Cleared location and dug out around the wellhead. Removed 7" X 2" swage and installed 7' X 8 5/8" Larkin wellhead. Rigged up and installed BOP.

9/28/2018      Made gauge ring run to 1870'. Set CIBP at 1850'. RIH with workstring and move in equipment.

10/1/2018      Circulated MLF and tested casing. Casing good to 500#. Spotted 80 sx on top of CIBP. POOH to 501' and spotted 40 sx cement with CaCl. WOC and tagged cement at 316'. POOH and perforated casing at 100'. Pumped 30 bbls brine down the 7" casing to perfs. Did not circulate or blow out of the surface head. Called OCD. Pumped 30 sx cement down 7" casing with CaCl. Shut in and rigged down.

10/3/2018      Filled up both strings of casing with 45 sx w/CaCl. Installed marker, cut off anchors, and cleaned the pit.