Office	State of New Mexico	Form C-103
<u>District I</u> = (575) 393-6161	Energy, Minerals and Natural Resources	Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 88240	COCD	WELL API NO.
811 S. First St., Artesia, NM 88210	OCD OIL CONSERVATION DIVISION 220 South St. Francis Dr.	30-025-43580 5. Indicate Type of Lease
District III - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 874 NOV 1 3 District IV - (505) 476-3460	2018 220 South St. Francis Dr.	STATE STEE
District IV ~ (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505 RECT!	YEN	
	AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DIFFERENT RESERVOIR. USE "APPLICATION."	TO DRILL OR TO DEEPEN OR PLUG BACK TO A	South Hobbs (G/SA) Unit
PROPOSALS.) 1. Type of Well: Oil Well Gas V	Well Other: Injector	8. Well Number: 24-686
2. Name of Operator		9. OGRID Number: 157984
Occidental Permian Ltd.		
3. Address of Operator		10. Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX 79323		
4. Well Location		
Unit LetterL_:2119feet from theSouth line and1308feet from theWestline		
Section 24 Township 18S Range 37E NMPM Lea County		
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3673' (GL)		
And the second second second and the second	5 (OL)	tions of the same
12 Check Appre	onrigte Roy to Indicate Nature of Notice	Penort or Other Data
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTEN	ITION TO: SUB	SEQUENT REPORT OF:
<u> </u>	JG AND ABANDON REMEDIAL WOR	
<u> </u>	ANGE PLANS COMMENCE DR	<u> </u>
PULL OR ALTER CASING MU DOWNHOLE COMMINGLE	LTIPLE COMPL CASING/CEMEN	I JOB
DOMAINHOLE COMMANINGLE		
OTHER:		
	OTHER:	
13. Describe proposed or completed	operations. (Clearly state all pertinent details, an	
 Describe proposed or completed of starting any proposed work). 	operations. (Clearly state all pertinent details, an SEE RULE 19.15.7.14 NMAC. For Multiple Co	
13. Describe proposed or completed	operations. (Clearly state all pertinent details, an SEE RULE 19.15.7.14 NMAC. For Multiple Co	
 Describe proposed or completed of starting any proposed work). 	operations. (Clearly state all pertinent details, an SEE RULE 19.15.7.14 NMAC. For Multiple Co- etion.	mpletions: Attach wellbore diagram of
 Describe proposed or completed of starting any proposed work). proposed completion or recomple MIRU PU POOH with existing injection equipm 	operations. (Clearly state all pertinent details, an SEE RULE 19.15.7.14 NMAC. For Multiple Co etion. During this	mpletions: Attach wellbore diagram of procedure we plan to use
 Describe proposed or completed of starting any proposed work). proposed completion or recompletion. MIRU PU POOH with existing injection equipm Set a CIBP plus 5' cement at approx. 	operations. (Clearly state all pertinent details, an SEE RULE 19.15.7.14 NMAC. For Multiple Coetion. During this 49.15' to isolate Zone I the closed-	procedure we plan to use
 Describe proposed or completed of starting any proposed work). proposed completion or recompleted of starting any proposed work). MIRU PU POOH with existing injection equipm Set a CIBP plus 5' cement at approx. Add perforations selectively in Zone 	operations. (Clearly state all pertinent details, an SEE RULE 19.15.7.14 NMAC. For Multiple Coetion. During this the closed-tank and 3G (4730°-4870°).	procedure we plan to use loop system with a steel aul contents to the required
 Describe proposed or completed of starting any proposed work). proposed completion or recompleted. MIRU PU POOH with existing injection equipm Set a CIBP plus 5' cement at approx. Add perforations selectively in Zone RIH with injection equipment and per 	operations. (Clearly state all pertinent details, an SEE RULE 19.15.7.14 NMAC. For Multiple Coetion. During this the closed-tank and 3G (4730°-4870°).	procedure we plan to use
 Describe proposed or completed of starting any proposed work). proposed completion or recomplete. MIRU PU POOH with existing injection equipm Set a CIBP plus 5' cement at approx. Add perforations selectively in Zone 	operations. (Clearly state all pertinent details, an SEE RULE 19.15.7.14 NMAC. For Multiple Coetion. During this the closed-stand 3G (4730°-4870°). tank and herform MIT.	procedure we plan to use loop system with a steel aul contents to the required er ODC Rule 19.15.17
 Describe proposed or completed of starting any proposed work). proposed completion or recompleted. MIRU PU POOH with existing injection equipm Set a CIBP plus 5' cement at approx. Add perforations selectively in Zone RIH with injection equipment and perforation equipment equipmen	operations. (Clearly state all pertinent details, an SEE RULE 19.15.7.14 NMAC. For Multiple Coetion. During this the closed-stank and h disposal pertinent. Condi	procedure we plan to use loop system with a steel aul contents to the required er ODC Rule 19.15.17
 Describe proposed or completed of starting any proposed work). proposed completion or recompleted. MIRU PU POOH with existing injection equipm Set a CIBP plus 5' cement at approx. Add perforations selectively in Zone RIH with injection equipment and perforation equipment and perforation. Turn well to injection 	operations. (Clearly state all pertinent details, an SEE RULE 19.15.7.14 NMAC. For Multiple Coetion. During this the closed-stank and h disposal pertinent. Condi	procedure we plan to use loop system with a steel aul contents to the required er ODC Rule 19.15.17
 Describe proposed or completed of starting any proposed work). proposed completion or recompleted. MIRU PU POOH with existing injection equipm Set a CIBP plus 5' cement at approx. Add perforations selectively in Zone RIH with injection equipment and perforation equipment equipmen	operations. (Clearly state all pertinent details, an SEE RULE 19.15.7.14 NMAC. For Multiple Coetion. During this the closed-tank and h disposal pertinent details, an operation.	procedure we plan to use loop system with a steel aul contents to the required er ODC Rule 19.15.17 tion of Approval: notify Hobbs office 24 hours
 Describe proposed or completed of starting any proposed work). proposed completion or recompleted. MIRU PU POOH with existing injection equipm Set a CIBP plus 5' cement at approx. Add perforations selectively in Zone RIH with injection equipment and perforation equipment equipmen	operations. (Clearly state all pertinent details, an SEE RULE 19.15.7.14 NMAC. For Multiple Coetion. During this the closed-tank and h disposal pertinent details, an operation.	procedure we plan to use loop system with a steel aul contents to the required er ODC Rule 19.15.17
 Describe proposed or completed of starting any proposed work). proposed completion or recomplete. MIRU PU POOH with existing injection equipm Set a CIBP plus 5' cement at approx. Add perforations selectively in Zone RIH with injection equipment and perforation equipment and perforation equipment and perforation. Turn well to injection 	operations. (Clearly state all pertinent details, an SEE RULE 19.15.7.14 NMAC. For Multiple Coetion. During this the closed-tank and h disposal perform MIT. Condi	procedure we plan to use loop system with a steel aul contents to the required er ODC Rule 19.15.17 tion of Approval: notify Hobbs office 24 hours
13. Describe proposed or completed of starting any proposed work). proposed completion or recompletion or recompletion or recompletion or recompletion. 1. MIRU PU 2. POOH with existing injection equipm 3. Set a CIBP plus 5' cement at approx. 4. Add perforations selectively in Zone 5. RIH with injection equipment and perform the RDMO PU. 7. Turn well to injection 8. 9. Spud Date:	operations. (Clearly state all pertinent details, an SEE RULE 19.15.7.14 NMAC. For Multiple Coetion. During this the closed-tank and h disposal perform MIT. Rig Release Date:	procedure we plan to use loop system with a steel aul contents to the required er ODC Rule 19.15.17 tion of Approval: notify Hobbs office 24 hours running MIT Test & Chart
13. Describe proposed or completed of starting any proposed work). proposed completion or recompletion or recompletion or recompletion or recompletion. 1. MIRU PU 2. POOH with existing injection equipm 3. Set a CIBP plus 5' cement at approx. 4. Add perforations selectively in Zone 5. RIH with injection equipment and perform the RDMO PU. 7. Turn well to injection 8. 9. Spud Date:	operations. (Clearly state all pertinent details, an SEE RULE 19.15.7.14 NMAC. For Multiple Coetion. During this the closed-tank and h disposal perform MIT. Condi	procedure we plan to use loop system with a steel aul contents to the required er ODC Rule 19.15.17 tion of Approval: notify Hobbs office 24 hours running MIT Test & Chart
13. Describe proposed or completed of starting any proposed work). proposed completion or recompletion or recompletion or recompletion or recompletion. 1. MIRU PU 2. POOH with existing injection equipm 3. Set a CIBP plus 5' cement at approx. 4. Add perforations selectively in Zone 5. RIH with injection equipment and perform the RDMO PU. 7. Turn well to injection 8. 9. Spud Date:	operations. (Clearly state all pertinent details, an SEE RULE 19.15.7.14 NMAC. For Multiple Coetion. During this the closed-tank and h disposal perform MIT. Rig Release Date: Rig Release Date:	procedure we plan to use loop system with a steel aul contents to the required er ODC Rule 19.15.17 tion of Approval: notify Hobbs office 24 hours running MIT Test & Chart
13. Describe proposed or completed of starting any proposed work). proposed completion or recompletion or recompletion or recompletion or recompletion. 1. MIRU PU 2. POOH with existing injection equipm 3. Set a CIBP plus 5' cement at approx. 4. Add perforations selectively in Zone 5. RIH with injection equipment and performed performed injection. 7. Turn well to injection. 8. 9. Spud Date:	operations. (Clearly state all pertinent details, an SEE RULE 19.15.7.14 NMAC. For Multiple Coetion. During this the closed-tank and h disposal perform MIT. Rig Release Date: Rig Release Date:	procedure we plan to use loop system with a steel aul contents to the required er ODC Rule 19.15.17 tion of Approval: notify Hobbs office 24 hours running MIT Test & Chart
13. Describe proposed or completed of starting any proposed work). proposed completion or recompletion or recompletion or recompletion or recompletion. 1. MIRU PU 2. POOH with existing injection equipm 3. Set a CIBP plus 5' cement at approx. 4. Add perforations selectively in Zone 5. RIH with injection equipment and perform the RDMO PU. 7. Turn well to injection 8. 9. Spud Date:	operations. (Clearly state all pertinent details, an SEE RULE 19.15.7.14 NMAC. For Multiple Coetion. During this the closed-tank and h disposal perform MIT. Rig Release Date:	procedure we plan to use loop system with a steel aul contents to the required er ODC Rule 19.15.17 tion of Approval: notify Hobbs office 24 hours running MIT Test & Chart
13. Describe proposed or completed of starting any proposed work). proposed completion or recompletion or recompletion or recompletion or recompletion or recompletion or recompletion or recompletion. 1. MIRU PU 2. POOH with existing injection equipm 3. Set a CIBP plus 5' cement at approx. 4. Add perforations selectively in Zone 5. RIH with injection equipment and performed for the proposed of t	operations. (Clearly state all pertinent details, an SEE RULE 19.15.7.14 NMAC. For Multiple Coetion. During this the closed-tank and h disposal perform MIT. Rig Release Date: Rig Release Date:	procedure we plan to use loop system with a steel aul contents to the required er ODC Rule 19.15.17 tion of Approval: notify Hobbs office 24 hours running MIT Test & Chart
13. Describe proposed or completed of starting any proposed work). proposed completion or recompletion or recompletion or recompletion or recompletion or recompletion or recompletion or recompletion. 1. MIRU PU 2. POOH with existing injection equipm 3. Set a CIBP plus 5' cement at approx. 4. Add perforations selectively in Zone 5. RIH with injection equipment and performed for the recompletion injection 8. 9. Spud Date: I hereby certify that the information above SIGNATURE **Ellipsi Additional Completion** SIGNATURE	operations. (Clearly state all pertinent details, an SEE RULE 19.15.7.14 NMAC. For Multiple Coetion. During this the closed-tank and h disposal perform MIT. Rig Release Date: Prior of Rig Release Date: TITLE L. Eguar DATE	procedure we plan to use cloop system with a steel aul contents to the required er ODC Rule 19.15.17 tion of Approval: notify Hobbs office 24 hours running MIT Test & Chart re and belief. //2//E
13. Describe proposed or completed of starting any proposed work). proposed completion or recompleted of starting any proposed work). 1. MIRU PU 2. POOH with existing injection equipm 3. Set a CIBP plus 5' cement at approx. 4. Add perforations selectively in Zone 5. RIH with injection equipment and performed performed to injection 8. 9. Turn well to injection 8. 9. Spud Date: I hereby certify that the information above SIGNATURE Type or print nameRick Reeves	operations. (Clearly state all pertinent details, an SEE RULE 19.15.7.14 NMAC. For Multiple Coetion. During this the closed-tank and h disposal perform MIT. Rig Release Date: Prior of Rig Release Date: TITLE L. Eguar DATE	procedure we plan to use cloop system with a steel aul contents to the required er ODC Rule 19.15.17 tion of Approval: notify Hobbs office 24 hours running MIT Test & Chart re and belief. //2//E
13. Describe proposed or completed of starting any proposed work). proposed completion or recompletion or recompletion or recompletion or recompletion or recompletion or recompletion or recompletion. 1. MIRU PU 2. POOH with existing injection equipm 3. Set a CIBP plus 5' cement at approx. 4. Add perforations selectively in Zone 5. RIH with injection equipment and performed for the proposed of t	operations. (Clearly state all pertinent details, an SEE RULE 19.15.7.14 NMAC. For Multiple Coetion. During this the closed-tank and h disposal perform MIT. Rig Release Date: Rig Release Date: TITLE Roy. Expure DATE	procedure we plan to use loop system with a steel aul contents to the required er ODC Rule 19.15.17 tion of Approval: notify Hobbs office 24 hours running MIT Test & Chart