

Submit 1 Copy To Appropriate District	State of 1	New Me	exico	Form C-103
Office District I – (575) 393-6161	Energy, Minerals	and Natu	ral Resources	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240				WELL API NO.
District II – (575) 748-1283	OIL CONSERV	ATION	DIVISION	30-025-01415
811 S. First St., Artesia, NM 88210 District III – (505) 334-6178	1220 South			5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe			STATE FEE
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Salla re	, INIVI 0	/303	6. State Oil & Gas Lease No.
87505				K-0385
SUNDRY NOT	CES AND REPORTS ON	WELLS		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPO				State 35
DIFFERENT RESERVOIR. USE "APPLIC PROPOSALS.)	CATION FOR PERMIT" (FORM	· · ·	,	8. Well Number #1
1. Type of Well: Oil Well	Gas Well 📋 Other	HÔ	BBS OCD	
2. Name of Operator		` .		9. OGRID Number
Mack Energy Corporation		DF	C 042018	013837
3. Address of Operator		P	2.010	10. Pool name or Wildcat
P.O. Box 960 Artesia,NM 88210				Corbin; Abo
4. Well Location		- RE	ECEIVED	1
Unit Letter M :	760 feet from the	e C	line and	330 feet from the W line
Section 35	Township 17S	Range	and the second	NMPM County Lea
	11. Elevation (Show wh 4131' GR	einer DR,	, KKB, KT, GK, etc.	
	4151 GK			Barran an and an art and the star star star was an art and a star a
	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL		SUE REMEDIAL WOF	RILLING OPNS.
DOWNHOLE COMMINGLE				
CLOSED-LOOP SYSTEM				
OTHER:			OTHER:	
of starting any proposed we proposed completion or rec 1. Tag 5 ½" CIBP @ 85 2. Spot 25 sx cmt @ 852 3. Spot 25 sx cmt @ 442 4. Perf & Sqz 75 sx cmt	ork). SEE RULE 19.15.7. ompletion. 20'. Pressure test csg. Cin 5-8220'. 3-4323'. WOC & Tag (D @ 3420-3020'. WOC & '	14 NMA rculate h <u>V Tool)</u> Tag (8 5/	C. For Multiple Co ole w/ MLF. 8" Shoe) 3].	and give pertinent dates, including estimated date completions: Attach wellbore diagram of 34' RFACE See Attached pprovaled See Attached pprovaled
5. Perf & Sqz 45 sx cmt @ 2800-2700'. (B/Salt) WOC \$TAG-				
6. Perf & Sqz 45 sx cmt @ 1680-1500'. WOC & Tag (T/Salt)				
20 4. 7. Perf & Sqz 120 sx cmt @ 410-316". WOC & Tag (11 3/4" Shoe) TO SURFACE				
9. Cut off well head, verify cement to surface, weld on Dry Hole Marker.				
				- noi-
]			
Spud Date:	Rig R	lelease Da	ate:	
	Ŭ			
I hereby certify that the information	above is true and complet	e to the b	est of my knowled	ge and helief
interest certify that the information	acove is and and complete		cor or my knowledg	Be wire Deller.
SIGNATURE 10 - · 1 AA		пΛ	T	DUTE IN LILION
SIGNATURE Ungail Montgomerys TITLE Agent DATE 12/4/2018				
Time any intrans (1). 1 Mg 1				
Type or print name Abigail Montgomere, E-mail address: me bernandassociates. com For State Use Only PHONE: 432-580-7161				
For State Use Only	(, , ° , ' , ' , ' , ' , ' , ' , ' , ' ,	_		•
APPROVED BY Mahl	titale_ TITI	EPE	.S.	DATE 12/04/2018
	III LI	~	• · •	

.

Conditions of Approval (if any):





GENERAL CONDITIONS OF APPROVAL:

- 1) Insure all bradenheads have been exposed, identified, and valves are operational prior to rigging up on well.
- 2) Contact the appropriate NMOCD District Office no later than 24 hours prior to moving in and rigging up.
- 3) A copy of the approved C103 intent to P&A should be distributed to the onsite company and plugging representatives. Approved procedures are good for a period of one year from approved date, unless otherwise specified on the C103 intent. Approvals past this date will require the submission and approval of a new C103 intent.
- 4) A company representative is required to be present to witness all operations including setting CIBP's, circulation of mud laden fluids, perforating, squeezing or spotting cement plugs, tags, or any other operations approved on the C103 intent to P&A. Company representative should contact the NMOCD and report all operations.
- 5) Any changes that may be required during plugging operations should be approved by the NMOCD before proceeding.
- 6) A closed loop system is to be used for all plugging operations. Contents of the steel pits to be hauled to a NMOCD permitted disposal facility.
- 7) Mud laden fluids must be placed between all cement plugs mixed at 25 sacks of salt gel per 100 barrels of brine.
- 8) All cement plugs will be 100' or 25 sacks cement, whichever is greater. Class 'C' cement will be used above 7500' and Class 'H' below 7500'.