UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

OMB NO. 1004-0137 Expires: January 31, 2018

5.	Lease Serial No.
	NMNM77058

BUREAU OF LAND MANAGEMENT	000 11 11
SUNDRY NOTICES AND REPORTS ON WELLS	UCD Hobbs
Do not use this form for proposals to drill or to re-enter	an

abandoned well. Use form 3160-3 (APD) for such proposals.

6. If Indian, Allottee or Tribe Name

FORM APPROVED

SUBMIT IN 1	TRIPLICATE - Other instructions	on page OBBS	OCD	7. If	Unit or CA/Agreement,	Name and	or No.			
 Type of Well Gas Well ☐ Oth 		FEB 07 2019 8. Well Name and RED TANK FE				/				
2. Name of Operator EOG RESOURCES INCORPO	DDOX esources RECEIN	/FN		PI Well No. 0-025-32539-00-S1		_				
3a. Address MIDLAND, TX 79702	ne No. (include area code) 2-686-3658		10. Field and Pool or Exploratory Area W RED TANK							
4. Location of Well (Footage, Sec., T.			11. C	ounty or Parish, State						
O Sec 14 T22S R32E SWSE 33	0FSL 2310FEL			LE	EA COUNTY, NM					
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA										
TYPE OF SUBMISSION	TYPE OF ACTION									
□ Notice of Intent	☐ Acidize ☐	Deepen	☐ Producti	ion (St	· —	Water Sh				
Subsequent Report	, 16 -	Hydraulic Fracturing	☐ Reclama			■ Well Integrity				
		New Construction	Recomp		_	Other				
☐ Final Abandonment Notice		Plug and Abandon Plug Back	☐ Tempor	•						
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLMBIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. EOG PLUGGED AND ABANDONED THIS WELL USING THE FOLLOWING PROCEDURE: 12/22/2018 MIRU 12/28/2018 SET CIBP @8400', TAG CIBP @ 8400', DMP 25 SXS CL H CMT 01/04/2018 TAG TOC ON TOP OF CIBP @ 8362' 01/05/2018 PMP 25 SXS CL H CMT @7531' 01/09/2018 TAG TOC @ 7513', SET ANOTHER CIBP @ 4790'DUMP 35 SXS CMT 01/11/2018 TAG TOC @4775', PERE @ 4480', COULD NOT PMP INTO PER BLM SPOT 30 SXS CI C CMT, WOC TAG TOC @4265' 01/11/2019 RIH PERF @1230', SQZ W/105 SXS CI C CMT TO SURFACE 14. I hereby certify that the foregoing is true and correct.										
Electronic Submission #450552 verified by the BLM Well Information System For EOG RESOURCES INCORPORATED, sent to the Hobbs Committed to AFMSS for processing by DEBORAH MCKINNEY on 01/28/2019 (18PP1908SE)										
Name (Printed/Typed) KAY MAD	Title REGUL	Title REGULATORY SPECIAL FOR RECORD				RD				
Signature (Electronic S	submission)	Date 01/14/20	019							
THIS SPACE FOR FEDERAL OR STATE OFFICE USE JAN 3 0 2019										
Approved By		Title		BU	DMG/Cinney IREAU OF LAND MA	1 ALL ACTION DATES	vi			
Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to condu		Ĺ	· - · · . · .	CARLSBAD FIELD	OFFICE					

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **

NMOCD 2-8-19



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines (Contact service companies, allowing plenty of time to have the risers and power lines and poles removed prior to reclamation, don't wait till the last day and try to get them to remove infrastructure). Strip and remove caliche, contour the location to blend with the surrounding landscape, re-distribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- 1. The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you

have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909, 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Crystal Weaver Environmental Protection Specialist 575-234-5943

Shelly Tucker Environmental Protection Specialist 575-234-5979

Trishia Bad Bear, Hobbs Field Station Natural Resource Specialist 575-393-3612