Submit 1 Copy To Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources			Form C-103 Revised August 1, 2011
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	 -			WELL API NO.
District II – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION			30-025-05492
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.			STATE STATE
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe (NW 87505)			6. State Oil & Gas Lease No.
87505 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lea				7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUCE BOOK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-1010) FOR SUCH PROPOSALS.)				South Hobbs (G/SA) Unit
1. Type of Well: Oil Well Gas Well Other: Injector			8. Well Number: 25-431 —	
2. Name of Operator				9. OGRID Number: 157984
Occidental Permian Ltd. 3. Address of Operator				10. Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX 79323			` _ '	
4. Well Location	0310 r		330	/
Unit Letter I: 2463 feet from the South line and 1108 feet from the East line				
Section 25 Township 18S Range 37E NMPM Lea County 11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
3649' (GL)				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
	NTENTION TO:			SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK			<u> </u>	
TEMPORARILY ABANDON			<u> </u>	
DOWNHOLE COMMINGLE		Ш	CASING/CEIVIEN	
	•	_		<u>_</u>
OTHER: 13 Describe proposed or com	unleted onerations (Clearly	state all r	OTHER:	d give pertinent dates, including estimated date
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. Condition of Approval: notify				
1. Injection Profile Log indicates the lower isolation packer is not set and injection is Colorate Packers 2. MIRLI PUI				
2. MIRU PU 3. POOH with existing injection equipment. prior of running MIT Test & Chart				
,				
 4. RIH with test packer and find a depth where we can set a hydraulic packer with confidence. 5. RIH and set isolation packers across Zone 2CL to isolate perforations 4456'- 				
4492'. Upper packer will be approx. 4440' and lower packer approx. 4505' During this procedure we plan to use				
(depending on test packer findings).				
o. Ferform Will.				
7. RDMO PU. 8. Turn well to injection disposal per ODC Rule 19.15.17				
6. Turn wen to injection				disposal per ODC Rule 19.15.17
				disposal per ODC Rule 19.15.17
G-1 Date		alaaa Da		disposal per ODC Rule 19.15.17
Spud Date:	Rig R	elease Da		disposal per ODC Rule 19.15.17
Spud Date:	Rig R	elease Da		disposal per ODC Rule 19.15.17
Spud Date: I hereby certify that the informatio			ite:	
	n above is true and complete	e to the be	est of my knowledge	e and belief.
I hereby certify that the information	n above is true and complete	e to the be	est of my knowledge	e and belief.
I hereby certify that the information SIGNATURE Mile 12	n above is true and complete	e to the be	est of my knowledge	e and belief.
I hereby certify that the information SIGNATURE Mill 12 Type or print name _Rick Reeves	n above is true and complete	e to the be	est of my knowledge	e and belief.
I hereby certify that the information SIGNATURE Mild 13 Type or print nameRick Reeves For State Use Only	n above is true and complete	Prod. E	est of my knowledge DATE Srick reeves@oxy.	e and belief.