

Submit 1 Copy To Appropriate District Office  
District I - (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II - (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV - (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised August 1, 2011

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO.
30-041-20940
5. Indicate Type of Lease STATE X FEE
6. State Oil & Gas Lease No. VB-1609
7. Lease Name or Unit Agreement Name PEP 36 STATE
8. Well Number 002
9. OGRID Number 1092
10. Pool name or Wildcat Wildcat; Penn

FEB 25 2019

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR PROPOSALS.)	
1. Type of Well: Oil Well X Gas Well Other	
2. Name of Operator ARMSTRONG ENERGY CORPORATION	
3. Address of Operator PO BOX 1973, ROSWELL, NM 88202-1973	
4. Well Location Unit Letter M : 330 feet from the South line and 330 feet from the West line Section 36 Township 5S Range 33E NMPM Roosevelt County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	P AND A <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPL <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>	
DOWNHOLE COMMINGLE <input type="checkbox"/>			
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

SEE ATTACHED

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Vice President Engineering DATE 2/22/19

Type or print name Kyle Alpers E-mail address: kalpers@aecnrm.com PHONE: 575-625-2222

For State Use Only

APPROVED BY: [Signature] TITLE Compliance Officer A DATE 3-4-19  
Conditions of Approval (if any):

Plugging Report  
Pep 36 State #2  
30-041-20940

1/30/2019 Moved in unit and rigged up. Moved in workstring and remaining plugging equipment. Picked up 6500' of workstring and SION.

1/31/2019 Circulated hole with MLF and tested casing to 500#. Casing good. Spot 25 sx Class C cement at 6500'. Top of Abo. Stood back 65 stands and laid down remaining tubing. Dug out cellar around the surface head and worked to remove the bolts from the bottom of the surface head. Installed four bolts to secure the wellhead and SION.

2/1/2019 Removed top casing spool and welded on 5 1/2" pull stub. Worked casing slips free from the wellhead. Worked casing in the hole and performed stretch tests. Casing showing to be free between 3000' and 3100'. Rigged up wireline and RIH with cutter and collar locator. Casing collar at 2990'. Cut casing at 3005'. Laid down top cut off joint, 67 full joints, and bottom cut off. Tally was 3004'. Reinstalled wellhead and shut down.

2/4/2019 RIH to 3055' with the tubing and caught circulation with brine. Circulated the hole with fluid from the steel pit until the hole was balanced. Spotted 50 sx class C cement with CaCl at 3055'. POOH and WOC. Tagged cement at 2777'. POOH to 2181' and spotted 40 sx class C cement with CaCl. POOH and WOC. Tagged cement at 2043'. POOH to 422' and spotted 35 sx cement. POOH to 102' and circulated cement to surface with 30 sx. Laid down and rinsed out remaining tubing. SION.

2/5/2019 Rigged down. Dug out wellhead and cut off. Filled up 8 5/8" casing to surface with less than 1 sack of cement. Installed marker, cut off anchors and cleared the location.



500 North Main Street, Suite 200  
P.O. Box 1973  
Roswell, New Mexico 88202-1973  
(575) 625-2222  
Fax (575) 622-2512

February 22, 2019

Oil Conservation Division  
1625 N. French Drive  
Hobbs, New Mexico 88240

Attention: Paul Kautz

Re: Pep 36 State #2  
Township 5 South, Range 33 East, NMPM  
Section 36M  
Roosevelt County, New Mexico

Dear Mr. Kautz:

Enclosed is a C-103, Sundry Notices and Reports on Wells, Subsequent Report, Plug and Abandon, for the Pep 36 State #2.

If you have any questions, please contact Kyle Alpers at 575-625-2222.

Sincerely,

ARMSTRONG ENERGY CORPORATION

By: *Irma Cunningham*  
Irma Cunningham, Geo Tech

Enclosures