

Submit 1 Copy To Appropriate District	State of New Me	vico		Form C-103	
Office	Energy, Minerals and Natural Resources		Revised July 18, 2013		
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240			WELL API NO.		
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DI		30-025-28010		
District III - (505) 334-6178	1220 South St. Francis Dr.		5. Indicate Type of Leas STATE	e FEE	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460	Santa Fe, NM 87	((<i>Y</i>)	6. State Oil & Gas Lease		
1220 S. St. Francis Dr., Santa Fe, NM			LG-2265		
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit A	greement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO			Superior WA State	<i>8</i> · · · · · · · · · · · · · · · · · · ·	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-1941) FOR SUCH			8. Well Number #1		
1. Type of Well: Oil Well 🔀 Gas Well 🗌 Other					
2. Name of Operator			9. OGRID Number		
Foundation Energy Management, LLC			143199 10. Pool name or Wildcat		
3. Address of Operator 5057 Keller Springs Rd Suite 650, Addison, TX 75001			Saunders Permo Upper Penn		
4. Well Location N					
Unit Letter N, 660' feet from the <u>South line and 660'</u> feet from the <u>West</u> line					
Section 11 Township 14S Range 33E NMPM County Lea					
	11. Elevation (Show whether DR,				
	4247.5	' GR			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON PERFORM REMEDIAL WORK PLUG AND ABANDON PULL OR ALTER CASING MULTIPLE COMPL DOWNHOLE COMMINGLE MULTIPLE COMPL					
	_			_	
OTHER:		OTHER:	1 - !		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.					
Set CIBP @ 9829' Bail Dump \$SX on top and WOC. Pressure Test tubing to 500#. TOH with tubing. Load casing with 258 bbl of 9.5 lb mud. Pump 100' (33 SX) plug inside casing from 50' below intermediate casing shoe (4235'-4135'). Perf and sqz 30 sx plug at base of salt section (~2841'). Perf and sqz 30 sx plug at top of salt section (-1833'). <u>Pump top plug inside/out (100')</u> to surface. Dig out wellhead, cut off wellhead, verify cement to surface on all strings, Add above ground marker with proper ID information. Note: All Balanced or Sqz plugs will wait on the surface of the notified 24 hours prior to beginning plugging operations.					
star Ar	٩	erfd Sæza	9 100' circ to	SurF	
er go'	•		5.100		
off wellhead, verify cement to surface on all strings, Add above ground marker with proper ID information. Note: All Balanced of Sqz plugs will wait on compression tag NMOCD will be notified 24 hours prior to beginning plugging operations. PerF4 Sqz@100' circ to SurF See information Note: All Balanced of Sqz PerF4 Sqz@100' circ to SurF INSTALL 4"dia 4'Tall MARKer					
A/2/2010		4/8/2010			
Spud Date: 4/2/2019	Rig Release Da	ite:			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.					
2/1	0 p	1 - 1	1	24 2010	
SIGNATURE	TITLE [2/	4 Engineer	DATE_	-26-2019	
Type or print name <u>Bill</u> Job For State Use Only	E-mail address	: bjohnsona fo	endation en ergy.com	918-526-5549	
APPROVED BY: <u>Kerry</u> Joi Conditions of Approval (if any):	terTITLE_	-pliance Off	uien A DATE 3	-1-19	

		/
onditions	of Approv	val (if and):





GENERAL CONDITIONS OF APPROVAL:

- 1) Insure all bradenheads have been exposed, identified, and valves are operational prior to rigging up on well.
- 2) Contact the appropriate NMOCD District Office no later than 24 hours prior to moving in and rigging up.
- 3) A copy of the approved C103 intent to P&A should be distributed to the onsite company and plugging representatives. <u>Approved procedures are good for a period of one year from approved date, unless otherwise specified on the C103 intent</u>. Approvals past this date will require the submission and approval of a new C103 intent.
- 4) A company representative is required to be present to witness all operations including setting CIBP's, circulation of mud laden fluids, perforating, squeezing or spotting cement plugs, tags, or any other operations approved on the C103 intent to P&A. Company representative should contact the NMOCD and report all operations.
- 5) Any changes that may be required during plugging operations should be approved by the NMOCD before proceeding.
- 6) A closed loop system is to be used for all plugging operations. Contents of the steel pits to be hauled to a NMOCD permitted disposal facility.
- 7) Mud laden fluids must be placed between all cement plugs mixed at 25 sacks of salt gel per 100 barrels of brine.
- All cement plugs will be 100' or 25 sacks cement, whichever is greater. Class 'C' cement will be used above 7500' and Class 'H' below 7500'. Plugs should be no more than 3000' apart
- 9) Site remediation due within one year of well plugging completion.