Submit 1 Copy To Appropriate District Office	State of New Mexico	Form C-103	
District I – (575) 393-6161	Energy, Minerals and Natural Resources	Revised July 18, 2013	
1625 N. French Dr., Hobbs, NM 88240	•	WELL API NO.	
<u>District II</u> – (575) 748-1283 811 S. Eirst St. Artesia NM 88210	CONSERVATION DIVISION	30-025-05448	
<u>District III</u> – (505) 334-6178	1220 South St. Francis Dr.	5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 834 A	Santa Fe, NM 87505	STATE FEE 6. State Oil & Gas Lease No.	
$\frac{District II}{District II} = (575) 748-1283$ 811 S. First St., Artesia, NM 88210 <u>District III</u> = (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 844 <u>District IV</u> = (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	A Santa Fe, NM 87505 ES D REPORTS ON WELLS	6. State Off & Gas Lease No.	
87505 CLINIDRY NOTIC	ES BEDORTS ON WELLS	7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOS	AS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	North Hobbs (G/SA) Unit	
DIFFERENT RESERVOIR. USE "APPEOA	AS TO DRILL OR TO DEEPEN OR PLUG BACK TO A TION FOR PERMIT" (FORM C-101) FOR SUCH	8. Well Number 13-131	
PROPOSALS.)		8. Well Nulliber 15-151	
1. Type of Well: Oil Well Gas 2. Name of Operator	s Well 🔲 Other Temporarily Abandoned 🛛	9. OGRID Number 157984	
Occidental Permian Ltd.		9. OOKID Nullider 137984	
3. Address of Operator		10. Pool name or Wildcat	
PO BOX 4294, HOUSTON, TX 772	10	Hobbs (G/SA)	
4. Well Location			
	1 <u>980</u> feet from theS line and330	feet from theWline	
Section 13			
	Township18SRange37E11. Elevation (Show whether DR, RKB, RT, GR, etc.		
	3691' KB		
12. Check Ar	propriate Box to Indicate Nature of Notice,	Report or Other Data	
-	• •		
NOTICE OF INT		SEQUENT REPORT OF:	
—	PLUG AND ABANDON		
TEMPORARILY ABANDON	CHANGE PLANS	— — —	
PULL OR ALTER CASING	MULTIPLE COMPL CASING/CEMEN	ГЈОВ 🔲	
DOWNHOLE COMMINGLE			
CLOSED-LOOP SYSTEM	_		
OTHER:			
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of			
proposed completion or recompletion			
proposed completion of recor	Th	No a	
 MIRU on TA'd well to perform MIT for extension of TA status Casing had 0 psig 			
3. Tested casing to 500 psig - held good for 30 minutes			
4. RDMO Abandonment E			
	ADEREODETTETT Employed	5-14-3	
	Abandonment Explicit 3-1	3-14-3021 2-2021	
Spud Date: 03/18/1961	Rig Release Date:		
I hereby certify that the information ab	ove is true and complete to the best of my knowledg	e and belief.	
	()) att		
SIGNATURE MANON W ARTA TITLE: Regulatory Lead - EOR DATE: 03/14/2019			
Type or print name: <u>Sharon Wyatt</u>	E-mail address: <u>Sharon_Wyatt@oxy.com</u> PH	IONE: <u>713-366-5162</u>	
For State Use Only			
APPROVED BY:	TITLE	DATE	
Conditions of Approval (if any):	111LE	DAIE	
conditions of reprived (it dify).			

