	UNITED STATES		OMB	M APPROVED NO. 1004-0137 : January 31, 2018	
BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such property BS OCD			5. Lease Serial No. NMNM11872	<ul> <li><sup>1</sup> '5. Lease Serial No. NMNM118722</li> <li>6. If Indian, Allottee or Tribe Name</li> </ul>	
			6. If Indian, Allotte		
SUBMIT IN	TRIPLICATE - Other instruct	tions on page 2 MAR 112	7. If Unit or CA/Ag	reement, Name and/or No.	
1. Type of Well  S Oil Well Gas Well Ot	DECEN	8. Well Name and No. SD WE 23 FEDERAL P7 3H			
2. Name of Operator Contact: CINDY H MURIL CHEVRON USA INC E-Mail: CHERRERAMURILLO@CHEV			9. API Well No. 30-025-43088-00-S1		
Ba. Address 1616 W. BENDER BLVD HOBBS, NM 88240	. Phone No. (include area code) a: 575-263-0431 b: 575-263-0445	10. Field and Pool or Exploratory Area JENNINGS-UPPER BONE SPRING SH			
Location of Well (Footage, Sec., 7		11. County or Paris	h, State		
Sec 14 T26S R32E SESE 21		LEA COUNTY	/, NM		
12. CHECK THE A	PPROPRIATE BOX(ES) TO	INDICATE NATURE OF	F NOTICE, REPORT, OR O	THER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent	Acidize	Deepen	Production (Start/Resume)	UWater Shut-Off	
	Alter Casing	Hydraulic Fracturing	Reclamation	Well Integrity	
Subsequent Report	Casing Repair	New Construction	Recomplete	Other Workover Operations	
Final Abandonment Notice	<ul> <li>Change Plans</li> <li>Convert to Injection</li> </ul>	Plug and Abandon Plug Back	Temporarily Abandon Water Disposal	workover operations	
Attach the Bond under which the wo following completion of the involved testing has been completed. Final A determined that the site is ready for f CHEVRON USA INC RESPE ATTEMPT TO CLEAN OUT T PERFORATIONS.	d operations. If the operation results bandonment Notices must be filed or final inspection. CTFULLY REQUESTS TO W	in a multiple completion or reco ly after all requirements, includi	mpletion in a new interval, a Form 3 ng reclamation, have been complete NELL. THE PROPOSED WC	160-4 must be filed once d and the operator has	
1. MIRU 2. PULL EQUIPMENT 3. RU WL AND RUN A CBL/C 4. PRESSURE TEST PRODU 5. CO TO TD 6. FRAC THE HORIZONTAL 7. CO TO TD 8. RIH WITH PRODUCTION	JCTION CASING PORTION OF THE WELL				
<ol> <li>I hereby certify that the foregoing is</li> <li>Cor</li> </ol>	Electronic Submission #4521	ON USA INIC, sent to the Ho	bbs		
	MURILLO		TING SPECIALIST		
	<b></b>				
Signature (Electronic		Date 01/29/20			
				Pres de la c	
Approved By /s/ Jonathon Shepard Conditions of approval, if any, are attached. Approval of this notice does not warrant or		Title 🔿		FEB 1 3 2019	
			vieum Engineer		
ertify that the applicant holds legal or eq hich would entitle the applicant to cond		bad Field Offic	e		
	N.S.C. Section 1212 melasity sector				
tle 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	statements or representations as to ar	e for any person knowingly and ny matter within its jurisdiction.	willfully to make to any department	or agency of the United	

## Additional data for EC transaction #452193 that would not fit on the form

32. Additional remarks, continued

9. RDMO.

. S

5

## **BUREAU OF LAND MANAGEMENT**

Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

## Conditions of Approval for Workover/Deepening of a Well

- <u>Notification</u>: Contact the appropriate BLM office at least 24 hours prior to the commencing of any operations. For wells in Eddy County, call 575-361-2822. For wells in Lea County, call 575-393-3612
- <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,100 feet, a 3M system for a well not deeper than 13,600 feet, or a 5M system for a well not deeper than 22,700 feet (all depths are for measured well depth).
- 3. <u>Cement</u>: Notify BLM if cement fails to circulate.

. . . Y

- <u>Subsequent Reporting</u>: Within 30 days after work is completed, file a Subsequent Report (Form 3160-5) to BLM. The report should give in detail the manner in which the work was carried out. <u>Show date work was completed</u>. If producing a new zone, submit a Completion Report (Form 3160-4) with the Subsequent Report.
- 5. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.
- If well location is within the Timing Limitation Stipulation Area for Lesser Prairie-Chicken: From March 1<sup>st</sup> through June 15<sup>th</sup> annually, abandonment activities will be allowed except between the hours from 3:00 am and 9:00 am. Normal vehicle use on existing roads will not be restricted.