Fcrm 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Hobbs

FORM APPROVED OMB NO. 1004-0137

Expires: January 31, 2018

5. Lease Serial No. NMNM94093

SUNDRY		NMNM94093					
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on page 2				6. If Indian, Allottee or Tribe Name 7. If Unit or CA/Agreement, Name and/or No. NMNM88523X			
2. Name of Operator Contact: JACKIE LATHAN MEWBOURNE OIL COMPANY E-Mail: jlathan@mewbourne.com				Well No. 30-025-31115-00-S1			
3a. Address P O BOX 5270 HOBBS, NM 88241	Phone No. (include area code): 575-393-5905	aclude area code) 10. Field and Pool or Exploratory Area			i		
4. Location of Well (Footage, Sec., T Sec 24 T18S R32E NWSW 23		1	11. County or Parish, State LEA COUNTY, NM				
12. CHECK THE AF	PROPRIATE BOX(ES) TO	INDICATE NATURE OF	F NOTICE, R	EPORT, OR OTH	ER DATA		
TYPE OF SUBMISSION TYPE OF ACTION							
□ Notice of Intent □ Subsequent Report □ Final Abandonment Notice 13. Describe Proposed or Completed Ope If the proposal is to deepen directions Attach the Bond under which the wor following completion of the involved testing has been completed. Final Abdetermined that the site is ready for fit OCT 11 2018 MIRU plugging BOP & release O/O tool. LD the CIBP. OCT 12 2018 RIH & set 4 1/2' Class H neat cmt from 8380' - Left EOT @ 7100'.	ally or recomplete horizontally, give k will be performed or provide the E operations. If the operation results andonment Notices must be filed on nal inspection. equipment. Dig cellar & ND W og. Notified Jim Amos w/BLM	subsurface locations and measurement No. on file with BLM/BIA in a multiple completion or recordly after all requirements, including the Attempted to release pof intent to leave packer in the state of	Reclamati Recomple Temporari Water Dis g date of any proper and true verti Required subsempletion in a new ing reclamation, in the color of the colo	te fily Abandon posal posed work and approx cal depths of all pertine quent reports must be in vinterval, a Form 3160 have been completed an ess. NU RECLAM sks	ent markers and filed within 30 d 1-4 must be filed and the operator h ATION PROC ATTACHED	hereof. zones. lays l once nas	
OCT 13 2018 POOH to 6980' & WOC. RIH & tag cmt @ 661 5249'. POOH to 4000'.	& spot 25 sks of class C cmt 1'. POOH to 5627' & spot 25	w/2% CaCl from 6980' - 6 sks of class C cmt w/2% (600'. POOH to CaCl from 562		C LAM A E <u>4-19</u>		
14. I hereby certify that the foregoing is	Electronic Submission #4552	E OIL COMPANY. sent to th	ne Hobbs				
Name (Printed/Typed) JACKIE L	ATHAN	Title REGUL	ATORY A	CCEPTED FO	R RECO	RN	
Signature (Electronic S	submission)	Date 02/20/20		COLITEDIO	JI NEOU		
	THIS SPACE FOR F	EDERAL OR STATE (OFFICE US	FEB 2 (2019		
Approved By		Title		pnekinne	UE		
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		varrant or		BUREAU OF LAND CARLSBAD FII	MANAGEME	AL .	
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s	U.S.C. Section 1212, make it a crime	e for any person knowingly and matter within its jurisdiction.	willfully to make	to any department or a	ngency of the U	nited	

(Instructions on page 2)
** BLM REVISED **

** BLM REVISED ** BLM REVISED **

** BLM REVISED ** BLM REVISED **

** BLM REVISED **

Additional data for EC transaction #455259 that would not fit on the form

32. Additional remarks, continued

OCT 16 2018 RIH & tag cmt @ 5350'. Spot 25 sks of class C cmt w/2% CaCl from 5350' - 4970'. POOH to 3730' & WOC. RIH & tag cmt @ 4980'. POOH to 4059' & spot 30 sks of class C cmt w/2% CaCl from 4059' - 3679'. POOH to 2439' & WOC. RIH & tag cmt @ 3638'. POOH to 3621' & spot 30 sks of class C cmt w/2% CaCl from 3321' - 2867'. POOH to 1627'. SWI & SDFD. Notified Jim McCormick w/BLM of plugs, approved.

OCT 17 2018 RIH & tag cmt @ 2890'. POOH & LD tbg. MIRU BCM WL. RIH w/1 11/16" gun & perf @ 2780'. RIH & set pkr @ 2294' & attempt to establish injection rate through perfs w/no success. Release pkr & POOH. RIH w/tbg to 2829'. Spot 25 sks class C cmt w/2% CaCl. POOH to 1590' & WOC. RIH & tag cmt @ 2502'. POOH to 1999' & spot 35 sks Class C cmt from 1999' - 1816'. POOH w/tbg.

OCT 18 2018 RIH & tag cmt @ 1846'. POOH to 1752' & spot 40 sks class C cmt w/2% CaCl from 1752' - 1598'. POOH w/tbg & WOC. RIH & tag cmt @ 1610'. POOH to 460' & spot 35 sks class C cmt w/2% CaCl from 460' - 344'. POOH & WOC. ND BOP. RIH & tag cmt @ 340'. POOH w/tbg. MIRU BCM WL & RIH w/1 - 11/16" Titan perf charges. Perf csg @ 60' & POOH w/WL. Squeeze 60 sks class "C" neat cmt. Moved in backhoe & welder. Dug out cellar. Cut off well head. Verified cmt to surface. Welded on Above Ground Dry hole Marker. Backfilled cellar, cut off deadmen, cleaned location & moved off.

OCT 19 2018 RDMO BCM. P&A'd effective as of 10/19/2018.

Bond on file: NM1693 nationwide & NMB000919



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines (Contact service companies, allowing plenty of time to have the risers and power lines and poles removed prior to reclamation, don't wait till the last day and try to get them to remove infrastructure). Strip and remove caliche, contour the location to blend with the surrounding landscape, re-distribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- 1 The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you

have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909, 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Crystal Weaver Environmental Protection Specialist 575-234-5943

Shelly Tucker Environmental Protection Specialist 575-234-5979

Trishia Bad Bear, Hobbs Field Station Natural Resource Specialist 575-393-3612