

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised July 18, 2013

OIL CONSERVATION
HOBBS OGD
1220 South St. Francis Dr.
Santa Fe, NM 87501
APR 01 2019

WELL API NO. 30-025-34111
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. VA-814
7. Lease Name or Unit Agreement Name M.J. Harvey "16"
8. Well Number 1
9. OGRID Number 258660
10. Pool name or Wildcat Vacuum; Grayburg-San Andres
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4065 GR

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	
2. Name of Operator Three Forks Resources, LLC	
3. Address of Operator 4080 Youngfield Street, Wheat Ridge CO 80033	
4. Well Location Unit Letter H : 2121 feet from the N line and 519 feet from the E line Section 16 Township 17S Range 34E NMPM County Lea	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4065 GR	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION PERFORM REMEDIAL WORK TEMPORARY PULL OUT DOWN CLOSE OTHER <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> P AND A <input type="checkbox"/> CASING/CEMENT JOB <input type="checkbox"/> OTHER: Recompletion <input checked="" type="checkbox"/>
--	--

13. E... proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

5/2/18 Pull rods and pump.
5-3-18 Pull tubing, pick up retrievable bridge plug with fishing neck. Run RBP and packer while hydro testing the tubing to 8500', set RBP, release from RBP and set packer at 8469'. Test RBP to 1000#, RBP held pressure.
5/4/18 Pull packer and tubing to 4800', lay down extra tubing, spot 200 gallons 15% acid from 4589-4793. Pull tubing and packer.
5-5-18 Perforate San Andres from 4763-4776 4 SPF. Pick up treating packer, set at 4639. Swab well dry, recover load of water and trace of oil. Load backside.
5/7/18 Acidize well with 5000 gallons 15% NEFE acid. After shut-in period start swabbing back load.
Recover load with oil cut improving, minimal gas.
Well Test
5/10/18 Run rods and pump, put on rod pump.

Spud Date: 5/2/18 Rig Release Date: 5/10/18

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Irene Trujillo TITLE Operations Technician DATE 3/11/19
IRENE TRUJILLO Irene@3forksres.com 303-318-0717
Type or print name E-mail address: PHONE:

For State Use Only
APPROVED BY: Karen Sharp TITLE Staff Mgr DATE 4-2-19
Conditions of Approval (if any): Provide tubing detail