

Submit 1 Copy To Appropriate District Office	State of New M		Form C-103
<u>District 1</u> – (575) 393-6161	Energy, Minerals and Natural Resources		Revised August 1, 2011 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283			30-025-31285
811 S. First St., Artesia, NM 88210	OIL CONSERVATIO		5. Indicate Type of Lease
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Fr		STATE 🔲 FEE 🖾
District IV - (505) 476-3460	Santa Fe, NM	87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			
	TICES AND REPORTS ON WELI	LS	7. Lease Name or Unit Agreement Name
	OSALS TO DRILL OR TO DEEPEN OR F LICATION FOR PERMIT" (FORM C-101)		
PROPOSALS.)	CATION FOR FERMIT (FORM C-101)		Lovington Paddock Unit
1. Type of Well: Oil Well 🛛	Gas Well 🔲 Other	IOBBS OCT	8. Well Number: 105
2. Name of Operator			9. OGRID Number
Chevron Midcontinent, LP		APR 2 3 2010	241333 10. Pool name or Wildcat
3. Address of Operator 6301 DEAUVILLE BLVD., 1	MIDI AND TX 70706	AFR 2 3 2019	Lovington Paddock
	R		Lovington Faudock
4. Well Location Unit Letter D : 69 feet from the North line and 1324 feet from the West line			
Unit Letter <u>D</u> :			
Section 31	Township 16S	Range 37E	NMPM County Lea
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
3,822' GL, 3,838' KB			
12. Charle Americanista Device India(ta Natura of Nation, Depart on Other Date			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK D PLUG AND ABANDON			
TEMPORARILY ABANDON CHANGE PLANS			
PULL OR ALTER CASING 🔲 MULTIPLE COMPL 🔲 CASING/CEMENT JOB 🗌			
]		
OTHER:		OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 8-5/8" @ 1,860' TOC Surface, 5-1/2" @ 6,450' TOC Surface, Perforations: 6,102'-			
6,299', CIBP set at 6,006' w/ 35' cmt cap.			
Chevron USA INC respectfully request to abandon this well as follows:			
1. Call and notify NMOCD 24 hrs before operations begin.			
2. Pressure test casing to 500 psi f/ 10 min rig-less.			
3. MIRU CTU, check well pressures, perform bubble test on intermediate and surface casing annuli, if bubble test fails			
Chevron intends to Zonite the well after it is plugged to a certain point agreed upon by the NMOCD and Chevron.			
4. TIH w/ coil tubing and tag CIBP cmt cap at 5,971', spot enough MLF t/ allow it to be between cement plugs, and			
spot 25 sx CL "C" cmt f/ 5,971' t/ 5,725', WOC & tag only if casing does not pressure test. 5. Spot 105 sx CL "C" cmt f/ 4,741' t/ 3,705' (San Andres, Grayburg, Queen).			
6. Spot 45 sx CL "C" cmt f/ 3,362' t/ 2,918' (7 Rivers, Yates). See Attached			
7. Spot 30 sx CL "C" cmt f/ 2,093' t/ 1,796' (Salt, Shoe). Conditions of Approval			–
8. Spot 35 sx CL "C" cmt f/ 300' t/ Surface (FW).			
9. Cut all casings & anchors & remove 3' below grade. <u>Verify</u> cement to surface & weld on dry hole marker (4" diameter 4' tall). Clean location			
diameter, 4' tall). Clean location. Note: All cement plugs class "C" (<7,500') or "H" (>7,500') with closed loop system used.			
		2) with alarad loop	sustam used
	ss "C" (<7,500') or "H" (>7,500		
I hereby certify that the informatio	ss "C" (<7,500') or "H" (>7,500 n above is true and complete to the	best of my knowledge	e and belief.
	ss "C" (<7,500') or "H" (>7,500	best of my knowledge	
I hereby certify that the informatio	ss "C" (<7,500') or "H" (>7,500 n above is true and complete to the TITLE <u>P&A Engineer, Attorn</u>	best of my knowledg ney in fact	e and belief. DATE <u>4/15/19</u>
I hereby certify that the informatio SIGNATURE Type or print name _Howie Lucas	ss "C" (<7,500') or "H" (>7,500 n above is true and complete to the TITLE <u>P&A Engineer, Attorn</u> E-mail address: <u>howi</u>	best of my knowledg ney in fact	e and belief. DATE <u>4/15/19</u> <u>n</u> PHONE: <u>(832)-588-4044</u>

WELLBORE DIAGRAM Lovington Paddock Unit # 105 Temporary Abandoned Oil Well (current)



TD: 6450'

WELLBORE DIAGRAM Lovington Paddock Unit # 105 Temporary Abandoned Oil Well (current)



····

GENERAL CONDITIONS OF APPROVAL:

- 1) Insure all bradenheads have been exposed, identified, and valves are operational prior to rigging up on well.
- 2) Contact the appropriate NMOCD District Office no later than 24 hours prior to moving in and rigging up.
- 3) A copy of the approved C103 intent to P&A should be distributed to the onsite company and plugging representatives. <u>Approved procedures are good for a period of one year from approved date, unless otherwise specified on the C103 intent</u>. Approvals past this date will require the submission and approval of a new C103 intent.
- 4) A company representative is required to be present to witness all operations including setting CIBP's, circulation of mud laden fluids, perforating, squeezing or spotting cement plugs, tags, or any other operations approved on the C103 intent to P&A. Company representative should contact the NMOCD and report all operations.
- 5) Any changes that may be required during plugging operations should be approved by the NMOCD before proceeding.
- 6) A closed loop system is to be used for all plugging operations. Contents of the steel pits to be hauled to a NMOCD permitted disposal facility.
- 7) Mud laden fluids must be placed between all cement plugs mixed at 25 sacks of salt gel per 100 barrels of brine.
- All cement plugs will be 100' or 25 sacks cement, whichever is greater. Class 'C' cement will be used above 7500' and Class 'H' below 7500'. Plugs should be no more than 3000' apart
- 9) Site remediation due within one year of well plugging completion.

_ `*