

Submit 1 Copy To Appropriate District	State of New Mexico	Form C-103
Office	Energy, Minerals and Natural Resour	
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283		WELL API NO.
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISIO	JN C. J. Farther T. Classical Stress
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis DB	BS OCD STATE FEE
District IV - (505) 476-3460	Santa Fe, NM 87505	
1220 S. St. Francis Dr., Santa Fe, NM 87505	MAY	0 3 20 9 A-1320
SUNDRY NOTIC (DO NOT USE THIS FORM FOR PROPOSA DIFFERENT RESERVOIR. USE "APPLICA	ES AND REPORTS ON WELLS ALS TO DRILL OR TO DEEPEN OR PLUCE REPORT TION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name Vacuum Glorieta East Unit 01
PROPOSALS.) 1. Type of Well: Oil Well 🛛 O	Gas Well 🔲 Other	-s. well Number 05
2. Name of Operator		9. OGRID Number
Cono	coPhillips Company	017643
3. Address of Operator		10. Pool name or Wildcat
	Parkway Houston, TX 77079	Vacuum; Glorieta
4. Well Location		
	286feet from theSouth line and	
Section 28	Township 17-S Range . 11. Elevation (Show whether DR, RKB, RT, G	35-E NMPM County Lea
	3968' GL	GK, elc.)
12. Check Ar	opropriate Box to Indicate Nature of N	Notice Report or Other Data
•	Jam	
NOTICE OF INT		SUBSEQUENT REPORT OF:
	MULTIPLE COMPL CASING/	
OTHER:	I OTHER:	tails, and give pertinent dates, including estimated date
		tiple Completions: Attach wellbore diagram of
proposed completion or reco		apie completions. Attach wendore diagram of
h h		
	D WH, NU BOP. POOH Prod Equipment	
	@ 5943' - Circ hole w/ MLF. Pressure test c	casing. Spot 25sx cmt @ 5943' – 5843'.
	s cmt @ 4789' – 4689'.	
Spot 25sx	cmt @ 4405' – 3975'. WOC-Tag	
Spot 40sx	$c \operatorname{cmt} (\hat{0}, 3745) - 3645)$	See Attached
	40sx cmt @ 3067' - 2640'. WOC-Tag	See Attached
	65sx cmt @ 1685' – 1480'. WOC-Tag 100sx cmt @ 521' – 421'. WOC-Tag	Conditions of Approva
	$50 \text{ sx cmt} (a) 527 - 427 \cdot w 0 \text{ cm} a$	- change of white
	ill wellbore. Verify cmt @ surface in all annu	ıli
	/H & anchors. Install <u>DH marke</u> r	•••
		, ,
	14 dia 4	l'above ground
A closed-loop system wil	ll be used for all fluids from this wellbore and d	isposed of required by OCD Rule 19.15.17
	[<u> </u>
Spud Date:	Rig Release Date:	
•		
I hereby certify that the information at	pove is true and complete to the best of my kn	nowledge and belief.
		-
SIGNATURE	TITLEAgent - Basic En	nergy ServicesDATE5/3/19
		DUONE. 433 843 3365
Type or print nameChris Rome	ero E-mail address:	PHONE:432-563-3355
For State Use Only	1	
APPROVED BY: Kerry For	TITLE Compliance (Office A DATE 5-7-19
Conditions of Approval (if any):		

WELLBORE SKETCH ConocoPhillips Company -- Permian Basin Business Unit

101304-27



WELLBORE SKETCH ConocoPhillips Company - Permian Basin Business Unit



GENERAL CONDITIONS OF APPROVAL:

- 1) Insure all bradenheads have been exposed, identified, and valves are operational prior to rigging up on well.
- 2) Contact the appropriate NMOCD District Office no later than 24 hours prior to moving in and rigging up.
- 3) A copy of the approved C103 intent to P&A should be distributed to the onsite company and plugging representatives. <u>Approved procedures are</u> good for a period of **one year** from approved date, unless otherwise <u>specified on the C103 intent</u>. Approvals past this date will require the submission and approval of a new C103 intent.
- 4) A company representative is required to be present to witness all operations including setting CIBP's, circulation of mud laden fluids, perforating, squeezing or spotting cement plugs, tags, or any other operations approved on the C103 intent to P&A. Company representative should contact the NMOCD and report all operations.
- 5) Any changes that may be required during plugging operations should be approved by the NMOCD before proceeding.
- 6) A closed loop system is to be used for all plugging operations. Contents of the steel pits to be hauled to a NMOCD permitted disposal facility.
- 7) Mud laden fluids must be placed between all cement plugs mixed at 25 sacks of salt gel per 100 barrels of brine.
- All cement plugs will be 100' or 25 sacks cement, whichever is greater. Class 'C' cement will be used above 7500' and Class 'H' below 7500'. Plugs should be no more than 3000' apart
- 9) Site remediation due within one year of well plugging completion.