Form 3160-5	-5 UNITED STATES					FORM APPROVED OMB No. 1004-0137	
(June 2015)		NITED STATES Hobbs			Expires: January 31, 2018		
BUREAU OF LAND MANAGEMENT						5. Lease Serial No. NMLC063916	
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or 7	Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on page 2						7. If Unit of CA/Agreement, Name and/or No.	
1. Type of Well Oil Well 🔽 Gas Well 🛄 Other						8. Well Name and No. ELLIOTT FEDERAL #006	
2. Name of Operator Special Energy Corporation						9. API Well No. 30-025-34452	
3a. AddressPO Drawer 3693b. Phone No. (include area code)Stillwater, OK 74076(405) 377-1177						10. Field and Pool or Exploratory Area [83810] RHODES;YATES-SEVEN RIVERS (GAS)	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) I-17-26S-37E 1650 FSL 660 FEL						11. Country or Parish, State Lea County, NM	
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOT							
TYPE OF SUBMISSION TYPE OF ACTION							
	51011	Acidize	Deep			luction (Start/Resume)	Water Shut-Off
✓ Notice of Intent		Alter Casing	= .	aulic Fracturing		lamation	Well Integrity
Subsequent Report		Casing Repair		Construction	_	omplete	Other
Final Abandonment	Notice	Change Plans		and Abandon Back	Ξ	porarily Abandon er Disposal	
 Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be perfonned or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has detennined that the site is ready for final inspection.) As required by 43 CFR 3100.0-5(a) and 43 CFR 3162.3, we are notifying you of a change of operator on the above referenced lease. Special Energy Corporation, as new operator, accepts all applicable terms, conditions, stipulations, and restrictions concerning operations conducted on the lease described. Special Energy Corporation meets federal bonding requirements as follows (43 CFR 3104): 							
BLM Bond File No.: NMB001116 Surety Bond No.: RLB0015342							
Effective Date: Octo Special Energy Cor P.O. Drawer 369 Stillwater, OK 74070	poration	and to I		nox.	SEI CO	E ATTACHI NDITIONS	ED FOR OF APPROVAL
14. I hereby certify that the Don Terry	foregoing is	true and correct. Name (Prin	- Y Y Y ned Typed)	Operation Title	ns Manage	er	
Signature	nte			Date		07/06/20	17
THE SPACE FOR FEDERAL OR STATE OFICE USE							
Approved by Conditions of approval, if any are attacted, approval of this police does not warrant or contribute the applicant holds legal or equitable attacted in the subject lease which would entitle the applicant to conduct operations therport							
Title 18 U.S.C Section 1001 and Title 43 U.S.C Section 12/2, make it a crime for any person knowingly and willfully to make to any department of agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. ROSWELL FIELD OFFICE							
(Instructions on page	2)						

Change of Operator Conditions of Approval

- 1. Tank battery must be bermed/diked (must be able to contain 1 1/2 times the volume of the largest tank).
- 2. Submit for approval of water disposal method.
- 3. Submit updated facility diagrams as per Onshore Order #3
- 4. This agency shall be notified of any spill or discharge as required by NTL-3A.
- 5. All outstanding environmental issue must be addressed within 90 days. Contact Jim Amos for inspection and to resolve environmental issues. 575-234-5909
- 6. Install legible well sign on location with operator name, well name and number, lease number, unit number, 1/4 1/4, section, township, and range. NMOCD requires the API number on well signs.
- 7. Subject to like approval by NMOCD.
- 8. All Reporting to ONRR (OGOR Reports) must be brought current within 30 days of this approval including any past history.
- 9. If this well is incapable of producing in paying quantities submit NOI to plug and abandon this well or obtain approval to do otherwise within 90 days.
- 10. Submit plan for approval of well operations for all TA/SI wells within 30 days of this approval to change operator.
- 11. If not in place acquire operating rights on this lease within 30 days with BLM office in Santa Fe, NM.

JAM 043019