UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

-	
	Lease Serial No.
•	
	NIMI COSSIDA

SUNDRY	5. Lease Serial No. NMLC032104						
abandoned wel	6. If Indian, Allottee or Tribe Name						
SUBMIT IN T	NOTICES AND REPOIS form for proposals to i. Use form 3160-3 (API	ructions on	page 2	MAY	9 2019 CEI	. If Unit or CA/Agree	ement, Name and/or No.
1. Type of Well Gas Well Gas Well Oth			•	RECE	8. Well Name and No.	EDERAL NCT-1 B3 25	
Name of Operator CHEVRON USA INCORPORA	NICK GLANN CHEVRON.C				9. API Well No. 30-025-21403-0	00-C1	
3a. Address 6301 DEAUVILLE BLVD MIDLAND, TX 79706		3b. Phone No. (include area code) Ph: 661-599-5062				10. Field and Pool or Exploratory Area BRUNSON TUBB OIL & GAS	
4. Location of Well (Footage, Sec., T	, R., M., or Survey Description,)		•	· · · · · · ·	11. County or Parish,	State
Sec 28 T22S R38E SESW 66					LEA COUNTY,	NM .	
12. CHECK THE A	PROPRIATE BOX(ES)	TO INDICA	TE NATU	IRE OF	NOTICE,	, REPORT, OR OTH	IER DATA
TYPE OF SUBMISSION			T	YPE OF	ACTION		
Notice of Intent $\sqrt{2}$	☐ Acidize	☐ Dee	pen		☐ Produc	tion (Start/Resume)	☐ Water Shut-Off
_	□ Alter Casing	☐ Hyd	traulic Frac	turing	☐ Reclam	ation	■ Well Integrity
☐ Subsequent Report	□ Casing Repair	□ Nev	v Construct	ion	☐ Recom	plete	Other
☐ Final Abandonment Notice	□ Change Plans	🛛 Plug	g and Aban	don	☐ Tempo	rarily Abandon	
i	Convert to Injection	Plug	Plug Back		☐ Water l	iter Disposal	
13. Describe Proposed or Completed Ope If the proposal is to deepen direction: Attach the Bond under which the wor following completion of the involved testing has been completed. Final At determined that the site is ready for final Notify BLM 24 hours prior to 2. MIRU rig, pull rods & pull 2. Run CBL in both the West & 4. MIRU coil unit	ally or recomplete horizontally, k will be performed or provide operations. If the operation remandonment Notices must be fill all inspection. MIRU in accordance with 1/16? tubing from the Weak East strings and discuss	give subsurface the Bond No. or sults in a multiple ed only after all th applicable est string, RD s results with	locations am n file with Bi le completion requirements COAS MO BLM & C\	d measure LM/BIA. n or recon s, includir	ed and true vi Required sumpletion in a ng reclamation	ertical depths of all pertin beequent reports must be new interval, a Form 316 in, have been completed a SEE ATTACHE CONDITIONS	nent markers and zones. filed within 30 days 0-4 must be filed once and the operator has
 Spot 205 sx CL C cmt in W 6612? t/ 3000?, depending on Tubb, Blineberry, Glorieta, Sa for 10 minutes Spot 75 sx CL C cmt into th (Yates, B. Salt). WOC & tag Perf & squeeze 365 sx CL (1452? (Yates, B. Salt). WOC 	CBL results on TOC? ments and the control of the co	eatch internal & tag. Press ot pass the pr	TOC to ex sure test e essure tes	dernal T ach strir at f/ 3000	FOC (Drinking to 500 p	kard, osi	
14. I hereby certify that the foregoing is	# Electronic Submission For CHEVRON	USA INCORP	DRATED,	sent to t	the Hobbs	•	= = - = - = - = - = - = - = - = - =
Committed to AFMSS for processing by PRIS						(19PP1372SE)	
Name (Printed/Typed) NICK GLANN				OW FIN	GINEER		

	For CHEVRON USA INCO Committed to AFMSS for processing by F	RPORATE	D. sent to the Hobbs	SE)
Name (Printed/T)	yped) NICK GLANN	Title	P&A ENGINEER	
Signature	(Electronic Submission)	Date	03/19/2019	
	THIS SPACE FOR FEDE	RAL OR	STATE OFFICE USE	
Approved By	James a. amo	Title	SYET	3-30-/ Date
certify that the applica	If it any, are attached. Approval of this notice does not warrant in tholds legal or equitable title to those rights in the subject least the applicant to conduct operations thereon.	or e Offic	· NFO	

Title 8 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any Talse, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2) ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **

X7 NMOCD 6-3-19

FOR RECORD ONLY

Additional data for EC transaction #458568 that would not fit on the form

32. Additional remarks, continued

8. Cut & pull the tubing string that did not pass the pressure test @ 1452?
9. Cut the tubing string that did pass the pressure test @ 1452? and use to lay 495 sx CL C cmt f/ 1452? t/ surface (T. Salt, Shoe, Rustler, Fresh Water)
10. Verify cement to surface

Current Well ID Info: Location: Wellbore Diagram 660' FSL & 1650' FWL Chevno: FF4757 API No: 30-025-21403 Section: 28 (SE/4 SW/4) L5/L6: U47 / 6800 / 7100 Township: 22S Range: 38E Unit: N Spud Date: 4/21/65 Rig Released: 5/12/65 County: Lea State: NM Compl. Date: 5/17/65 Surface Csg: 8 5/8" 17# Set: @ 1402 w/ 600 sx cmt Elevations: GL: 3360 Hole Size: 11" TO 1402 KB: 3374 Circ: Yes TOC: Surface TOC By: Circulation DF: 3373 Log Formation Tops Rustler 1340 1420 Salt 2586 B/Salt 2720 Yates 3558 Queen San Andres 4153 5343 Glorieta Blinebry 5740 6297 Tubb Drinkard 6624 ?? PMP & RODS PULLED IN 11/2004 Initial Completion: 5/65 (Drinkard) perf (2jspf) 6870, 6900, 34, 52, 82, 7051, 67, 78, 89, 96 7102, 05, 35, 37, 50, 82, 91, 7223; A/10000 gal 15% NE 6643-45, 6647-49, 6652-56, 6663-67, 6679-83, 6701-06; A/1000 gal 6/65 (Tubb) perf (1jspf) 6298, 6303, 24, 33, 37, 57, 71, 84, 88, 6404; A/1500 gal 15% NE ; F/15000 gal lease crude & 15000 lbs sd Subsequent Work 12/69 DHC Tubb - Drinkard Perf 6557-62 w/spiral pattern gun to communicate Tubb & Drinkard zones bg Detail: 11/29/2004 (WEST STRING) Administration Order No. : DHC-9 (Tubb : 20%; Drinkard : 80%) 20 JTS 2 1/16" 2.66# INTEGRAL 1.751ID 1.719 DRIFT 7143.7 1/81 (Drinkard) A/1500 gal 15% NEFE; (Commingle Perfs) A/50 gal - 2 1/16" MA 33.3 15% NEFE ; (Tubb) A/1000 gal 15% NEFE - 2 1/16" CUP TYPE SN 7144.8 EOT 3/81 Perf (Drinkard string) 6398-6404 w/10 spiral gun shots to increase commingling; A/Drinkard 6870-7223 w/1500 gal 15% NEFE Ε RA Collar @ 6223 producer vent Perfs Status 6298, 6303, 24, 33, 37, 57, 71, 84, 88, 6404 Tubb - open 6398-6404 Commingling Perfs **-**6557-62 Commingling Perfs String 1: 2 7/8" 6.5# J-55 @ 7245 (east) String 2: 2 7/8" 6.5# J-55 @ 7248 (west) Cmt: 1000 sx each string

TD: 7250 COTD: 7242 PBTD: 7242 COTD: 6612 PBTD: 6612

Updated: 8/23/2012 SEHE

Hole Size: 7 7/8" to 7250 Circ: No TOC: 3000 TOC By: Calculated @ 80% fill up

By: S E HEIDELBERG

6870, 6900, 34, 52, 82, 7051, 67, 78, 89, 96,

7102, 05, 35, 37, 50, 82, 91, 7223

Drinkard - open

Drinkard - open

Well: A. H. Blinebry Federal NCT-1 #25

Field: Tubb Oil & Gas Reservoir: DHC - TUBB/DRINKARD ABO

Location:

660' FSL & 1650' FWL

Section: 28 (SE/4 SW/4) Township: 22S Range: 38E Unit: N County: Lea State: NM

Elevations:

GL: 3360 KB: 3374 DF: 3373

Log Formation Tops				
Rustler	1340			
Salt	1420			
B/Salt	2586			
Yates	2720			
Queen	3558			
San Andres	4153			
Glorieta	5343			
Blinebry	5740			
Tubb	6297			
Drinkard	6624			


?? PMP & RODS PULLED IN 11/2004



bg Detail: 11/29/2004 (WEST STRING) 20 JTS 2 1/16" 2.66# INTEGRAL 1.751ID 1.719 7143.7

- 2 1/16" MA - 2 1/16" CUP TYPE SN EOT

33.3 7144.8



String 1: 2 7/8" 6.5# J-55 @ 7245 (east)

String 2: 2 7/8" 6.5# J-55 @ 7248 (west)

Cmt: 1000 sx each string Hole Size: 7 7/8" to 7250

Circ: No TOC: 3000 TOC By: Calculated @ 80% fill up

Proposed Wellbore Diagram



Well ID Info:

Chevno: FF4757 API No: 30-025-21403 L5/L6: U47 / 6800 / 7100 Spud Date: 4/21/65 Rig Released: 5/12/65 Compl. Date: 5/17/65

Surface Csg: 8 5/8" 17# Set: @ 1402 w/ 600 sx cmt Hole Size: 11" TO 1402 Circ: Yes TOC: Surface TOC By: Circulation

Cut tubing string that did pass pressure test @ 1452' & use to lay 495 sx CL C cmt f/ 1452' t/ surface (T. Salt, Shoe, Rustler, Fresh Water)

Cut & pull tubing string that did not pass pressure test @ 1452*

Perf & squeeze 365 sx CL C cmt into tubing string that did pass pressure test f/ ~3000' t/ 1452' (Yates, B. Salt). WOC & tag

Spot 75 sx CL C cmt into tubing string that did not pass pressure test f/ ~3000' t/ 1452' (Yates, B. Sait). WOC & tag

Spot 175 sx CL C cmt in East string f/ 6612' t/ ~3000' and 205 sx CL C cmt in West string f/ 7242' t/ ~3000', depending on CBL results on TOC match it to external TOC. (Drinkard, Tubb, Blineberry, Glorieta, San Andres, Queen). WOC & tag. Pressure test each string t/ 500 psi

RA Collar @ 6223 Perfs

6298, 6303, 24, 33, 37, 57, 71, 84, 88, 6404 6398-6404

Tubb - open **Commingling Perfs**

Status

√6557-62

Commingling Perfs

6870, 6900, 34, 52, 82, 7051, 67, 78, 89, 96, 7102, 05, 35, 37, 50, 82, 91, 7223

Drinkard - open Drinkard - open

TD: 7250 COTD: 7242 PBTD: 7242 COTD: 6612 PBTD: 6612

Updated: 8/23/2012 SEHE

By: S E HEIDELBERG

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.