Office	ate of New Mexico	Form C-103
Finerov Mil	nerals and Natural Resources	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240 District II - (575) 748-1283 811 S. First St., Artesia, NM 188240 District III - (505) 334-6178 1000 Rip Brazos Rd Aztec, NM 87410 1 3 2019		WELL API NO. 30-025-12493
811 S. First St., Artesia, NR 182 18 OIL CON	SERVATION DIVISION	5. Indicate Type of Lease
District III - (505) 334-6178 1220	South St. Francis Dr.	STATE X FEE
<u> </u>	nta Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505 SUNDREFEES AND REPOR		
SUNDRY CES AND REPOR	RTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT		North Hobbs G/SA Unit
PROPOSALS.)		8. Well Number 241
1. Type of Well: Oil Well X Gas Well Ot	her	
Name of Operator Occidental Permian LTD		9. OGRID Number 157984
3. Address of Operator		10. Pool name or Wildcat
PO Box 4294 Houston, TX 77210		Hobbs; (G/SA)
4. Well Location		
	om the S line and	2310 feet from the W line
	hip 18S Range 38E	NMPM County Lea
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3652' GL		
3652 G	<u> </u>	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ARANDON CHANCE BLANCE BLANCE OF COMMENCE DRILLING ORDIS READING		
TEMPORARILY ABANDON		
DOWNHOLE COMMINGLE		
CLOSED-LOOP SYSTEM	_ 1	_
OTHER.		
OTHER:	OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and	
13. Describe proposed or completed operations. (of starting any proposed work). SEE RULE 1	Clearly state all pertinent details, and	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and	
 Describe proposed or completed operations. (of starting any proposed work). SEE RULE 1 proposed completion or recompletion. 	Clearly state all pertinent details, and 9.15.7.14 NMAC. For Multiple Cor	mpletions: Attach wellbore diagram of
 Describe proposed or completed operations. (of starting any proposed work). SEE RULE 1 proposed completion or recompletion. 4/2/19: MIRU x NDWH x NUBOP. POOH 115 jts 	Clearly state all pertinent details, and 9.15.7.14 NMAC. For Multiple Cor	mpletions: Attach wellbore diagram of 4 1/8 bit x tagged @ 4330'.
 13. Describe proposed or completed operations. (of starting any proposed work). SEE RULE 1 proposed completion or recompletion. 4/2/19: MIRU x NDWH x NUBOP. POOH 115 jts 4/3/19: RIH 5"cibp @ 4300' x dumped 35' of peratical starting in the starting in t	Clearly state all pertinent details, and 9.15.7.14 NMAC. For Multiple Con 2 7/8 tbg x esp equipment. RIH 4 ga gravel x 5' of cmt on cibp. Tage	npletions: Attach wellbore diagram of 4 1/8 bit x tagged @ 4330'. ged TOC @ 4215'. RIH 5" cicr @ 4100'.
 13. Describe proposed or completed operations. (of starting any proposed work). SEE RULE 1 proposed completion or recompletion. 4/2/19: MIRU x NDWH x NUBOP. POOH 115 jts 4/3/19: RIH 5"cibp @ 4300' x dumped 35' of pe 4/4/19: Pumped 50 sxs thixotropic cmt as a lea 	Clearly state all pertinent details, and 9.15.7.14 NMAC. For Multiple Con 2 7/8 tbg x esp equipment. RIH 4 ea gravel x 5' of cmt on cibp. Tagg d x 30 sxs as a tail to squeeze off	4 1/8 bit x tagged @ 4330'. ged TOC @ 4215'. RIH 5" cicr @ 4100'.
13. Describe proposed or completed operations. (of starting any proposed work). SEE RULE 1 proposed completion or recompletion. 4/2/19: MIRU x NDWH x NUBOP. POOH 115 jts 4/3/19: RIH 5"cibp @ 4300' x dumped 35' of pe 4/4/19: Pumped 50 sxs thixotropic cmt as a lea stung out cicr, x reversed out cmt w/ 40 bbls FV	Clearly state all pertinent details, and 9.15.7.14 NMAC. For Multiple Con 2 7/8 tbg x esp equipment. RIH 4 a gravel x 5' of cmt on cibp. Tage d x 30 sxs as a tail to squeeze off N. 4/5/19 - 4/8/19: Drilled cmt x	4 1/8 bit x tagged @ 4330'. ged TOC @ 4215'. RIH 5" cicr @ 4100'.
 13. Describe proposed or completed operations. (of starting any proposed work). SEE RULE 1 proposed completion or recompletion. 4/2/19: MIRU x NDWH x NUBOP. POOH 115 jts 4/3/19: RIH 5"cibp @ 4300' x dumped 35' of pe 4/4/19: Pumped 50 sxs thixotropic cmt as a lea 	Clearly state all pertinent details, and 9.15.7.14 NMAC. For Multiple Con 2 7/8 tbg x esp equipment. RIH 4 a gravel x 5' of cmt on cibp. Tage d x 30 sxs as a tail to squeeze off N. 4/5/19 - 4/8/19: Drilled cmt x	4 1/8 bit x tagged @ 4330'. ged TOC @ 4215'. RIH 5" cicr @ 4100'.
13. Describe proposed or completed operations. (of starting any proposed work). SEE RULE 1 proposed completion or recompletion. 4/2/19: MIRU x NDWH x NUBOP. POOH 115 jts 4/3/19: RIH 5"cibp @ 4300' x dumped 35' of pe 4/4/19: Pumped 50 sxs thixotropic cmt as a lea stung out cicr, x reversed out cmt w/ 40 bbls FV	Clearly state all pertinent details, and 9.15.7.14 NMAC. For Multiple Con 2 7/8 tbg x esp equipment. RIH 4 a gravel x 5' of cmt on cibp. Tage d x 30 sxs as a tail to squeeze off N. 4/5/19 - 4/8/19: Drilled cmt x	4 1/8 bit x tagged @ 4330'. ged TOC @ 4215'. RIH 5" cicr @ 4100'.
13. Describe proposed or completed operations. (of starting any proposed work). SEE RULE 1 proposed completion or recompletion. 4/2/19: MIRU x NDWH x NUBOP. POOH 115 jts 4/3/19: RIH 5"cibp @ 4300' x dumped 35' of pe 4/4/19: Pumped 50 sxs thixotropic cmt as a lea stung out cicr, x reversed out cmt w/ 40 bbls FV	Clearly state all pertinent details, and 9.15.7.14 NMAC. For Multiple Con 2 7/8 tbg x esp equipment. RIH 4 a gravel x 5' of cmt on cibp. Tage d x 30 sxs as a tail to squeeze off N. 4/5/19 - 4/8/19: Drilled cmt x	4 1/8 bit x tagged @ 4330'. ged TOC @ 4215'. RIH 5" cicr @ 4100'.
13. Describe proposed or completed operations. (of starting any proposed work). SEE RULE 1 proposed completion or recompletion. 4/2/19: MIRU x NDWH x NUBOP. POOH 115 jts 4/3/19: RIH 5"cibp @ 4300' x dumped 35' of pe 4/4/19: Pumped 50 sxs thixotropic cmt as a lea stung out cicr, x reversed out cmt w/ 40 bbls FV	Clearly state all pertinent details, and 9.15.7.14 NMAC. For Multiple Con 2 7/8 tbg x esp equipment. RIH 4 a gravel x 5' of cmt on cibp. Tage d x 30 sxs as a tail to squeeze off N. 4/5/19 - 4/8/19: Drilled cmt x	4 1/8 bit x tagged @ 4330'. ged TOC @ 4215'. RIH 5" cicr @ 4100'.
13. Describe proposed or completed operations. (of starting any proposed work). SEE RULE 1 proposed completion or recompletion. 4/2/19: MIRU x NDWH x NUBOP. POOH 115 jts 4/3/19: RIH 5"cibp @ 4300' x dumped 35' of pe 4/4/19: Pumped 50 sxs thixotropic cmt as a lea stung out cicr, x reversed out cmt w/ 40 bbls FV	Clearly state all pertinent details, and 9.15.7.14 NMAC. For Multiple Con 2 7/8 tbg x esp equipment. RIH 4 a gravel x 5' of cmt on cibp. Tage d x 30 sxs as a tail to squeeze off N. 4/5/19 - 4/8/19: Drilled cmt x	4 1/8 bit x tagged @ 4330'. ged TOC @ 4215'. RIH 5" cicr @ 4100'.
13. Describe proposed or completed operations. (of starting any proposed work). SEE RULE 1 proposed completion or recompletion. 4/2/19: MIRU x NDWH x NUBOP. POOH 115 jts 4/3/19: RIH 5"cibp @ 4300' x dumped 35' of pe 4/4/19: Pumped 50 sxs thixotropic cmt as a lea stung out cicr, x reversed out cmt w/ 40 bbls F\ 4/9/19: RIH 115 jts 2 7/8" tbg @3668' x esp @3	Clearly state all pertinent details, and 9.15.7.14 NMAC. For Multiple Con 2 7/8 tbg x esp equipment. RIH 4 a gravel x 5' of cmt on cibp. Tagg d x 30 sxs as a tail to squeeze off N. 4/5/19 - 4/8/19: Drilled cmt x 3707'. RD x NDBOP x NUWH.	4 1/8 bit x tagged @ 4330'. ged TOC @ 4215'. RIH 5" cicr @ 4100'.
13. Describe proposed or completed operations. (of starting any proposed work). SEE RULE 1 proposed completion or recompletion. 4/2/19: MIRU x NDWH x NUBOP. POOH 115 jts 4/3/19: RIH 5"cibp @ 4300' x dumped 35' of pe 4/4/19: Pumped 50 sxs thixotropic cmt as a lea stung out cicr, x reversed out cmt w/ 40 bbls F\ 4/9/19: RIH 115 jts 2 7/8" tbg @3668' x esp @3	Clearly state all pertinent details, and 9.15.7.14 NMAC. For Multiple Cor. 2 7/8 tbg x esp equipment. RIH 4 ea gravel x 5' of cmt on cibp. Tagg d x 30 sxs as a tail to squeeze off N. 4/5/19 - 4/8/19: Drilled cmt x 3707'. RD x NDBOP x NUWH.	4 1/8 bit x tagged @ 4330'. ged TOC @ 4215'. RIH 5" cicr @ 4100'.
13. Describe proposed or completed operations. (of starting any proposed work). SEE RULE 1 proposed completion or recompletion. 4/2/19: MIRU x NDWH x NUBOP. POOH 115 jts 4/3/19: RIH 5"cibp @ 4300' x dumped 35' of pe 4/4/19: Pumped 50 sxs thixotropic cmt as a lea stung out cicr, x reversed out cmt w/ 40 bbls F\ 4/9/19: RIH 115 jts 2 7/8" tbg @3668' x esp @3	Clearly state all pertinent details, and 9.15.7.14 NMAC. For Multiple Con 2 7/8 tbg x esp equipment. RIH 4 a gravel x 5' of cmt on cibp. Tagg d x 30 sxs as a tail to squeeze off N. 4/5/19 - 4/8/19: Drilled cmt x 3707'. RD x NDBOP x NUWH.	4 1/8 bit x tagged @ 4330'. ged TOC @ 4215'. RIH 5" cicr @ 4100'.
13. Describe proposed or completed operations. (of starting any proposed work). SEE RULE 1 proposed completion or recompletion. 4/2/19: MIRU x NDWH x NUBOP. POOH 115 jts 4/3/19: RIH 5"cibp @ 4300' x dumped 35' of pe 4/4/19: Pumped 50 sxs thixotropic cmt as a lea stung out cicr, x reversed out cmt w/ 40 bbls F\ 4/9/19: RIH 115 jts 2 7/8" tbg @3668' x esp @3	Clearly state all pertinent details, and 9.15.7.14 NMAC. For Multiple Cor. 2 7/8 tbg x esp equipment. RIH 4 ea gravel x 5' of cmt on cibp. Tagg d x 30 sxs as a tail to squeeze off N. 4/5/19 - 4/8/19: Drilled cmt x 8707'. RD x NDBOP x NUWH. Rig Release Date: 4/9/19	A 1/8 bit x tagged @ 4330'. ged TOC @ 4215'. RIH 5" cicr @ 4100'. @ 2500 psi w/ 14 bbls into formation, cibp to TD @ 4330'.
13. Describe proposed or completed operations. (of starting any proposed work). SEE RULE 1 proposed completion or recompletion. 4/2/19: MIRU x NDWH x NUBOP. POOH 115 jts 4/3/19: RIH 5"cibp @ 4300' x dumped 35' of pe 4/4/19: Pumped 50 sxs thixotropic cmt as a lea stung out cicr, x reversed out cmt w/ 40 bbls FV 4/9/19: RIH 115 jts 2 7/8" tbg @3668' x esp @3	Clearly state all pertinent details, and 9.15.7.14 NMAC. For Multiple Cor. 2 7/8 tbg x esp equipment. RIH 4 ea gravel x 5' of cmt on cibp. Tagg d x 30 sxs as a tail to squeeze off N. 4/5/19 - 4/8/19: Drilled cmt x 8707'. RD x NDBOP x NUWH. Rig Release Date: 4/9/19	A 1/8 bit x tagged @ 4330'. ged TOC @ 4215'. RIH 5" cicr @ 4100'. @ 2500 psi w/ 14 bbls into formation, cibp to TD @ 4330'.
13. Describe proposed or completed operations. (of starting any proposed work). SEE RULE 1 proposed completion or recompletion. 4/2/19: MIRU x NDWH x NUBOP. POOH 115 jts 4/3/19: RIH 5"cibp @ 4300' x dumped 35' of pe 4/4/19: Pumped 50 sxs thixotropic cmt as a lea stung out cicr, x reversed out cmt w/ 40 bbls FV 4/9/19: RIH 115 jts 2 7/8" tbg @3668' x esp @3 Spud Date: 4/2/19 I hereby certify that the information above is true and completed operations. (A/2/19	Clearly state all pertinent details, and 9.15.7.14 NMAC. For Multiple Cor. 2 7/8 tbg x esp equipment. RIH 4 a gravel x 5' of cmt on cibp. Tagg d x 30 sxs as a tail to squeeze off N. 4/5/19 - 4/8/19: Drilled cmt x 3707'. RD x NDBOP x NUWH. Rig Release Date: 4/9/19	### Attach wellbore diagram of the street of
13. Describe proposed or completed operations. (of starting any proposed work). SEE RULE 1 proposed completion or recompletion. 4/2/19: MIRU x NDWH x NUBOP. POOH 115 jts 4/3/19: RIH 5"cibp @ 4300' x dumped 35' of pe 4/4/19: Pumped 50 sxs thixotropic cmt as a lea stung out cicr, x reversed out cmt w/ 40 bbls FV 4/9/19: RIH 115 jts 2 7/8" tbg @3668' x esp @3 Spud Date: 4/2/19 I hereby certify that the information above is true and completed operations. (SIGNATURE AND SEE RULE 1 Proposed work). Se	Clearly state all pertinent details, and 9.15.7.14 NMAC. For Multiple Cor. 2 7/8 tbg x esp equipment. RIH 4 ea gravel x 5' of cmt on cibp. Tagg d x 30 sxs as a tail to squeeze off N. 4/5/19 - 4/8/19: Drilled cmt x 8707'. RD x NDBOP x NUWH. Rig Release Date: 4/9/19 omplete to the best of my knowledge TITLE Regulatory Specialist	A 1/8 bit x tagged @ 4330'. ged TOC @ 4215'. RIH 5" cicr @ 4100'. ged TOT @ 4330'. ged TOT @ 4330'. ged TOT @ 4330'. a 2500 psi w/ 14 bbls into formation, cibp to TD @ 4330'.
13. Describe proposed or completed operations. (of starting any proposed work). SEE RULE 1 proposed completion or recompletion. 4/2/19: MIRU x NDWH x NUBOP. POOH 115 jts 4/3/19: RIH 5"cibp @ 4300' x dumped 35' of pe 4/4/19: Pumped 50 sxs thixotropic cmt as a lea stung out cicr, x reversed out cmt w/ 40 bbls FV 4/9/19: RIH 115 jts 2 7/8" tbg @3668' x esp @3 Spud Date: 4/2/19 I hereby certify that the information above is true and completed operations. (SIGNATURE April Hood	Clearly state all pertinent details, and 9.15.7.14 NMAC. For Multiple Cor. 2 7/8 tbg x esp equipment. RIH 4 a gravel x 5' of cmt on cibp. Tagg d x 30 sxs as a tail to squeeze off N. 4/5/19 - 4/8/19: Drilled cmt x 3707'. RD x NDBOP x NUWH. Rig Release Date: 4/9/19	A 1/8 bit x tagged @ 4330'. ged TOC @ 4215'. RIH 5" cicr @ 4100'. ged TOT @ 4330'. ged TOT @ 4330'. ged TOT @ 4330'. a 2500 psi w/ 14 bbls into formation, cibp to TD @ 4330'.
13. Describe proposed or completed operations. (of starting any proposed work). SEE RULE 1 proposed completion or recompletion. 4/2/19: MIRU x NDWH x NUBOP. POOH 115 jts 4/3/19: RIH 5"cibp @ 4300' x dumped 35' of pe 4/4/19: Pumped 50 sxs thixotropic cmt as a lea stung out cicr, x reversed out cmt w/ 40 bbls FV 4/9/19: RIH 115 jts 2 7/8" tbg @3668' x esp @3 Spud Date: 4/2/19 I hereby certify that the information above is true and completed operations. (SIGNATURE Applied To See The See	Clearly state all pertinent details, and 9.15.7.14 NMAC. For Multiple Cor. 2 7/8 tbg x esp equipment. RIH 4 ea gravel x 5' of cmt on cibp. Tagg d x 30 sxs as a tail to squeeze off N. 4/5/19 - 4/8/19: Drilled cmt x 8707'. RD x NDBOP x NUWH. Rig Release Date: 4/9/19 omplete to the best of my knowledge TITLE Regulatory Specialist	A 1/8 bit x tagged @ 4330'. ged TOC @ 4215'. RIH 5" cicr @ 4100'. ged TOT @ 4330'. ged TOT @ 4330'. ged TOT @ 4330'. a 2500 psi w/ 14 bbls into formation, cibp to TD @ 4330'.
13. Describe proposed or completed operations. (of starting any proposed work). SEE RULE 1 proposed completion or recompletion. 4/2/19: MIRU x NDWH x NUBOP. POOH 115 jts 4/3/19: RIH 5"cibp @ 4300' x dumped 35' of pe 4/4/19: Pumped 50 sxs thixotropic cmt as a lea stung out cicr, x reversed out cmt w/ 40 bbls FV 4/9/19: RIH 115 jts 2 7/8" tbg @3668' x esp @3 Spud Date: 4/2/19 I hereby certify that the information above is true and completed operations. (SIGNATURE April Hood	Clearly state all pertinent details, and 9.15.7.14 NMAC. For Multiple Cor. 2 7/8 tbg x esp equipment. RIH 4 ea gravel x 5' of cmt on cibp. Tagg d x 30 sxs as a tail to squeeze off N. 4/5/19 - 4/8/19: Drilled cmt x 8707'. RD x NDBOP x NUWH. Rig Release Date: 4/9/19 omplete to the best of my knowledge TITLE Regulatory Specialist	A 1/8 bit x tagged @ 4330'. ged TOC @ 4215'. RIH 5" cicr @ 4100'. ged TOT @ 4330'. ged TOT @ 4330'. ged TOT @ 4330'. a 2500 psi w/ 14 bbls into formation, cibp to TD @ 4330'.