
Submit 1 Copy To Appropriate District	State of New Mexico	Form C-103
Office <u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Resources	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240 District II - (575) 748-1283		WELL API NO. 30-025-30950
811 S. First St., Artesia, NM 88210	OIL CONSERVAT HO B ÍTISI OIC	5. Indicate Type of Lease
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE X FEE
District IV - (505) 476-3460	Santa Fe, NM SE 0\$ 3 2019	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	STR. STR. Co. Location or community	
SUNDRY NOTICES AND REPORTS ON WEIR ECEIVED		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		J.F.JANDA (NCT-D)
PROPOSALS.)		
1. Type of Well: Oil Well X Gas Well Other		8. Well Number 6
2. Name of Operator XTO Energy, Inc		9. OGRID Number 5380
3. Address of Operator 6401 Holiday Hill, Rd #5		10. Pool name or Wildcat
Midland, Tx 79707		OIL CENTER GLORIETA
4. Well Location		
Unit Letter T: 1660 feet from the South line and 530 feet from the WEST line		
Section 2	Township 21S Range 36E	County Lea
	11. Elevation (Show whether DR, RKB, RT, GR, etc.	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING		
TEMPORARILY ABANDON		
PULL OR ALTER CASING		
DOWNHOLE COMMINGLE		
CLOSED-LOOP SYSTEM OTHER:	☐ OTHER:	П
	leted operations. (Clearly state all pertinent details, ar	nd give pertinent dates, including estimated date
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of		
proposed completion or recompletion.		
XTO Energy, Inc. respectfu API: 3002530950	Ily requests to PA the above referenced well.	pressure test casing
Set CIBP @ 5,152' with 35' of Cement. WOC. Tag TOC @5,115';		- C:RC MLF
Spot a 25 3x3 balanced plug nom 4,124 to 5,572. WOC. Tag TOC @5,572,		
Spot a 25 sxs balanced plug from 3,384' to 2,934'. WOC. Tag TOC @2,934';		
Spot a 25 sxs balanced plug from 2,724' to 2,474'. WOC. Tag TOC @2,474'; Perf @1,353'; Spot a 25 sxs balanced plug from 1,403' to 1,153'. WOC. Tag TOC @1,153';		
Perf @601'; Spot plug circ to Surface.		
CUT & CAP Well 3' BELOW	GROUND LEVEL AND INSTALL P&A MARKER.	
See Attached		
		See Attached Conditions of Approval
		Conditions of Approv
Spud Date:	Rig Release Date:	Jones
I hereby certify that the information	above is true and complete to the best of my knowled	ge and belief.
SIGNATURE COOOL WO	TITLE Regulatory Analyst	DATE 09/19/19
DATE TO COMPONIE THE INCOME OF THE PROPERTY OF		
Type or print name Cassie Evans E-mail address: cassie evans@xtoenergy.com PHONE: 432.218.3671		
For State Use Only		
APPROVED BY: Kerry Forter TITLE C. O. A DATE 9-2 4-19		
APPROVED BY: New Jork TITLE C. (), H DATE 1-27-17 Conditions of Approval (if any):		



GENERAL CONDITIONS OF APPROVAL:

- 1) Insure all bradenheads have been exposed, identified, and valves are operational prior to rigging up on well.
- 2) Contact the appropriate NMOCD District Office no later than 24 hours prior to moving in and rigging up.
- 3) A copy of the approved C103 intent to P&A should be distributed to the onsite company and plugging representatives. Approved procedures are good for a period of one year from approved date, unless otherwise specified on the C103 intent. Approvals past this date will require the submission and approval of a new C103 intent.
- 4) A company representative is required to be present to witness all operations including setting CIBP's, circulation of mud laden fluids, perforating, squeezing or spotting cement plugs, tags, or any other operations approved on the C103 intent to P&A. Company representative should contact the NMOCD and report all operations.
- 5) Any changes that may be required during plugging operations should be approved by the NMOCD before proceeding.
- 6) A closed loop system is to be used for all plugging operations. Contents of the steel pits to be hauled to a NMOCD permitted disposal facility.
- 7) Mud laden fluids must be placed between all cement plugs mixed at 25 sacks of salt gel per 100 barrels of brine.
- 8) All cement plugs will be 100' or 25 sacks cement, whichever is greater. Class 'C' cement will be used above 7500' and Class 'H' below 7500'. Plugs should be no more than 3000' apart
- 9) Site remediation due within one year of well plugging completion.