
Submit 1 Copy To Appropriate District Office	State of New Mexico		Form C-103
<u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Resources		Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240 District II - (575) 748-1283			WELL API NO. 30-025-41771
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION		5. Indicate Type of Lease
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr. Santa Fe, NM 87500CD		STATE Z FEE
District IV - (505) 476-3460	Santa Fe, NM 8250		6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	Dr., Santa Fe, NM		
SUNDRY NOTICES AND REPORTS IN WELLS 1 2019			7. Lease Name or Unit Agreement Name
			Big Eddy Unit DI 29
PROPOSALS.) 1. Type of Well: Oil Well	PROPOSALS TO DRILL OR TO DEEPEN OR PLUB BACK TO A APPLICATION FOR PERMIT" (FORM C- TON FOR SUCH Gas Well Cother		8. Well Number 320H
2. Name of Operator	ame of Operator		9. OGRID Number
XTO Permian Operating, LLC. 3. Address of Operator		373075 10. Pool name or Wildcat	
· ·			Wildcat; Bone Spring
6401 Holiday Hill Road, Bldg 5 Midland, Texas 79707 4. Well Location			wildcat, Bone Spring
Unit Letter M : 330 feet from the South line and 330 feet from the West line			
Section 16	Township 20S Ran		NMPM County Eddy Lea
10	11. Elevation (Show whether DR,		
3513 GL			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB PAND A DOWNHOLE COMMINGLE COMENCE DRILLING OPNS. P AND A CASING/CEMENT JOB COSED-LOOP SYSTEM OTHER: Image: Completed operations. CClearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. XTO Permian Operating, LLC respectfully submits for plug and abandon of the subject well with the below procedure. A proposed WBD is attached. 1. Tag PBTD to verify depth at ~4.543. Cag w/25x cmt. WOC. Tag. Circulate 9.5# salt gel mud. Pressure test to 500psi. 2. PUH w/ tbg to 3.070. Spot 35 xs Class C cmt to ensure plug top is 2.950' or above. WOC & Tag. 3. PUH w/ tbg to 2.470'. Spot 420 xs Class C cmt to ensure plug top is 2.950' or above. WOC & Tag. 4. POOH w/ tbg. RU & RIH WL to 60' and perf 9-58' casing. Sqz 30 xsx Class C cmt and ensure top is at surface inside and outside all strings of casing. WOC & Tag. 5. Cut off WH, Install Belowgrade Dry Hole Marker. Dry hole marker requested due to drill island and future activity in the area. See Atttached <t< th=""></t<>			
			Conditions of Approx
Spud Date:	Rig Release Date	:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE Auphanie Rabadul TITLE Permitting Lead DATE 10/01/2019			
Type or print name <u>Stephanie Rabadue</u> E-mail address: <u>stephanie_rabadue@xtoener</u> PHONE: <u>432-620-6714</u> For State Use Only			
APPROVED BY: <u>Yeary</u> Conditions of Approval (if any):	nte TITLE C. O.	A	DATE 10-9-19



Big Eddy Unit DI29 #320 Current and Proposed WBD's

GENERAL CONDITIONS OF APPROVAL:

- 1) Insure all bradenheads have been exposed, identified, and valves are operational prior to rigging up on well.
- 2) Contact the appropriate NMOCD District Office no later than 24 hours prior to moving in and rigging up.
- 3) A copy of the approved C103 intent to P&A should be distributed to the onsite company and plugging representatives. <u>Approved procedures are good for a period of one year from approved date, unless otherwise specified on the C103 intent</u>. Approvals past this date will require the submission and approval of a new C103 intent.
- 4) A company representative is required to be present to witness all operations including setting CIBP's, circulation of mud laden fluids, perforating, squeezing or spotting cement plugs, tags, or any other operations approved on the C103 intent to P&A. Company representative should contact the NMOCD and report all operations.
- 5) Any changes that may be required during plugging operations should be approved by the NMOCD before proceeding.
- 6) A closed loop system is to be used for all plugging operations. Contents of the steel pits to be hauled to a NMOCD permitted disposal facility.
- 7) Mud laden fluids must be placed between all cement plugs mixed at 25 sacks of salt gel per 100 barrels of brine.
- All cement plugs will be 100' or 25 sacks cement, whichever is greater. Class 'C' cement will be used above 7500' and Class 'H' below 7500'. Plugs should be no more than 3000' apart
- 9) Site remediation due within one year of well plugging completion.