

| Submit 1 Copy To Appropriate District State of New Mexico | Form C-103 |
|--|--|
| District I– (575) 393-6161Energy, Minerals and Natural Resources1625 N. French Dr., Hobbs, NM 88240District II– (575) 748-1283Bill S. First St., Artesia, NM 88210OIL CONSERVATIONDistrict III– (505) 334-61781220 South St. Francis Dr. 2019 | Revised July 18, 2013 WELL API NO. 30-025-31785 5. Indicate Type of Lease |
| District IV = $(505) 476-3460$ Santa Fe, NM 8/000 | 6. State Oil & Gas Lease No. |
| 1220 S. St. Francis Dr., Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELL RECEIVED (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH | 7. Lease Name or Unit Agreement Name Central Vacuum Unit |
| PROPOSALS.) 1. Type of Well: Oil Well 🖾 Gas Well 🗌 Other | 8. Well Number 222 |
| 2. Name of Operator | 9. OGRID Number |
| Chevron USA INC. 3. Address of Operator 6301 Deauville BLVD, Midland, TX 79706 | 4323 10. Pool name or Wildcat Vacuum; Grayburg, San Andres |
| 4. Well Location | |
| Unit Letter K : South feet from the 2522 line and 2283 feet from the West line Section of Township 17S Range 34E NMPM | |
| West line Section 25 Township 17S Range 34E NMPM I1. Elevation (Show whether DR, RKB, RT, GR, etc.) | |
| | |
| 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPL | |
| | |
| CLOSED-LOOP SYSTEM | |
| 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 8-5/8 @ 1550 TOC Surface, 5-1/2 @ 6300' TOC Surface | |
| Chevron USA INC respectfully request to abandon this well as follows: 1.Call and notify NMOCD 24 hrs before operations begin. 2.MIRU CTU, TIH and tag CIBP cement cap at 4,359'. 3.Spot 90 sx CL "C" cmt f/ 4359't/ 3540', do not WOC & tag if casing passed a pressure test (perfs, Queen,Grayburg,San Andres) 4.Spot 70 sx of Class C CMT f/ 32130' t/ 2576 ' (Tansil,Yates,Seven Rivers). 5.Spot 200 sx f/1742't/ Suface' (Santa Rosa, Tecovas,Dewey Lake,Rustler,Salt,Shoe). 6. RD CTU and move out. 7.Cut all casings & anchors & remove 3' below grade. Verify cement to surface & weld on dry hole marker as per, NMOCDrequirements | |
| See Attached Conditions of Approval | |
| I hereby certify that the information above is true and complete to the best of my knowledge | e and belief. |
| SIGNATURE | anager DATE 9/27/2019 |
| Type or print name Ricky Villanueva E-mail address: ryqg@chevro | |
| APPROVED BY: <u>Xerry</u> forther TITLE C. O. A Conditions of Approval (if app): | DATE 10-9-19 |
| | |

CURRENT WELLBORE DIAGRAM



CURRENT WELLBORE DIAGRAM



GENERAL CONDITIONS OF APPROVAL:

- 1) Insure all bradenheads have been exposed, identified, and valves are operational prior to rigging up on well.
- 2) Contact the appropriate NMOCD District Office no later than 24 hours prior to moving in and rigging up.
- 3) A copy of the approved C103 intent to P&A should be distributed to the onsite company and plugging representatives. <u>Approved procedures are good for a period of one year from approved date, unless otherwise specified on the C103 intent</u>. Approvals past this date will require the submission and approval of a new C103 intent.
- 4) A company representative is required to be present to witness all operations including setting CIBP's, circulation of mud laden fluids, perforating, squeezing or spotting cement plugs, tags, or any other operations approved on the C103 intent to P&A. Company representative should contact the NMOCD and report all operations.
- 5) Any changes that may be required during plugging operations should be approved by the NMOCD before proceeding.
- 6) A closed loop system is to be used for all plugging operations. Contents of the steel pits to be hauled to a NMOCD permitted disposal facility.
- 7) Mud laden fluids must be placed between all cement plugs mixed at 25 sacks of salt gel per 100 barrels of brine.
- 8) All cement plugs will be 100' or 25 sacks cement, whichever is greater. Class
 'C' cement will be used above 7500' and Class 'H' below 7500'. Plugs should be no more than 3000' apart
- 9) Site remediation due within one year of well plugging completion.