
Submit 1 Copy To Appropriate District State of New Mexico	Form C-103
District 1 – (575) 393-6161 Energy, Minerals and Natural Coorces	Revised August 1, 2011 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283	30-005-29019
811 S. First St., Artesia, NM 88210 OIL CONSERVAL OF DIV	5. Indicate Type of Lease
District III – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	STATE X FEE
District IV – (505) 476-3460 Santa Fe, NM 83505	6. State Oil & Gas Lease No.
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505 SUDIDRY NOTICES AND REPORTS ON WELLS	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	~
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	SARATOGA 30 STATE COM
1. Type of Well: Oil Well X Gas Well Other	8. Well Number
2. Nome of Operator	001
2. Name of Operator CIMAREX ENERGY CO. OF COLORADO	9. OGRID Number 162683
3. Address of Operator	102005 10. Pool name or Wildcat
600 N. MARIENFELD, SUITE 600, MIDLAND, TEXAS 79701	ABO; WILDCAT
4. Well Location	
Unit Letter E : 1980 feet from the NORTH line and 990 feet from the WEST line	
	1E NMPM CHAVES County
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	.
4,450' – GR	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
A Diversity of the second se	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK 🔲 PLUG AND ABANDON 🗴 📻 REMEDIAL WORK 📃 ALTERING CASING 🗌	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT	JOB L
OTHER: D OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of	
proposed completion or recompletion.	
 b) starting any proposed work). SEE ROLE 19.13.7.14 NMAC. For Multiple Completions. Attach wendore diagram of proposed completion or recompletion. 1) SET 7" CIBP @ 8,300'; PUMP 25 SXS. CMT. @ 8,300'-8,200'; CIRC. WELL W/ M.L.R. 2) PUMP 45 SXS. CMT. @ 7,495'-7,325' (T/ABO). 3) PUMP 40 SXS. CMT. @ 4,046'-3,906' (9-5/8" CSG.SHOE); WOC X TAG CMT. PLUG. 4) CUT X PULL 7" CSG. @ +/-3,000'. 5) PUMP 50 SXS. CMT. @ 3,065'-2,935' (7" CSG.STUB); WOC X TAG CMT. PLUG. 6) PUMP 55 SXS. CMT. @ 2,378'-2,258' (T/YATES, B/SALT); WOC X TAG CMT. PLUG. 7) PUMP 50 SXS.CMT. @ 1,398'-1,288' (T/SALT); WOC X TAG CMT. PLUG. 8) PUMP 45 SXS. CMT. @ 400'-300' (13-3/8" CSG.SHOE); WOC X TAG CMT. PLUG. 9) MIX X CIRC. TO SURF. 25 SXS. CMT. @ 63'-3'. 	
2) PUMP 45 SXS. CMT. @ 7,495'-7,325' (T/ABO).	
3) PUMP 40 SXS. CMT. @ 4,046'-3,906' (9-5/8" CSG.SHOE); WOC X TAG CMT. PLUG.	
4) CUT X PULL 7" CSG. @ +/-3,000'.	5 BC
5) PUMP 50 SXS. CMT. @ 3,065'-2,935' (7" CSG.STUB); WOC X TAG CMT. PLUG.	
 6) PUMP 55 SXS. CMT. @ 2,378'-2,258' (T/YATES, B/SALT); WOC X TAG CMT 7) PUMP 50 SXS.CMT. @ 1,398'-1,288' (T/SALT); WOC X TAG CMT. PLUG. 	. PLUG.
 8) PUMP 45 SXS. CMT. @ 400'-300' (13-3/8" CSG.SHOE); WOC X TAG CMT. PLOG. 	
9) MIX X CIRC. TO SURF. 25 SXS. CMT. @ 63'-3'.	
, Ç	~
DURING THIS PROCEDURE WE PLAN TO USE THE CLOSED-LOOP SYSTEM W/ A STEEL TANK AND HAUL RETURNS	
TO THE REQUIRED DISPOSAL, PER OCD RULE 19.15.17.	W/ A STEEL TANK AND HAUL RETURNS
IO THE REQUIRED DISPOSAL, PER OCD ROLE 19.13.17.	
I hereby certify that the information above is true and complete to the best of my knowledge	and belief.
SIGNATURE	DATE: 11/19/19
Type or print name: DAVID A. EYLER E-mail address: DEYLER@MILAGRO-RES.COM PHONE: 432.687.3033	
For State Use Only	
APPROVED BY: Kenny Further TITLE C.O. H	
Conditions of Approval (if any):	
Conditions of Approval (if any):	DATE
Conditions of Approval (if any):	



Printed 11/12/2019

Cimarex Energy Co. of Colorado KB: 25' above GL CIMAREX Saratoga 30 State Com #1 SHL - 1980' FNL & 990' FWL Ç CARA BHL - 1973' FNL & 534' FEL Sec. 30, T-15-S, R-31-E, Chaves Co., NM T/SALT~ 1.343' API # 30-005-29019 M.L.F. S. Gengler 11/11/2019 T/ YARES ~ 2,318' CIRC. 255×5.063-5 T17-R- 2,537' 13-3/8", 48# H-40 csg @ 350', cmtd w/ 330 sx, cmt circ. - Pump 40 5 x 5. @ 4/60 - 300,' - 7AG - Pump 50 sx 5. @ 1,398 - 1,288 ' - 7AG - Pump 55 5 x 6 C 2,378 - 2,258 ' - 7AG Pump 50 5 x 5. C 3,065' - 2,935' - 7AG TIEN. - 3,123' T/TUBB-6,616' M.L.F T/ABO-7.410' T/wcmp - 8,720' cur 7" eson e +1-3,000 ! TOC @ 3450' by CBL 9-5/8", 40# N-80 csg @ 3976' , cmtd w/ 1485 sx, cmt circ. Pump 40 5x5.@ 4,046'- 3,906'-746-M.L.F. Pump 45 5x5. @ 7,495 - 7,325 M.L.F. Pump 25 5 × 5. C 8,300 '- 8,200 ' 160-4 SET 7" CIBPE 8,300 ' TOL @ 8364' Abo Perfs (9226' - 12275') Whipstock (8471' - 8484') Peak ISO Pack OH Pkrs @ 9225', 9459', 10207', 10569', 10974', 11467', 11918' CIBP @ 8485' TD @ 12275' (MD) & 8737' (TVD) Liner: 4-1/2" 11.6# P-110 @ 12275' 7", 26# P-110 csg @ 9222' TD @ 9222' cmtd w/ 775 sx 191

Printed 11/12/2019

GENERAL CONDITIONS OF APPROVAL:

- 1) Insure all bradenheads have been exposed, identified, and valves are operational prior to rigging up on well.
- 2) Contact the appropriate NMOCD District Office no later than 24 hours prior to moving in and rigging up.
- 3) A copy of the approved C103 intent to P&A should be distributed to the onsite company and plugging representatives. <u>Approved procedures are good for a period of one year from approved date, unless otherwise specified on the C103 intent</u>. Approvals past this date will require the submission and approval of a new C103 intent.
- 4) A company representative is required to be present to witness all operations including setting CIBP's, circulation of mud laden fluids, perforating, squeezing or spotting cement plugs, tags, or any other operations approved on the C103 intent to P&A. Company representative should contact the NMOCD and report all operations.
- 5) Any changes that may be required during plugging operations should be approved by the NMOCD before proceeding.
- 6) A closed loop system is to be used for all plugging operations. Contents of the steel pits to be hauled to a NMOCD permitted disposal facility.
- 7) Mud laden fluids must be placed between all cement plugs mixed at 25 sacks of salt gel per 100 barrels of brine.
- All cement plugs will be 100' or 25 sacks cement, whichever is greater. Class 'C' cement will be used above 7500' and Class 'H' below 7500'. Plugs should be no more than 3000' apart
- 9) Site remediation due within one year of well plugging completion.