UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Hobbs

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 201

OMB NO. 1004-013
Expires: January 31, 20
5. Lease Serial No.
NMLC068281B

SUNDRY N	IOTICES AND REPORTS (ON WELLS
Do not use this	form for proposals to drill o	or to re-enter an
abandoned well.	. Use form 3160-3 (APD) for	such proposals.

6. If Indian, Allottee or Tribe Name

	· 	· · · · · · · · · · · · · · · · · · ·		<u> </u>			
SUBMIT IN T	RIPLICATE - Other inst	ructions on p	age 205	019	7. If Unit or CA/Agree	ment, Name and/or No.	
1. Type of Well ☑ Oil Well ☐ Gas Well ☐ Oth	er	Ý	OBBS O	Qs, eg	8. Well Name and No. BUCK 20 FEDERA	AL 6H	
2. Name of Operator CONOCOPHILLIPS COMPANY E-Mail: greg.bryant@basicenergyservices.com			ENT	9. API Well No. 30-025-40902-00-S1			
3a. Address 925 N ELDRIDGE PARKWAY HOUSTON, TX 77079 3b. Phone No Ph: 432-56		3b. Phone No. Ph: 432-563	(include a see de) -3355		10. Field and Pool or Exploratory Area JENNINGS		
4. Location of Well (Footage, Sec., T.	, R., M., or Survey Description,)	***		11. County or Parish, State		
Sec 20 T26S R32E NENW 55FNL 2659FEL					LEA COUNTY, NM		
12. CHECK THE AP	PROPRIATE BOX(ES)	TO INDICAT	E NATURE O	F NOTICE,	REPORT, OR OTH	ER DATA	
TYPE OF SUBMISSION	.•		TYPE O	FACTION			
Notice of Intent	☐ Acidize	□ Deep	en	□ Product	ion (Start/Resume)	■ Water Shut-Off	
	☐ Alter Casing	☐ Hydi	aulic Fracturing	□ Reclam	ation	■ Well Integrity	
☐ Subsequent Report	□ Casing Repair	□ New	Construction	☐ Recomp	olete	☐ Other	
☐ Final Abandonment Notice	□ Change Plans	🚄 🏿 Plug	and Abandon	☐ Tempor	arily Abandon		
	☐ Convert to Injection	Plug	Back	■ Water I	Disposal		
Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. 1) MIRU. NU WH, ND BOP, POOH w/ Prod Equip 2) Set 7" CIBP @ 6022!—Circ hole w/ MLF. Pressure test casing \$700 — \$500 cm². 3) Spot 30sx cmt @ 8022!—7922!—8237 — \$057 (7/B2) 4) Spot 25sx cmt @ 6555'—645							
14. I hereby certify that the foregoing is true and correct. Electronic Submission #489537 verified by the BLM Well Information System For CONOCOPHILLIPS COMPANY, sent the Hobbs Committed to AFMSS for processing by PRISCILA PEREZ on 10/24/2019 (20PP0211SE)							
Name (Printed/Typed) GREG BR	YANI		Title AGENT				
Signature (Electronic Submission)		Date 10/23/2	019				
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
Approved By James	a. Comos		Title 57	ET		11-2-19 Date	
Conditions of approval of any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Office							
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.							

(Instructions on page 2) ** BLM REVISED ** BLM REVI

WELLBORE SKETCH ConocoPhillips Company -- Permian Basin Business Unit

Date: 10/14/2019 RKB @3<u>193'</u> DF @ <u>3193'</u> GL @ <u>3177'</u> Subarea : Avolon Lease & Well No. : Buck Federal 20-6H 17/2 Lol4 Surface -13-3/8", 54.5#/ft to 1052' 4 |Cmt'd w/950 SX Sec-20C T-26S R-32E NE NW Legal Description : County: State: New Mexico JENNINGS (Red Hills West) Circ'd to surface Field: Date Spudded : 2/16/2013 API Number : Intermediate1 - 9-5/8", 36# to 4435 4480 Operator Number: Cmt'd w/1460 SX Lease ID: 1214 Circ'd to surface Field Number: Play Name: BONE SPRING/WOLFBONE - DELAWARE Intermediate2 - 7", 29# to 9998 914 4 37/2 70 C 874 Cmt'd w/440 SX TOC - Circ'd to surface Rustler 1037 Cost: 18e HAD SEEPAGE DURING CMT JOB/ 35 BBLS. DID NOT BUMP PLUG, PUMPED DISPLACEMENT + 1BBL OVER. See Tubing & Rods tab for Equipment retails Del 4378 BS 8187 Gas Lifted Horizontal Well PBR @ 8723' 70 4 Perf'ed in Hoizontal Lateral 9178' - 13,411' KB Packer Element 8729 TD_ (TVD) 8806* Frac stimulated w/ 28 stages ner - 4.5", ::.6#/ft to 13.436'. TD @ 13,470',(MD) ann ann ann amhann aith addichtu ann an bana an aith didicin ann an

WELLBORE SKETCH ConocoPhillips Company -- Permian Basin Business Unit

Date: 10/14/2019

RKB @3 <u>193'</u> DF @ <u>3193'</u>	500. <u>10.142</u> 515
GL @ :3177	Subarea : Avolon
	Lease & Well No. : Buck Federal 20-6H
Surface -13-3/8", 54.5#/ft to 1052'	Legal Description : Sec-20C T-26S R-32E NE NW
	County: Lea State New Mexico
Circ'd to surface	Field: JENNINGS (Red Hills West)
Spot 60sx cmt @ 300'-3'	Date Spudded : 2/16/2013 API Number : 30-025-40902
Spot 40sx cmt @ 1102'-937' - Tag	APT Number . 30-025-40902
Intermediate1 - 9-5/8", 36# to 4435	Operator Number:
Cmt'd w/1460 SX	Lease ID:
Circ'd to surface	Field Number:
	Play Name: BONE SPRING/WOLFBONE - DELAWARE
0.0000000000000000000000000000000000000	
Spot 25sx cmt @ 2566'-2466' - Tag	
Spot 50sx cmt @ 4530'-4303' - Tag	
Intermediate2 - 7", 29# to 9098'	
Cmt'd w/440 SX	
TOC - Circ'd to surface	A NOT BUILD BUILD BUILDED BIODI LOCKENT . 4884 OVER
HAD SEEPAGE DURING CMT JOB/ 35 BBLS. DII	NOT BUMP PLUG, PUMPED DISPLACEMENT + 1BBL OVER.
<u> </u>	
Spot 25sx cmt @ 6555'-6455'	
Spot 30sx cmt @ 8022'-7922'	
Set CIBP @ 8022*	
KOP ~8122'	
11 1	Gas Lifted Horizontal Well
PBR @ 8723'	
	Perf'ed in Hoizontal Lateral 9178' - 13,411' KB
Packer Element 8729'	
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Frac stimulated w/ 28 stages TD_ (TVD) 8806'
Liner - 4.5", 11.6#/ft to 13.436	TD @ 13,470',(MD)
1915 IIII 1111 IIII 1111 III	
¥ \	64 MX
3	
The state of the s	

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>minety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification</u>: Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3 <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet: and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of brime water. Minimum nine (9) pounds per gallon.
- 5 <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In heu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date well was plugged.</u>
- 8. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.